FINAL

SITE INSPECTION ADDENDUM REPORT JOLIET ARMY AMMUNITION PLANT, ILLINOIS

SEPTEMBER 2009

Prepared for:

UNITED STATES ARMY CORPS OF ENGINEERS, BALTIMORE DISTRICT

P.O. Box 1715 Baltimore, Maryland 21203

Prepared by:

MALCOLM PIRNIE, INC.

701 Town Center Drive Suite 600 Newport News, Virginia 23606

FINAL

SITE INSPECTION ADDENDUM REPORT JOLIET ARMY AMMUNITION PLANT, ILLINOIS

DoD Contract Number:		W912DR-05-D-0004
Reviewed and Approved by:		
Heather Polinely		Heather Polinsky, Vice President Project Officer Malcolm Pirnie, Inc.
CHS8	Courtney	Ingersoll Project Manager Malcolm Pirnie, Inc.
Unexploded	Greg	Peterson Ordnance Safety Officer

Malcolm Pirnie, Inc., p repared this report at the direction of the United States Army Corps of Engineers (USACE). This document should be used only with the approval of the USACE. This report is based, in part, on information provided in other documents and is subject to the limitations and qualifications presented in the referenced documents.

Malcolm Pirnie, Inc.

September 2009

TABLE OF CONTENTS

TAB	LE OF ACRO	ONYMS	i
GLC	SSARY OF T	TERMS	iv
EXE	CUTIVE SUN	MMARY	I
ACK	NOWLEDGI	EMENTS	III
1. I	NTRODUCT	ION	1-1
1.1	Military Muni	itions Response Program Overview	1-1
1.2		pe, and Objectives	
1.3		rs	
2. I	NSTALLATI(ON OVERVIEW	2-1
2.1	Previous Inve	stigations	2-3
3. S	SITE INSPEC	TION OVERVIEW	3-1
3.1	Site Inspection	n Tasks	3-1
3.2		n Findings	
4. S	-	TION DETAILS	
		led Buffer Area (JAAP-001-R-02)	
		Description and Historical Overview	
		dwork Activities	
		dwork Results	
		ceptual Site Model	
		lilitary Munitions Response Program Site Profile	
		Area and Layout	
	4.1.4.1.2	Structures	4-4
	4.1.4.1.3	Utilities	4-4
	4.1.4.1.4	Boundaries	4-4
	4.1.4.1.5	Security	4-4
	4.1.4.2 Ph	nysical Profile	4-5
	4.1.4.2.1	Climate	4-5
	4.1.4.2.2	Geology	4-5
	4.1.4.2.3	Topography	4-5
	4.1.4.2.4	Soil	4-6
	4.1.4.2.5	Hydrogeology	4-7
	4.1.4.2.6	Hydrology	4-7
	4.1.4.2.7	Vegetation	
	4.1.4.3 La	and Use and Exposure Profile	
		Current Land Use / Activities	
	4.1.4.3.2	Current Human Receptors	4-8
	4.1.4.3.3	Potential Future Land Use	4-8

6.	REFERENCES	S	6-1
5.1		Final Acreage	
5. 5.1		Site Inspection Recommendations	
5.	RECOMMEN	DATIONS REVIEW	5 1
	4.1.6 Site	Recommendations	4-15
		funitions Constituents	
		funitions and Explosives of Concern	
		Summary and Conclusions	
	4.1.4.6.2	Munitions Constituents	
	4.1.4.6.1		
		athway Analysis	
	4.1.4.5.6		
	4.1.4.5.5		
	4.1.4.5.4		
	4.1.4.5.3	· · · · · · · · · · · · · · · · · · ·	
	4.1.4.5.1 4.1.4.5.2	Jr	
		Junitions/Release Profile	
	4.1.4.4.3	\mathcal{C}	
	4.1.4.4.2	8	
	4.1.4.4.1	J 1	
		cological Profile	
		Demographics/Zoning	
	4.1.4.3.6	Beneficial Resources	4-8
		Zoning / Land Use Restrictions	
	4.1.4.3.4	Potential Future Human Receptors	4-8

List of Figures

Figure	2-1:	Location	of JOAAP

Figure 2-2: MFG Area and LAP Area at JOAAP Figure 4-1: MEC Exposure Pathway Analysis

List of Maps

Map 2-1:	Overview of MRSs
Map 4-1:	Survey Transects and Inaccessible Areas
Map 4-2:	Points of Interest
Map 4-3:	50-Foot Transects in Agricultural Field
Map 4-4:	Proposed MRS Boundary

List of Tables

Table ES-1:	SI Findings and Recommendations	II
	Summary of MEC TPP Decisions	
Table 3-2:	Summary of MC TPP Decisions	3-2
Table 4-1:	Summary of Potential MEC Types – L2-L3 Extended Buffer Area	4-11
Table 5-1:	Summary of Recommendations	5-1
Table 5-2:	Final Acreage Rationale.	5-2

List of Appendices

Appendix A:	Field Notes
-------------	-------------

Appendix B: Field Forms and Photographic Log Appendix C: Geographic Information Systems Data

Appendix D: Technical Project Planning Meeting 2 Minutes

Appendix E: Munitions Response Site Prioritization Protocol Tables

TABLE OF ACRONYMS

Acronym	Definition	
°F Degrees	Fahrenheit	
APC-T	Armor Piercing Capped-Tracer	
APERS Anti-person	nel	
BD Base	Detonating	
BLU	Bomb Live Unit	
BRAC	Base Realignment and Closure	
CERCLA	Comprehensive Environmental Response, Compensation, and Liability Act	
CTC	Cost to Complete	
CTT	Closed, Transferred, and Transferring	
DERP Defense	Environmental Restoration Program	
DMM Discarded	Military Munitions	
DNT Dinitrotoluene		
DoD	Department of Defense	
DOE	Department of Energy	
FS Feasibility	Study	
FUDS	Formerly Used Defense Site	
FY Fiscal	Year	
GPS	Global Positioning System	
HE High	Explosive	
HE-T High	Explosive-Tracer	
HRR	Historical Records Review	
IEPA	Illinois Environmental Protection Agency	
IL Illinois		
IRP	Installation Restoration Program	
JOAAP	Joliet Army Ammunition Plant	

LAP Load-Assemble-Pack age		
MC Munition	s Constituents	
MD Munition	s Debris	
MEC	Munitions and Explosives of Concern	
MFG	Manufacturing	
MGFD	Munition with the Greatest Fragmentation Distance	
mm Millim	eter	
MMRP Milita	ry Munitions Response Program	
MRS	Munitions Response Site	
MT Mechanical	Time	
NFA No	Further Action	
NM Non-	metallic	
NPL	National Priorities List	
PA Prelim	inary Assessment	
PD Point	Detonating	
Pirnie	Malcolm Pirnie, Inc.	
RA Rem	oval Action	
RDX Cyclotrim	ethylene trinitramine	
RI Rem	edial Investigation	
ROD	Record of Decision	
SARA Superfund	Amendment and Reauthorization Act	
SI Site	Inspection	
Tetryl trinitrophenyl	m ethylnitramine	
TNT Trinitroto	luene	
TP Target	Practice	
TPP	Technical Planning Process	
U.S. United	States	
USACE	United States Army Corps of Engineers	
U.S.C.	United States Code	

USDA	United States Department of Agriculture
USEPA	United States Environmental Protection Agency
UXO Unexploded	Ordnance
UXOSO	Unexploded Ordnance Safety Officer
WWII W	orld War II

GLOSSARY OF TERMS

Closed Range – A military range that has been taken out of service as a range and that either has been put to new uses that are in compatible with range activities or is not considered by the military to be a potential range area. A closed range is still under the control of a Department of Defense (DoD) component.

Defense Site – Locations that are or were owned by, leased to, or otherwise possessed or used by the DoD. The term does not include any operational range, operating st orage or manufacturing facility, or facility that is used f or or was permitted for the trea tment or disposa 1 of military munitions.

Discarded Military Munitions (DMM) – Military munitions that have been abandoned without proper disposal or removed from storage in a military magazine or other storage area for the purpose of disposal. The term does not include unexploded ordnance (UXO), military munitions that are being held for future use or planned disposal, or military munitions that have been properly disposed of, consistent with applicable environmental laws and regulations.

Explosive Ordnance Disposal – The detection, identification, on-site evaluation, rendering safe, recovery, and final disposal of U XO and of ot her munitions that have become an imposing danger, for example, by damage or deterioration.

Explosives Safety – A condition where operational capabil ity and readiness, people, property, and the env ironment are protected from the un acceptable effects of risks of potential m ishaps involving military munitions.

Formerly Used Defense Site (FUDS) Property – A facility or site (property) that was under the jurisdiction of the Secretary of Defense and owned by, leased to, or otherwise possessed by the United States at the time of actions leading to contamination by hazardous substances. By the Department of Defense Environmental Restoration Program (DERP) policy, the FUDS program

is limited to those real propert ies that were transferred from DoD control prior to 17 October 1986. FUDS properties can be located within the 50 State, Dist rict of Colum bia, Commonwealths, and possessions of the United States. (USACE ER 200-3-1, May 2004)

Military Munitions – All ammunition products and components produced for or used by the armed forces for national defense and security, including ammunition products or components under the control of the DoD, United States Coast Guard, Department of Energy (DOE), and National Guard. The termincludes confined gaseous, liquid, and solid propellants; explosives, pyrotechnics, chemical and riot control agents, smokes, and incendiaries, including bulk explosives and chemical warfare agents; chemical munitions; rockets; guided and ballistic missiles; bombs; warheads; mortar rounds; artillery ammunition; small arms ammunition; grenades; mines; torpedoes; depth charges; cluster munitions and dispensers; demolition charges; and devices and components thereof.

The term does not inc lude wholly inert item s; im provised explosive devices; and nuclear weapons, nuclear devices, and nuclear components other than nonnuclear components of nuclear devices that are m anaged under the nuclear w eapons program of the DOE after all required sanitization operations under the Atom ic Energy Ac t of 1954 (42 United States Code [U.S.C.] 2011 et seq.) have been completed.

Munitions and Explosives of Concern (MEC) – This term , which di stinguishes specific categories of military munitions that may pose unique explosives safety risks, includes UXO, as defined in 10 U.S.C. 101(e)(5); DMM, as d efined in 1 0 U.S.C. 2710(e)(2); and m unitions constituents (MC) (e.g., trinitroto luene [TNT], cyclotrimethylene trinitramine [RDX]) present in high enough concentrations to pose an explosive hazard.

Munitions Constituents (MC) – Any materials originating from UXO, DMM, or other military munitions, including explosive and nonexplosive materials, and emission, degradation, or breakdown elements of such ordnance or munitions.

Munitions Debris (MD) – Remnants of munitions (e.g., fragments, penetrators, projectiles, shell casings, links, fins) remaining after munitions use, demilitarization, or disposal.

Operational Range – A range that is under the jurisdicti on, custody, or control of the Secretary of Defense and that is used for range activitie s or, although not currently being used for range activities, that is still considered by the Secretary to be a range and has not been put to a new use that is incompatible with range activities.

Range – A designated land or water area set aside, managed, and used for range activities of the DoD. The term includes firing lines and pos itions, maneuver areas, fi ring lanes, test pads, detonation pads, impact areas, electronic scoring sites, buffer zones with restricted access, and exclusionary areas. The term also include s a irspace areas designated for military use in accordance with regulations and procedures prescribed by the Administrator of the Federal Aviation Administration.

Transferred Range – A range that is no longer under m ilitary control and had been leased by the DoD, transferred, or returned from the DoD to another entity, including federal entities. This includes a m ilitary range that is no longer under military control, but that was us ed under the terms of an executive order, special-use permit or authorization, right-of-way, public land order, or other instrument issued by the federal land manager. Additionally, property that was previously used by the military as a range, but did not have a formal use agreement, also qualifies as a transferred range.

Transferring Range – A range that is propose d to be leased, transferred, or returned from the DoD to another entity, including f ederal entities. This includes a m ilitary range that was us ed under the term s of a wi thdrawal, executive order, special-use permit or authorization, right-of-way, public land order, or other instrument is sued by the federal land meanager or property owner. An active range will not be considered a transferring range until the transfer is imminent (generally defined as the transfer details within 12 ments and a receiving entity has been notified).

Unexploded Ordnance (UXO) – Military munitions that (a) have been primed, fused, armed, or otherwise prepared for action; (b) have been—fired, dropped, launched, projected, or placed in such a manner as to constitute a hazard to operations, installations, personnel, or material; and (c) remain unexploded either by malfunction, design, or any other cause.

EXECUTIVE SUMMARY

The Departm ent of Defense (DoD) establishe d the Military Munitions Response Program (MMRP) under the Defense Environm ental Restoration Program to address defense sites with munitions and explosives of concern (MEC) (which include unexploded ordnance [UXO] and discarded military munitions [DMM]) and munitions constituents (MC) located on current and former military installations. Properties classified as operational military ranges, permitted munitions disposal facilities, or operating munitions storage facilities are not eligible for the MMRP. The United States (U.S.) Army's inventory of closed, transferred, and transferring (CTT) military ranges and defense sites identified sites with UXO, DMM, or MC eligible for action under the MMR P. This report presents the results of the MMRP Site Inspection (SI) Addendum for the L2-L3 Extended Buffer Area (JAAP-001-R-02) conducted at Joliet Army Ammunition Plant (JOAAP) located in Will County, Illinois (IL).

The DoD is currently establishing policy and gu idance for munitions response actions under the MMRP. However, key program dr ivers develope d to date conclude that m unitions response actions will be conducted under the process outline d in the National Contingency Plan (40 Code of Federal Regulations 300) as authorized by the Com prehensive Environm ental Response, Compensation and Liability Act of 1980, 42 United States Code 9605, as a mended by the Superfund Am endments and Reauthorization Act of 1986, Pub. L. 99-499 (hereinafter CERCLA). The Final U.S. Army Closed, Transferred and Transferring Range/Site Inventory Report, completed in September 2002 for the JOAAP, marks the completion of the Preliminary Assessment (PA) phase of work under CERCLA. E ach of the sites found to be MMRP-eligible in the CTT Range/Site Inventory Re port were carried through to the SI phase of the MMRP. In addition, post-SI removal action work identified a potential new Munitions Response Site (MRS) which was determined eligible for the MMRP. An addendum SI is being completed to further evaluate this new MRS. The SI Report and Addendum are part of the CERCLA process and complete the PA/SI requirement for all of the MMRP eligible sites.

Joliet Army Ammunition Plant

JOAAP is located in Will County, IL and was on e of the largest and m ost productive ordnance complexes in the U.S., having assembled over 4 billion pounds of m ilitary munitions. JOAAP encompassed approximately 23,000 acres 10 m iles south of Joliet, IL and 40 m iles southwest of Chicago, IL. All production halted in 1976, and the plant was assigned a nonoperating status in 1977. Closure activities are ongoing at JOAAP.

An SI Report for JOAAP was completed in May 2005 and addressed four MRSs identified during the 2002–2003 CTT Range/Site Inventory. A Historical Records Review (HRR) Addendum, completed in November 2008, identified a new MRS: the L2-L3 Extended Buffer Area (JAAP-001-R-02). This SI Report Addendum is part of the CERCLA process and completes the PA/SI requirement for this newly identified MMRP-eligible site.

The SI Addendum at JOAAP inc luded only MEC field activities, as agreed upon during Technical Project Planning Meeting 2, held on 15 October 2008. Field activities were conducted from 2–5 March 2009. MEC field activities included a ge ophysical instrument-assisted visual survey of the L2-L3 Extended Buffer Area. The survey was conducted in areas where HRR findings and previous fieldwork indicated a potential for MEC. The goals of the MEC fieldwork were to ascertain the presence of MEC, to determine the appropriate actions, and to complete the MRS Prioritization Protocol for the site. The see goals were achieved through the MEC field activities.

A summary of the findings and recommendations for the MRS at JOAAP, based on the results of the SI field activities, is provided in **Table ES-1**.

Table ES - 1: SI Findings and Recommendations

MRS Size	2009 SI Addendum Recommendation	Basis for Recommendation
L2-L3 Extend	led Buffer Area (JAAP-	001-R-02)
201 acres	RI	MEC and munitions debris (MD) were located on the surface in the L2-L3 Extended Buffer Area (Map 4-2). The L2-L3 Extended Buffer Area footprint has been reduced from a total area of 396 a cres to 201 acres (Map 4-4). No MEC or MD were located in the area re commended for exclusion from the MRS.

ACKNOWLEDGMENTS

The Site Investigation Addendum field activities were performed at Jolie t Army Ammunition Plant by Malcolm Pirnie, Inc. from 2–5 March 2009 as part of the Military Munition's Response Program for the Department of Defense. The entire Site Inspection process began in February 2004 and is scheduled to conclude in January 2010. Malcolm Pirnie, Inc. would like to acknowledge the following people for their participation and cooperation throughout the Site Inspection process:

United States Army Environmental Command Mary

Ellen Maly

MMRP Program Manager

Andrew

MMRP Project Manager

United States Army Corps of Engineers, Baltimore District Travis

McCoun

JOAAP MMRP SI Project Manager

United States Army Corps of Engineers, Louisville District

Mike Saffran

Installation Restoration Program Project Manager

United States Environmental Protection Agency, Region 5

Tom Barounis

Restoration Project Manager

Illinois Environmental Protection Agency

Nicole Wilson

Project Manager

Joliet Army Ammunition Plant

Art Holz

Comm

ander's Representative JOAAP

Tim Jeremiah Industrial Specialist

United States Department of Agriculture

Wade Spang

Prairie Supervisor

Malcolm Pirnie, Inc. Courtney

Ingersoll

Project

Manager

Catherin

e Kelly

Field Project Manager

Greg

Peterson

Unexploded Ordnance Safety Officer

1. INTRODUCTION

1.1 MILITARY MUNITIONS RESPONSE PROGRAM OVERVIEW

The Departm ent of Defense (DoD) establishe d the Military Munitions Response Program (MMRP) under the Defense Environmental Restoration Program (DERP) to address unexploded ordnance (UXO), discarded military munitions (DMM), and munitions constituents (MC) located on current and former military installations. Properties classified as operational military ranges, permitted munitions disposal facilities, or operating munitions storage facilities are not eligible for the MMRP. The United States (U.S.) Ar my's inventory of closed, transferred, and transferring (CTT) m ilitary ra nges and defe nse sites identified sites with munitions and explosives of concern (MEC) (which include UXO and DMM) and/or MC that are eligib le for action under the MMRP. Each of the sites found to be MMRP-eligible in the CTT Range/Site Inventory R eport were carried the rough to the Site Inspection (S I) phase of the MMRP. In addition, post SI-removal action work identified a potential new Munitions Response Site (MRS) which was determined eligible for the MMRP. An addendum SI is being completed to further evaluate this MRS. This report presents the results of the MMRP SI Addendum for the L2-L 3 Extended Buffer Area (JAAP-001-R-02) conducted at Joliet Army Ammunition Plant (JOAAP) located in Will County, Illinois (IL).

The DoD is currently establishing policy and gu idance for munitions response actions under the MMRP. However, key program drivers developed to date conclude that m unitions response actions will be conducted under the process outline d in the National Contingency Plan (40 Code of Federal Regulations 300) as authorized by the Comprehensive Environmental Response, Compensation and Liability Act of 1980, 42 United States Code (U.S.C.) 9605, as am ended by the Superfund Am endments and Reauthor ization Act (SARA) of 1986, Pub. L. 99-499 (hereinafter CERCLA). The *Final U.S. Army Closed, Transferred and Transferring Range/Site Inventory Report*, completed in Septem ber 2002 at the JOAAP, m arks the completion of the Preliminary Assessment (PA) phase of work under CERCLA. The SI Report and Addendum is part of the CERCLA process and completes the PA/SI requirement for the MMRP-eligible sites.

Malcolm Pirnie, Inc. (Pirnie) is performing this SI Addendum for J OAAP from April 2008 to January 2010.

The initial CTT Range/Site Inve ntory was completed in 2002 a nd identified four MRSs at JOAAP:

- Demolition Area (L3) (JAAP-001-R-01)
- Explosive Burning Ground 1 (L2) (JAAP-002-R-01)
- Training Area 7 (JAAP-003-R-01)
- Former Burning Area (L34) (JAAP-004-R-01)

Following a Historical Records Review (HRR) in February 2005, an SI was completed in May 2005. This SI recomm ended no further action (N FA) at Training Area 7 (JAAP-003-R-01). A non–time critical removal action was recommended at Former Burning Area (L34) (JAAP-004-R-01) and completed in 2007. The Former Burning Area (JAAP-004-R-01) was considered response complete in 2008 and is currently undergoing completion of the CERCLA documentation for NFA. Currently, the action memorandum is being prepared for the implementation of the 2000 Engineering Evaluation/Cost Analysis (EE/CA). The NFA decision document will be completed for all JOAAP M MRP sites as part of the Record of Decision for the L2-L3 Extended Buffer Area (JAAP-001-R-02).

Further investigation was recommended for the Explosive Burning Ground 1 (L2) (JAAP-002-R-01) and the Demolition Area (L3) (JAAP-001-R-01). Based on this recommendation, a removal action (RA) was undertaken in 2007 at L2 (JAAP-002-R-01) and L3 (JAAP-001-R-01), a 200-foot buffer area surrounding the Installation Restoration Program (IRP) sites, L2 and L3. During the RA, MEC were located beyond this buffer area, likely the result of kick-ou t from munition demolition activities at the site. An additiona 1 area of concern was identified as a result of the findings of the RA, and it was determined this area was eligible for the MMRP. An approximate boundary was estab lished for further SI as de termined by the munition with the greatest fragmentation distance (MGFD). The cont ractor who conducted the characterization documented an explosive-filled 105 mm M1 and deemed this the MG FD (Historical Records

Review, November 2008). This was used to extrapolate the resulting MRS which contained approximately 396 acres and was named the L2-L3 Extended Buffer Area (JAAP-001-R-02).

This SI Report Addendum details the field activities conducted at this newly identified MRS and conclusions and recommendations based on findings from the field activities. Pirnie performed the SI Addendum field activities at the L2-L 3 Extended Buffer Area (JAAP-001-R-02) at JOAAP from 2–5 March 2009.

1.2 PURPOSE, SCOPE, AND OBJECTIVES

The primary goal of the SI Addendum is to collect a sufficient amount of information necessary to make one of the following decisions: 1) whet her a Remedial Investigation (RI) / Feasibility Study (FS) is required at a site, 2) whether an immediate response is need ed, or 3) whether the site qualifies for NFA. The s econdary goal of the SI is to collect information for building the MMRP, including cost to complete (CTC) es timates and site prioritization for the MMRP-eligible sites.

The SI Addendum at J OAAP investigated the pr esence of MEC for the newly-identified MRS mentioned in Section 1.1 in order to fulfill these goals. The field activities for the SI Addendum were not intended to confirm all types of MEC present, determ ine MEC density, or define the limits of the MEC impacts.

1.3 PROJECT DRIVERS

The key legislative, administrative, and historical precedents for managing MMRP sites include the following:

DERP Management Guidance (September 2001)

The DERP Managem ent Guidance establishe d an MMRP elem ent for UXO, DM M, and MC defense sites. The history of DERP dates back to the SARA of 1986. The scope of the DERP is

defined in 10 U.S.C. §2701(b), which states:

Goals of the program shall inc lude the f ollowing: (1) the iden tification, investigation, research and development, and cleanup of contamination from hazardous substances, and pollutants and contaminants; (2) correction of other environmental damage (such as detection and disposal of unexploded ordnance) which creates an imminent and substantial endangerment to the public health or welfare or to the environment.

Army DERP Management Guidance for Active Installations (November 2004)

The Army DERP Management Guidance provides guidance for active installations and non-Base Realignment and Closu re (BRAC) excess p roperties on the m anagement of the Arm y IRP, the MMRP, and the Building Demolition and Debris Removal Program categories that are related to environmental cleanup. The Arm y DERP Mana gement Guidance does not apply to Arm y restoration activities overseas, the BRAC Environmental Restoration Program, the Compliance-Related Cleanup Program, or the FUDS Restor ation Program. The guidance docum ent was provided to implement the Arm y's DERP in accordance with the DoD DERP Managem ent Guidance (September 2001). The Arm y DERP Management Guidance supplements the roles, responsibilities, and procedures contained in Arm y Regulation 200-1 and Department of the Army Pamphlet 200-1.

National Defense Authorization Act (Fiscal Year [FY] 02) (Sections 311–312)

Sections 311–312 of the National Defense Authorization Act of FY02 reinforced the DoD's 2001 DERP Management Guidance by tasking the DoD to develop and maintain an inventory of defense sites that are known or suspected to contain MEC or MC. Section 311 requires the DoD to develop a protocol for priori tizing defense sites for response activities in consultation with the states and tribes. Section 312 requires the DoD to create a separate program element to ensure that the DoD can identify and track munitions response funding.

The September 2001 DoD DERP Managem ent Guidance and the National Defense Authorization Act of FY02, described above, established the MMRP. The DERP and the MMRP provide guidance and methods for conducting a baseline inventor y of defense sites containing, or potentially containing, UXO, DMM, or MC.

2. INSTALLATION OVERVIEW

JOAAP is located in Will County, IL and was on e of the largest and m ost productive ordnance complexes in the United States, having assembled over 4 billion pounds of military munitions. It encompassed approximately 23,000 acres 10 m iles south of Joliet, IL and 40 m iles southwest of Chicago, IL (marked by the red star in **Figure 2-1**).



Figure 2-1: Location of JOAAP

JOAAP was constructed on agricultural land in the early 1940s—for the purpose of munitions production in support of the U.S. in volvement in World War II (WW II). It was built as two separate units: the Elwood Ordnance Plant, cons—isting of 14 square mules, and the Kankakee Ordnance Works, consisting of 22 square mules. These units later were referred to as the Load-Assemble-Package (LAP) Area and the Manufacturing (MF G) Area, respectively (**Figure 2-2**). The two units were joined in 1946 and became known as the Joliet Arsenal.




Figure 2-2: MFG Area and LAP Area at JOAAP

Joliet Arsenal was the nation's largest ammunition manufacturer at the end of WWII. When the Uniroyal Chemical Company (the n known as the U.S. Rubber Company) assumed operational responsibility for both plants in 1 965, it was renamed the Joliet Arm y Ammunition Plant. Production facilities went on inactive or standby status when demand decreased; some of the facilities were leased for commercial use at that time. During times when production was halted, activities at the plant included demilitarization of deteriorated and obsolete ammunition items, as well as loading nonstandard research and development ammunition items. The plant was reactivated and production commenced during the Korean and Vietnam conflicts. All production halted in 1976, and the plant was assigned a nonoperating status in 1977.


The MFG Area produced explosives, including trin itrotoluene (TNT), dinitrotoluene (DNT), trinitrophenylmethylnitramine (tetryl), and of her constituent chem icals. The LAP Are assembled and packaged bom bs, projectiles, fuzes, and supplementary charges almost without interruption from WWII through 1975. Some of the munitions produced included the standard

105-millimeter (mm) high explosive (HE) M1 cartri dge, the 8-inch ho witzer HE projectile, 40 mm cartridges, and M14 mines. The property contained 392 igloos for munitions storage.

Congress placed the MFG Area on the National Priorities List (NPL) in July 1987 and placed the LAP Area on the NPL in March 1989. JOAAP wa splaced on Inactive-Modified Caretaker Status, and the Arm y declared the 23,000 acres ex cess property in 1993. As determined by the Illinois Land Conservation Act of 1995, approxim ately 19,100 acres would be transferred to the U.S. Department of Agriculture (USDA) for the establishment of the Midewin National Tallgrass Prairie; the rest of the property would be used for a national veteran's cemetery, a landfill, and two industrial parks. JOAAP is currently undergoing closure activities in order to complete the transfer of lands.

2.1 Previous Investigations

After concluding that MEC potentially were lo cated outside the IRP boundaries of L2 and L3 during the 2005 HRR, a 200-foot buffer area was delineated ar ound each site for further investigation and was d etermined eligible f or the MMRP; the resulting MRSs were named L2 (JAAP-002-R-01) and L3 (JAAP-003-R-01) and are shown on Map 2-1. An RA to a depth of 1 foot was completed at the two MRSs in 2007. ME C were located at the outer boundary of the MRSs, suggesting ME C m ay be present beyond this boundary. The U.S. Ar my Corps of Engineers (USACE) and a contractor conducted a random site walk; their findings confirmed MEC were located beyond the MRSs. Detailed descriptions of the previous investigations conducted at JOAAP are presented in the HRR Addendum (Malcolm Pirnie, 2008).



3. SITE INSPECTION OVERVIEW

3.1 SITE INSPECTION TASKS

In order to complete the JOAAP SI Addendum, field activities were conducted from 2–5 March 2009 at the L2-L3 Extended Buffer Area (JAAP -001-R-02). Field activities included a geophysical instrument-assisted visual survey. The survey was conducted in the MRS where HRR findings and previous field investigations indicated a potential for MEC. The purpose of the field activities was to collect sufficient information to support one of the following decisions for the MRS: 1) whether an RI/FS is required, 2) whether an immediate response is needed, or 3) whether the site qualifies for NFA.

The goal of the field activities at the L2-L 3 Extended Buffer Area (JAAP-001-R-02) was to determine if MEC are p resent on the ground su rface. Due to the potential hazards associated with the presence of MEC, the UXO Safety Officer (UXOSO) escorted the field team members during the reconnaissance activities using MEC avoidance techniques. The locations of encountered MEC and/or munitions debris (MD) items were recorded using a handheld Global Positioning System (GPS) unit, each item was documented in the field log book, and an MEC/Multiple Anomaly Discovery Form was completed for each item found.

As agreed upon by the Illinois E nvironmental Protection Agency (IEPA), United States Environmental Protection Agency (USEPA), and st akeholders at the Technical Project Plann ing (TPP) Meeting 2 on 15 October 2008, no MC activities were completed for the SI Addendum. It was determined the site has been characterized sufficiently in previous sampling efforts, and the 2004 Record of Decision (ROD) granted an NF A determ ination for soils. Future MC investigation in the L2-L3 Extended Buffer Ar ea is dependent upon the presence of MEC in the area and would occur during an RI, if warranted.

Field activities conducted at JOAAP were dictated by the results of the TPP Meeting 2 held on 15 October 2008, decisions m ade after the TPP session, and comments to the W ork Plan (finalized in February 2009). **Table 3-1** and **Table 3-2** s ummarize the TPP decisions that

determined the field activities. Details regard ing the field procedures are presented in the SI Addendum Work Plan (Malcolm Pirnie, 2009). A summary of field activities conducted at the MRS as part of the SI Addendum work is provided in Section 4.

Table 3-1: Summary of MEC TPP Decisions

MRS Activity		EC SI Activities	
		Purpose	
L2-L3 Extended Buffer Area (JAAP-001-R-02)	Conduct geophysical instrument-assisted visual survey of 10% of the site.	To support MEC NFA or RI determination. If no MEC are identified, the site qualifies for NFA. If MEC are found, the site will move to an RI.	

Table 3-2: Summary of MC TPP Decisions

MRS	MC SI Activities	
	Activity	Purpose
L2-L3 Extended Buffer Area (JAAP-001-R-02)	No MC activities were recommended for this MRS under the SI.	Previously collected data will be used to support CTC/prioritization and RI or NFA determination. It was determined that the site has been characterized sufficiently in previous sampling efforts.

3.2 SITE INSPECTION FINDINGS

The results of the SI field activities conducted at JOAAP, including MEC findings for the MRS, are discussed in Section 4. The M EC and/or MD items identified, as well as oth er significant visual observations, were record ed using a Trimble Geoexplore r XT handheld GP S unit. The field notes and observations m ade during the SI Addendum fiel d activities are summarized in Appendix A (Field Notes) and Appendix B (Field Forms and Photographic Log). Geographic coordinates of field observations (including MEC, MD, and other notable items) are provided in Appendix C. The TPP Meeting 2 minutes are provided in Appendix D. The MRS Prioritization Protocol tables are included in Appendix E.

4. SITE INSPECTION DETAILS

This section presents the site-specific information for the L 2-L3 Extended Buffer Area (JAAP-001-R-02) MRS at JOAAP, including a site description and historical overview, an overview of the fieldwork activities that o coursed on the MRS, the results of the fieldwork, the conceptual site model, a site summary, and site recommendations.

4.1 L2-L3 EXTENDED BUFFER AREA (JAAP-001-R-02)

4.1.1 Site Description and Historical Overview

The HRR Addendum -proposed L2-L3 Extended Buffer Area (JAAP-001-R-02) was approximately 396 acres and surrounds the 200-f oot buffer areas, L2 (JAAP-002-R-01) and L3 (JAAP-001-R-01) MRSs. This new MRS, L2-L 3 Extended Buffer Area (JAAP-001-R-02), was first identified during the 2007 RA that occurred at the L2 (JAAP-002-R-01) and L3 (JAAP-001-R-01) MRSs. MEC were discovered at the boundary of the L3 (JAAP-001-R-01) MRS and near the boundary of the L2 (JAAP-002-R-01) MRS, indicating MEC likely were present beyond the MRS boundaries. A follow-on m agnetometer-assisted survey conducted by the USACE and a contractor confirmed MEC were present beyond the boundary designated for the RA at the L2 (JAAP-002-R-01) and L3 (JAAP-001-R-01) MRSs.

The MEC located beyond the L2 (JAAP-002-R- 01) and L3 (JAAP-002-R-01) MRS boundaries are likely a result of kick-out from the munition demolition activities at the site. This addition al area of concern was identified as a result of the RA and was determ ined to be elig ible for the MMRP. An approximate boundary as determined by the MGFD was established in the HRR Addendum for further SI and in cluded approximately 396 acres; however, findings during field activities would dictate the final boundary and acreage. The re sulting MRS was named the L2-L3 Extended Buffer Area (JAAP-001-R-02).

Currently, the property has been transferred to the USDA, and a portion of the land is leased for agriculture. The central portion of the MRS is wooded and undeveloped.

4.1.2 Fieldwork Activities

Munitions and Explosives of Concern Activities and Purpose

Based on infor mation presented in the HRR A ddendum, the potential for MEC a t the L2-L3 Extended Buffer Area (JAAP-001-R-02) MRS exists; therefore, MEC activities to determine presence were performed, including a geophysical instrument-assisted visual survey of approximately 10% of the 396-acre site. As agreed upon by Stakeholders, the Work Plan (February 2009) established that areas previously surveyed during summer 2007 by USACE and the contractor would not be re-surveyed duringthe SI Addendum field activities. This area included approximately 54 acres.

A UXOSO escorted the field personnel on random transects which were presented in the EPAapproved Work Plan (February 2009). Transect s spanned across the en tire site, with the exception of sm all portions which were inaccessible due to terrain or a locked gate; however, activities completed in the field included more transects than those proposed in the Work Plan. The UXOSO used an all-m etals detector for ano maly avoidance and to ai d in the detection of metal objects on the su rface that m ay have been c overed by vegetation. A sm all area in the southwest corner was enclosed inside a locked fence and was not accessible. A creek, a pond, and a swampy area limited transects surveyed southwest of L3 (JAAP-001-R-01). A swamp and Prairie Creek restricted access to the area immediately west and north of L2 (JAAP-002-R-01). A m ap of transects surveyed is provided as Map 4-1, with approxim ately 54 acres of inaccessible areas high lighted in pink on the m ap. Of the 396 acres included in the L2-L3 Extended Buffer Area (JAAP-001-R-02), 54 acres were previously su rveyed and 54 acres were inaccessible. Of the remaining 288 acres, approximately 30 acres, or 10.4%, were visually surveyed.

4.1.3 Fieldwork Results

Munitions and Explosives of Concern Results

Visibility was maintained for a width of 10 feet on all trans ects, except where limited by thick brush as recorded in the field notes included in Appendix A.

No unusual pits, craters, or mounds were encountered. Foundations of for mer buildings and old pipes were located in the far southeast corner and in the inner section of the southwest boundary of the L2-L3 Extended Buffer Area (JAAP-001-R- 02). No MD or MEC were located in the vicinity. **Map 4-2** depicts the areas where the foundations and pipes were encountered as orange circles.

Two unidentified metallic objects were located at the inner boundary of the southeast corner of the L2-L3 E xtended Buffer Area (JAAP-001-R-02). Photographs are included in Appendix B. A scattered junk pile was found in the sam e area, and the metallic objects are likely associated with the junk pile; however, they were not c onfirmed or denied as MD and, therefore, are marked as unidentified metallic objects. Locations where the junk pile and metallic objects were found are shown as purple and green circles, respectively, on **Map 4-2**.

Six surface anomalies located during the survey were identified by the UXOSO as MD; all were left in place. **Map 4-2** depicts the locations where MD was found as yellow circles. Only one item (part of a base from a 155-mm projectile) was found beyond the L2 (JAAP-002-R-01) MRS boundary. Two items were found in the woods east of the L3 (JAAP-001-R-01) MRS near items found by the USACE during the 2007 random surve y. Three MD item s were located in the agricultural fields east of the L3 (JAAP-001-R-01) MRS. Af ter identifying the objects in the agricultural fields, tighter grid s were surveyed surrounding thes e pieces of MD. The grids extended approxim ately 150 feet north and sout h of the object, and 50-foot transects were surveyed moving east beyond the MD until no other MEC/MD was located for a distance of 100 feet. **Map 4-3** shows these tighter transects that were surveyed.

Details of the MD encountered are provided on the MEC/Multip le Anomaly Discovery Forms included in Appendix B. Furthe r details regarding the survey a reincluded in field no tes provided in Appendix A.

4.1.4 Conceptual Site Model

4.1.4.1 *Military Munitions Response Program Site Profile*

4.1.4.1.1 *Area and Layout*

The L2-L3 Extended B uffer Area (JAAP-001-R-02) MRS survey area included approxim ately 396 acres and is located in the west-central portion of the LAP Area at JOAAP. Central Road runs east-west through the central part of the site, Coldwate r Road runs north-south through the eastern part of the site, and an unnamed road runs east-west through the southern part of the site. Prairie Creek flows to the southwest cutting through the west-central portion of the site. Most of the site is used for agriculture, while remaining areas are wooded or open grassy field. A small cemetery is located west of the L3 (JAAP-001-R-01) MRS. None of the site is used for residential purposes.

4.1.4.1.2 *Structures*

No structures are located on the site. Old foundations and piping were located west, southwest, and southeast of the L3 (JAAP-001-R-01) MRS, but no intact structures or pipes were located. The locations of these former foundations are depicted on **Map 4-2** as orange circles.

4.1.4.1.3 *Utilities*

The L2-L3 Extended Buffer Area (JAAP-001-R-02) MRS is prim arily used for agricultural purposes. An electrical line runs east-west along the unnam ed road in the southern part of the site. Specific information on the locations of other utilities at the site is unknown.

4.1.4.1.4 *Boundaries*

The L2-L3 Extended Buffer Area (JAAP-001-R-02) MRS is bordered on all sides by agricultural land with small undeveloped wooded areas located so uthwest and northeast of the site. Part of the former magazine storage area is located in the south-southwest area of the site and is fenced and locked. This land may be used for grazing.

4.1.4.1.5 *Security*

The public has no access to the IRP sites, L2 and L3; they are surrou — nded by a fence with a locked gate. Only two keys exist for the lock, and all visitors must be accompanied by facility personnel. The L2-L3 Extended Buffer Area (JAAP-001-R-02) MRS has limited public access.

4.1.4.2 *Physical Profile*

4.1.4.2.1 *Climate*

Average summer tem peratures at JOAAP are in the 70s degrees Fahrenheit (°F), while average winter tem peratures are in the 20s. July is the warm est month of the year, with an average maximum temperature of 84.6 °F; January is the coldest month of the year, with an average minimum temperature of 13.5 °F. Precipitation gene rally is distributed evenly throughout the year, but July tends to be the wettest month, receiving an average of 4.34 inches of rain. Average an nual precipitation is 36. 96 inches, with an average of 17 inches of snow per year (*IDcide – Location Information Data Server*, 2009).

4.1.4.2.2 *Geology*

At JOAAP, two glacial deposits ha ve been identified: the Henry and the W edron for mations. The Henry Formation underlies most of the outwash plain in the central and western parts of the MFG Area. It is 5 to 25 feet thick, and includes sandy and gravelly silts and distinct beds of sand and gravel. The W edron Formation is extensive in the upland area east of the main part of the MFG Area. This for mation till is composed of clayey silt with minor sand. The combined thickness of the W edron and Henry for mations is generally less than 25 feet in the western part of the MFG Area. In the eastern part of the MFG Area, the thickness increases to 60–70 feet (Draft Semi-Annual Report for the Groundwater Operable Unit—Long-Term Monitoring Report, Spring Sampling Event 2006, March 2008).

The Silurian dolomite is the underlying bedrock throughout the MFG Area. In num erous boring logs, the do lomite is described as a fine-gra in rock, commonly pyritic, and in som e places includes shaley beds. The dolomite is yellow or yellow-brown where it is weathered and gray or greenish gray otherwise (*Draft Semi-Annual Report for the Groundwater Operable Unit—Long-Term Monitoring Report, Spring Sampling Event 2006*, March 2008).

4.1.4.2.3 *Topography*

JOAAP is located within the northern part of the extensive Central Lowlands physiographic province, which is characterized by relatively flat topography and low relief. The most prominent topographic feature is a 50-foot-high escarpment that trends generally north-south through the installation. JOAAP lies within the fork of the confluence of the Des Plaines and

Kankakee rivers. Most of the LAP Area drains to the Kank akee River. The Grant Creek and Prairie Creek drainage basins cover approxim ately 70% of the installation, and the Jackson Creek drainage basin covers the rem ainder. Jackson and Grant creeks are tributaries of the Des Plaines River, whereas Prairie Cr eek eventually discharges to the Kankakee River. Man-m ade ditches facilitate drainage to these creeks from the sites (U.S. Department of the Army, 1998).

4.1.4.2.4 *Soil*

A 1994 Phase 2 RI described the soil at JOAAP as follows:

JOAAP con tains five distinct soil a ssociations. Groups I and II are term ed "upland soils" and have de veloped over unstratified, ca lcareous, silty clay and glacial till. The lowland s soils—Groups III, IV, and V—have developed west of the es carpment. Group III is developed over 5 feet of medium-textured glacial outwash. Group IV is developed over 5 feet of medium-textured outwash. Group V is developed over a stringer of calcareous, porous, loamy gravel outwash.

The five soil associations at JOAAP are described as follows:

Elliott-Ashkum Soil Association (Group I) — The surface 12 to 15 in ches of this soil consist of dark gray silt loam -to-silty clay loam; the subsoil consists of 15 to 20 inches of fir m brown silty cla y. This soil—dev eloped under prairie vegetation—is high in organic m atter and water-ho lding capacity, is s lightly acidic to neutral, and has a low permeability.

<u>Blount Soil Association (Group II)</u>—The surface 9 inches of this soil consist of dark gray friable silt lo am; the subsoil c onsists of 21 inches of firm brown silty clay. This soil group developed under a de ciduous hardwood forest and is low in organic matter, water-holding capacity, pH (4.7 to 6.0), and permeability.

<u>Drummer-Brenton Soil Association (Group III)</u>—The top 14 inches consist of black silt loam-to-silty clay loam; the subsoil c onsists of 21 to 27 inches of dark gray firm—silty clay loam—. This—soil, developed under m—arsh and prairie vegetation, is high in organic matter and water-holding capacity, is slightly acidic to neutral, and has a moderately low permeability.

Joliet-Millsdale Soil Association (Group IV) — The surface 1 4 inches of this so il consist of black friable silty clay loa m; the subsoil consists of 6 to 20 inches of grayish-brown fir m silty clay lo am. This soil—developed under prairie vegetation—is high in organic m atter and water-holding capacity, is neutral to slightly alkaline, and has a low permeability.

<u>Lorenzo-Rodman Soil Association (Group V)</u>—This soil consists of 7 to 17 inches of dark brown friable silty-to-grave lly loam. It is ap proximately neutral,

moderately high in organic matter, low in water-holding capacity, and has a high permeability.

4.1.4.2.5 *Hydrogeology*

The hydrogeology of the area is subdivided into f our aquifer systems and major confining beds. From the upperm ost downward, the aquifer system's are (1) the glacial drift (Pleistocene glacial deposits), (2) shallow bedrock (Silurian dolom ites), (3) Ca mbrian-Ordovician (san dstones and dolomites), and (4) Mount Simon (Cambrian sandstone). Groundwater flow at the MFG Area is generally westward but is influenced locally by streams that are incised into the glacial drift. Groundwater flow occurs in several aquifers be neath the installation. The shallow overburden aquifer is composed of glacial drift and is underlain by the Silurian dolomite water-bearing zone. Deeper bedrock aquifers are isolated from the shallow aquifer by low-permeability shale beds in the Maquoketa Group. Groundwater at the installation has been determined to be both Class I (potable) and Class II (nonpotable general resource). The IEPA has classified the glacial drift aquifer as Class II because its low yield does not supply usable quantities of groundwater. The Silurian dolomite is considered a Class I groundwater resource and has limited use near the installation as a water source despite elevated levels of sulfate and iron (U.S. Department of the Army, 1998).

4.1.4.2.6 *Hydrology*

A 1994 Phase 2 RI described the hydrology at JOAAP, and site conditions have not changed since this report. JOAAP lies within the fork of the confluence of the Des Plaines and Kankakee Rivers, with most of the LAP Area draining to the Kankakee River. Grant Creek drains a small portion of the northwestern corner of the LAP Area before reaching the MFG Area and ultimately flowing to the Des Plaines River. Prairie Creek drains the majority of the LAP Area and flows westerly through the MFG Area to the Kankakee River. Jordan Creek and Spoil Bank Creek drain the remainder of the LAP Area and discharge to the Kankakee River south of JOAAP.

The Federal Emergency Management Agency has produced 100-year flood maps indicating that part of the LAP Area is subject to flooding.

4.1.4.2.7 *Vegetation*

The woodlands at JOAAP are primarily a mix of hardwood species, including oaks, maples, ashes, black walnut, shagbark hickory, cottonwood, elms, locusts, box elder, osage orange, black cherry, hackberry, red mulberry, Kentucky coffeetree, field cedar, and hawthorne. JOAAP is located in the tallgrass prairie region, and vegetation includes both upland and lowland grasses. Lowland species include Indian grass and switchgrass; upland species include little bluestem and sideoats gramma (U.S. Department of the Army, 1978).

4.1.4.3 *Land Use and Exposure Profile*

4.1.4.3.1 Current Land Use / Activities

Land included in the L 2-L3 Extended Buffer Area (JAAP-001-R-02) prim arily is used for agricultural purposes; a small portion is undeveloped and wooded.

4.1.4.3.2 Current Human Receptors

The current hum an receptors on the L2-L3 Exte nded Buffer Area include off-site residen ts, installation personnel, tr espassers, and authorized contractor s or workers working in the L2-L 3 Extended Buffer Area (JAAP-001-R-02).

4.1.4.3.3 Potential Future Land Use

The planned future us e for this site is op en space for the USDA Midewin Nation al Tallgrass Prairie.

4.1.4.3.4 *Potential Future Human Receptors*

Future receptors are off-site residents, trespassers, and public recreational users, including prairie workers.

4.1.4.3.5 *Zoning / Land Use Restrictions*

The site-specific zoning is unknown, but the area is fenced and monitored by the USDA. Partial open access is available.

4.1.4.3.6 Beneficial Resources

There are no known be neficial resources specific to the L2-L3 Extended Buffer Ar ea (JAAP-001-R-02); however, JOAAP lies with in the Midewin N ational Tallgrass Prairie, an ecological area designated by the Illinois La nd Conservation Act in 1996. It is the first na tional tallgrass

prairie in the country and spans 15,454 acres. The preserve was created with the objectives of enhancing, restoring, and conserving native for lora and fauna; providing opportunities for environmental education and research; allow in gontinuation of existing agriculture; and providing appropriate recreational activities. The preserve contains agricultural fields, hardwood forests, creeks, and ponds. It supports a variety of flora and fauna.

4.1.4.3.7 *Demographics/Zoning*

The L2-L3 Extended Buffer Area (JAAP-001-R-02) MRS lies within Will County, IL. The 2000 U.S. Census lists the population of Will County as 502,266 residents, and land area is 837 square miles.

4.1.4.4 *Ecological Profile*

4.1.4.4.1 *Habitat Type*

The HRR Addendum -proposed L2-L3 Extended Bu ffer Area (JAAP-001-R-02) MRS contains approximately 396 acres of land us ed for agri culture or undeveloped grasslands and wooded area. No residential areas are present on the site. The areas open to the public are available for hunting, as monitored by the USDA.

4.1.4.4.2 *Degree of Disturbance*

The degree of disturbance at the L2-L3 Extended Buffer Area (JAAP-001-R-02) MRS is high, as the area is developed farm—land that is regularly disturbed during agricultural activities (e.g., planting, harvesting).

4.1.4.4.3 *Ecological Receptors*

An ecologist at Midewin National Tallgrass Pr airie confirm ed grassland birds are the only threatened and endangered specie s that m ight be im pacted at JOAAP. These birds include bobolinks, upland sandpipers, and Henslow's sparrows, which have been spotted w est of Prairie Creek and north of Central Road. The area supports a variety of flora and fauna in terrestrial and aquatic habitats.

4.1.4.5 *Munitions/Release Profile*

4.1.4.5.1 Munitions Types **Maximum** Probability Penetration Depth

MEC and MD kicked out of demolition shots do not have an associated m aximum probability penetration depth, as they are not fired. Typically, MEC and MD deposited due to demolition operations are on or near the ground surface. Therefore, it is assumed that any potential MEC or MD that may remains within the MRS would be found at or just below the ground surface.

4.1.4.5.2 *Munitions and Explosives of Concern Density*

A geophysical instrument-assisted visual survey was conducted to verify the presence or absence of MEC within the L2-L3 Extended Buffer Ar ea (JAAP-001-R-02) MRS. It was agreed upon during TPP 2 that approxim ately 10% of the 396- acre MRS would be visually surveyed during SI Addendum field activities. No MEC were obs erved during the SI Adde ndum field activities; however, a random site walk conducted by the USACE in 2007 did confir m MEC were located beyond the L3 (JAAP-001-R-01) MRS to the east, south, and southwest of the site. MEC were confirmed during the USACE site walk out to distances of 900 feet to the east and southeast, 350 feet to the south, and 50 feet to the south hwest of the L3 (JAAP-001-R-01) MRS boundary, as shown on **Map 4-2.**

The survey conducted during the S I Addendum verified the USACE findings. Although MEC was not found, MD was located on the east and southeast sides of the L3 (JAAP-001-R-01) MRS at 900 feet, on the south side at 350 feet, and on the southwest side at 50 feet as discussed above, and out to distances of 1200 feet, 400 feet, and 500 feet, respectively (**Map 4-2**). Based on this evidence, it is believed that MEC could be present out to distances of 1200 feet, 400 feet, and 500 feet from the outer boundaries of the L3 (JAAP-001-R-01) MRS on the east/southeast, south, and southwest sides, respectively. These distances were established based on the farthest distance MD was discovered during the SI Addendum and USACE investigations.

Table 4-1 presents a summary of the types of m unitions that could be expected. These were presented in the HRR Addendum as m unitions and components handled at IRP sites L2 (Explosive Burning Ground) and L3 (De molition Area). Also presented in this table is the mechanism by which munitions would be expected to be released to the environment if present.

4.1.4.5.1 *Maximum Probability Penetration Depth*

MEC and MD kicked out of demolition shots do not have an asso ciated maximum probability penetration depth, as they are not fired. Typically, MEC and MD deposited due to demolition operations are on or near the ground surface. Therefore, it is assumed that any potential MEC or MD that may remains within the MRS would be found at or just below the ground surface.

4.1.4.5.2 *Munitions and Explosives of Concern Density*

A geophysical instrument-assisted visual survey was conducted to verify the presence or absence of MEC within the L2-L3 Extended Buffer Ar ea (JAAP-001-R-02) MRS. It was agreed upon during TPP 2 that approxim ately 10% of the 396- acre MRS would be visually surveyed during SI Addendum field activities. No MEC were obs erved during the SI Adde ndum field activities; however, a random site walk conducted by the USACE in 2007 did confir m MEC were located beyond the L3 (JAAP-001-R-01) MRS to the east, southeast, south, and southwest of the site. MEC were confirmed during the USACE site walk out to distances of 900 feet to the east and southeast, 350 feet to the south, and 50 feet to the south hwest of the L3 (JAAP-001-R-01) MRS boundary, as shown on Map 4-2.

The survey conducted during the S I Addendum verified the USACE findings. Although MEC was not found, MD was located on the east and southeast sides of the L3 (JAAP-001-R-01) MRS at 900 feet, on the south side at 350 feet, and on the southwest side at 50 feet as discussed above, and out to distances of 1200 feet, 400 feet, and 500 feet, respectively (**Map 4-2**). Based on this evidence, it is believed that MEC could be present out to distances of 1200 feet, 400 feet, and 500 feet from the outer boundaries of the L3 (JAAP-001-R-01) MRS on the east/southeast, south, and southwest sides, respectively. These distances were established based on the farthest distance MD was discovered during the SI Addendum and USACE investigations.

4-11

Table 4-1: Summary of Potential MEC Types – L2-L3 Extended Buffer Area

MRS	MD/MEC Observed During SI Field Activities	Items Manufactured and/or Handled at JOAAP ¹	Primary Release Mechanism
L2-L3 Extended			Kick out and
Buffer Area (JAAP-001-R-02)	155 mm base plate (1/3)	4.5-inch rocket (M16)	fragmentation from demolition
(JAA1 -001-K-02)	Remains of PD projectile fuze	90 mm, HE-T (M71E1)	operations
	Nose fuze adapter	81 mm mortar, HE without fuze	conducted at L3
	76 mm steel shot from canister projectile	75 mm APC-T (M61A1) without fuze BD (M66A1)	
		37 mm, TP (M63 Mod 1)	
		Mine, antitank (M4 and NM M5)	
		BLU-26/B	
		Primer (M1A2, M22A2, M28A2&3, M31A2, M40A1, M46-49)	
		Fuze; antitank mine, BD, MT, proximity	
		Mk 29 auxiliary booster depth mines	
		Mk III adapter-boosters	
		M66A1	
		M1 mines	
		M1A1 mines	
		M5 antitank mines	
		Booster cup assembly for M21A4 booster	
		Tracer assembly M66A1 fuze	
		75 mm base plugs	

Note:

APC-T: Armor Piercing Capped-Tracer

APERS: Anti-personnel
BD: Base Detonating
BLU: Bomb Live Unit
HE-T: High Explosive Tracer
MT: Mechanical Time

NM: Non-metallic PD: Point Detonating TP: Target Practice

1: Historical Records Review for Other Than Operational Ranges at JOAAP, 2005; and Engineering Evaluation and Cost Analysis for Sites L2, L3, L11, L16, L21, and L34, 1999.

The SI Addendum and USACE surveys located ME C and MD evidence in the L2-L3 Extended Buffer Area (JAAP-001-R-02). This evidence indicates that some percentage of the L2-L3 Extended Buffer Area (JAAP-001-R-02) MRS to the east and southeast has moderate to heavy MEC and/or MD present, and the south and southwest portions have light to moderate MEC and/or MD present. An RI would be required to establish MEC and/or MD density and depths and site boundaries within portions of the L2-L3 Extended Buffer Area (JAAP-001-R-02).

4.1.4.5.3 *Munitions Debris*

A survey was conducted as part of the SI A ddendum fieldwork effort, and MD was located on the east side of the L2-L3 Extended Buffer Ar ea (JAAP-001-R-02) MRS, as indicated by yellow circles on **Map 4-2**.

4.1.4.5.4 Associated Munitions Constituents

As agreed upon by regulators an d stakeholders during TP P M eeting 2, environm ental media sampling was not conducted. Previous analytical data from the 2004 ROD indicate that chemical constituents are not a concern in the area of the MRS. The need for further characterization will be discussed in a subsequent RI.

4.1.4.5.5 *Transport Mechanisms / Migration Routes*

Soil disturbance is the prim ary transport mechanism identified for the L2-L3 Extended Buff er Area (JAAP-001-R-02) MRS. The current degree of disturbance at the site is high in the agricultural portions of the parcel and is low in the undeveloped wooded areas.

4.1.4.6 *Pathway Analysis*

4.1.4.6.1 *Munitions and Explosives of Concern*

Based the findings of the SI Addendum fieldwork and 2007 RA, the potential exists for MEC to be present on the groun d surface at the L2-L3 Extended Buffer Area (JAAP-001-R-02) MRS. Therefore, the MEC surface and subsurface pathways are potentially complete for all receptors. The MEC Exposure Pathway Analysis is provided as **Figure 4-1**.

MEC Location/ Release Activity Source Area Receptors Access Mechanisms Authorized Authorized Off-site Installation Trespasser Biota Contractors Residents Personnel Potential MEC Handle/Tread Underfoot Surface Soil Limited JAAP-001-R-02 Access L2-L3 Extended Available Buffer Area Potential MEC Intrusive • • • • • Subsurface Soil Complete Pathway O Incomplete Pathway Potentially Complete Pathway Prepared for:

MALCOLM PIRNIE

USACE Baltimore

SITE INSPECTION ADDENDUM L2-L3 EXTENDED BUFFER AREA – JAAP-001-R-02 MEC EXPOSURE PATHWAY ANALYSIS - JOLIET ARMY AMMUNITION PLANT, IL MALCOLM PIRNIE, INC.

FIGURE 4-1 SEPTEMBER 2009

4.1.4.6.2 *Munitions Constituents*

MC data were not collected for this SI Addendum based on stak eholder decisions made at TPP Meeting 2 on 15 October 2008. Therefore, an MC Exposure Pathway Analysis could not be created for this MRS as this time.

4.1.5 Site Summary and Conclusions

4.1.5.1 *Munitions and Explosives of Concern*

The SI Addendum and USACE surveys located ME C and MD evidence in the L2-L3 Extended Buffer Area (JAAP-001-R-02) MRS. This eviden ce indicates that a percentage of the L2-L3 Extended Buffer Area (JAAP-001-R-02) MRS to the east and southeast has moderate to heavy MEC and/or MD present and the south and sout hwest portions have light to moderate MEC and/or MD present.

4.1.5.2 *Munitions Constituents*


As agreed upon by the IEPA, USEPA, and stak eholders during TPP Me eting 2 on 15 October 2008, environmental media samples were not collected as part of the SI Addendum. Please refer to Appendix D for the TPP meeting minutes. It was determined that the site has been characterized sufficiently in previous same pling efforts, and the 2004 ROD granted an NFA determination for soils. Per discussion at the TPP Meeting 2 and input from the IEPA, future MC investigation in the L2-L3 Extended Buffer Area (JAAP-001-R-02) MRS is dependent upon the presence of MEC in the area. Given the ME C and MD discoveries during the SI Addendum field activities, MC will be further evaluated in a future RI.


4.1.6 Site Recommendations


The findings of the MEC SI Addendum field act ivities and USACE surveys (2007) indicate MEC and MD are present in the L2-L3 Extende d Buffer Area (JAAP-001-R-02) MRS. It is recommended the HRR Addendum -proposed MRS land area be reduced from 396 acres to 201 acres to exclude areas where MEC and MD were not discovered. Inaccessible areas adjacent to


areas with potential ME C/MD anomalies detected are included in the proposed MR S boundary. Every attempt should be made in the next phase of the MMRP to access the see areas for investigation; however, some areas may remain inaccessible due to terrain. Inaccessible areas where no visual observations of MEC/MD were located have been excluded from the proposed MRS boundary.

Map 4-4 presents a recommended MRS boundary for a future RI to fully assess the site.









Site Inspection Addendum Joliet AAP, IL





FINAL Map 4-4 **Proposed MRS Boundary**

Legend

- MD Found by USACE
- MEC Found by USACE
- MD Found by Pirnie
- Unidentified Metallic Object
- Former Foundation
- Junk Pile
- 200-Foot Buffer Area MRSs
- Proposed MRS Boundary
- L2 and L3 IRP
- L2-L3 Extended Buffer Area

Inaccessible During 2009 Survey

Locked Gate

Terrain


Data Source: TerraServer 1M DOQQ

Coordinate System: UTM Zone 16 Datum: WGS 84 Units: Meters

Contract: DACA31-00-D-0043

Edition: Final

Date: September 2009



5. RECOMMENDATIONS REVIEW

5.1 SUMMARY OF SITE INSPECTION RECOMMENDATIONS

During the HRR Adde ndum, 396 acres were de signated for a new MRS based on research conducted. A geophysical instrument-assisted visual survey was conducted on approximately 30 acres to determine the presence of MEC on the gr ound surface. Since no visual observations of anomalies were made in large ex tents of the MRS, it is recommended that the MRS be reduce d to 201 acres, to exclude these are as. Areas within the MRS that were not accessible in the SI Addendum, will be studied further during future MMRP phases. The recommendation for the L2-L3 Extended Buffer Area (JAAP-001-R-02) MRS at JOAAP is presented in **Table 5-1**. It is based on the results of the research conducted for the HRR, the TPP session held on 15 October 2008, the data collected during the S I Addendum field activities, and the conclusions presented in Section 4 of this report.

Table 5-1: Summary of Recommendations

MRS Size	SI Recommendation	Basis for Recommendation	
L2-L3 Extended Buffer Area (JAAP-001-R-02)			
201 acres	RI	MEC and MD were found at the MRS.	

5.2 RATIONALE FOR FINAL ACREAGE

The final site acreage is presented in **Table 5-2**.

Table 5-2: Final Acreage Rationale

MRS	AEDB-R ID *	CTT Range/Site Inventory Acreage	2008 HRR Addendum Acreage	2009 SI Addendum Acreage	Rationale for Change
L2-L3 Extended Buffer Area	JAAP-001- R-02	0	396	201	MEC and MD were located on the surface in the L2-L3 Extended Buffer Area. The MRS footprint was reduced to exclude areas where no MEC or MD was located. Inaccessible areas adjacent to areas with potential MEC/MD anomalies detected are included in the proposed MRS boundary.

^{*}AEDB-R ID = Army Environmental Database-Restoration Identification Number

6. REFERENCES

- e²M. 2005. Final Site Inspection Report, Military Munitions Response Program, Site Inspection Munitions Response Sites.
- Dames and Moore, Inc. 1994. Final Phase 2 Remedial Investigation, Load-Assemble-Package Area, Joliet Army Ammunition Plant, Volume 1.
- IDcide Local Information Data Server. 2009. http://www.idcide.com/weather/il/joliet.htm.
- Malcolm Pi rnie, Inc. 2008. Final Historical Records Review Addendum, Joliet Army Ammunition Plant, Wilmington, Illinois.
- -----. 200 9. Final Site Inspection Addendum Work Plan, Joliet Army Ammunition Plant, Wilmington, Illinois.
- MKM Engineers, Inc. 2008. Draft Semi-Annual Report for the Groundwater Operable Unit— Long-Term Monitoring Report, Spring Sampling Event 2006, Joliet Army Ammunition Plant.
- United States Arm y Corps of Engineers. 2005. Historical Records Review for Other Than Operational Ranges at JOAAP.
- United States Departm ent of the Ar my. 1978. Installation Assessment of the Joliet Army Ammunition Plant.
- -----. 199 8. Record of Decision for the Soil and Groundwater Operable Units on the Manufacturing and Load-Assemble-Package Areas, National Priorities List Sites.
- -----. 2002 . Final U.S. Army Closed, Transferring, and Transferred Range/Site Inventory for Joliet Army Ammunition Plant, Illinois.

Appendix A: Field Notes

Field Logbook Notes Daily Quality Control Reports Safety Tailgate Form Location_ Date _ Project / Client ___

Location JOAA?	Date 3 2 39 65
Project / Client	
Weither: 20°, light breeze	, sunny
3:15 Arrived at JOAAP offi	
Discussed plans for day	
- plan to start in	
more to NE quadro	mt.
Art gave a key to gate.	
Have to be out of land	fill gate by 4.30
- Art my see if he can	n ojet key or arrange
for later jute closure.	
Art drove to site with us	
9:00 Set up to stan wa	
9.40 Starter walking trans	
Found 3 HITT of metalli	
along the forceting. One	
metal-prob from fence.	
In field 2 other subsurface	met objects. One along
Side fenchine.	
11:45 Completed transacts 1	
qualitant. No unusual	
Nevt, Walked on other side	
of 12. Were hindered fr	
border of 200' buffer	by swamp & Praire
Creek. Area immediatel	
inaccessible due to surf.	aa water.
Moved to the of 12 &	walked transects to

Date 3	12	09	
	Date 3	Date 3 2	Date 3 2 09

Project / Client ___

Cover areas remaining around LZ. Encountered one anomaly that is potential MD.

- Located at 4580108.88 m N 408425.99 m E

It was frozen into ground. Approximately 3-4" across. Height unknown (in ground). Brown with reddish hue.

- Possible that it is a rock-could not distinguish because it was embedded in the ground.

Photograpes taken.

Were able to maintain visual of at least 10ft on all transects, except where noted below. Greg tested the metal detector on metal every ~3-5 minutes.

No unusual pitx/orates/mounds encountered.

Forest Service came on site ~3:00 to find out what we were doing.

Wrapped up at 3:30 & drove rest of sife to make plans for the rest of the week Project / Client

4.00 Debrief with Art & Mark. Discussed paths ground covered & plans for following day. Did have some hits with detector, but usually hear a fence line & all but 2 Subsurface. 1 surface - obviously fonce metal debris. 2nd surface - wire Nomeness were with multiple hits. Scattered & all small-likely scrap or high-iron untent rocks. (0-foot transects not maintained completely in areas immediately west & north of L2. Thick brush NE of L2 also.

of Doyle Road/west of Prairie Creek.

- Several subsurface hits in area poor west of L3 about 1/2-way/a little more than 1/2-way down L3. This area is wooded. Were not able to identify any hits-all subsurface. # of hits dropped sharply 1/2-way out of woods.

- Unable to walk part of this area - frozen swamp/pond, small creek, & Prairie Creek

- Worked area south of roud below L3.

 Magazine area, located on western side of this piece was believed a locked fence unable to access. Almost zero metal contacts in the rest of this area. No surface anomalies.
- -Worked area lest of old RR line on east side of L3, & area east of road that is east of L3. Almost zero hits. None surfau.
 - Part of this area swampy, or thick brush- unable to cover some of this area but worked around it.

Location	Date 3 3 0 9
Project / Client	

- Forma	Some	old	Form	datio	ns l	pipin	5
in wo	od v	rest o	f L3	2 1	ane	a som	n
of ro	ad k	sel on	1_3	(also	in to	u woo	ls)
- Able to	mai	ntain	10-	foot 1	risual	,except	noke
- Able to	lested	the	metal	l dete	ctor «	every.	-5 n
Photogra words	phed	form	dation	ns w	est of	L3, 4	
words	South	of 1	3.				-
Plan to	Stard	l in d	helas	east	of L	3 toma	MOM
10-Foot	lyan se	ed in	ot m	aintai	ined 1	or sm	all
area	near	RR I	sed S	E of	L3.		-
				-			-
				-			-
1 1					10 10		

Date 314 109

Project / Client

8:30 Arnied at Site. First went to dreck potential MD found 3/2 Hetterday. Confirmed it is ~ 3 base plate off 155. Took pictures - # 1750, 1751, 1752, 1753 1754, 1755, 1756, 1157, 1956 Logged Hem - MD001

Next went to field east of 13. Logged MDWZ & MD003. Photographed. MD002 & MD003 were found hear western edge of agricultural field. MDOOM IN WOOLLS

Cleared entired field & men van transed back through the woods. Found several contacts but all were subsurface. Marked subsurface contacts Will return to get further coverage to butter delineate where contacts are no longer made.

Went & field South of 13, Found some metal wire associated with electric lines. No other Contacts in the field.

In wooded area west of field, made some contacts but also found old foundations & junk. Contacts were likely associated with this but were so subsurface so unable to determine. Went into woods south of 13 but did not make contact.

- 100 - 100
In wood SE of L3-
- right by the creek, there was a lot of
trasci, - glass, metal cans, miscellaneous.
- one contact subsurface here-likely trash
- Anomoly 002 found in middle of junt
pile. Funne shape - unable to confirm MD
- Anomaly OUI found SW of Junkpik - tube -
shaped object with grooves. Unable to
confirm MD.
1:30 Call from MWH - Mark - looking for
us to clear areas marked for well installable
Stopped running transects & went to
assist Mark.
Maintained 10-Fost transacts except for brushy
area Siw of L3.

ocation Joliet AAP	Date 3/5/09 7
oject / Client	
veather: 60s, mad to high win	d, clear, sunny
Arrived at site at 7.45 am.	
New to field east of 13. F	Re located Movo
2 MD003. Walked 150-20	1
of both MD Fods, & 50-fo	
between. Found grape sho	
No other MEC/MD found	21 (Stor C 15 . C
subsurface contacts. Exter	54 T
or 50-Foot transects until	O1 238-1 10 50 H
were made for 100 feet.	
haved to edge of forest eas	t of L3.
Relocated MD004 & mean	
woods. Found MD 006 (root shoulder)
~ 150 A NW of MD004	
MD or MEC Found. M	
subsurface contacts.	
Valked through cometary &	meanlered
work.	
Moved to area SW of L3. V-	ery thick
brush for outer to of	
in from blue line. No 1	
Marked subsurface contac	& Difficult
to walk - went where po	issible.

75 Location Joliet AMP Date 3/5/09 Project / Client Project / Client _____ 10-foot transects maintained except in area SW of L3. Thick brush limited visibility & sweep distance of metal detector. 10:43 Left sik. Debniefed Am Holz on andow finds in SI field activities. See MEC Anomoly forms for details on MD found.

FIGURE 10-1	DATE	3/2/0	9				
MMRP: (Installation name) DAILY QUALITY CONTROL REPORT	DAY	s M	T W	TH	F	s	
USACE PROJECT MGR. Travis McCoun		BRIGHT SUN Sorne clove	CLEAR S	OVER	CAST	RAIN	snow Light
PROJECT 2118-145 Joliet AAP	TEMPERATURE	(32)	32 - 50	50 -	. 70	70-85	>85
JOB NO.	WIND	STILL	MODERATE	ню	GH	REPO	RT NO
CONTRACT NO.	HUMIDITY	DRY	MODERATE	HUI	VID		
SUBCONTRACTORS ON-SITE: MOWE							
7,010							
EQUIPMENT ON SITE: All-metals hand held	doninche	Tamble	GOAVU	40.	. 41.	0 d G	26
EQUIPMENT ON SITE: P(1) - WC (20) WANA KEA	APPRECIOI,	HIII	GWO XII	nav	CAPL	ea q	(F3
				- / -	,		
WORK PERFORMED (INCLUDING SAMPLING): VISUAL TANK SUIFACE FOY MEC/MD/SUIFACE	fratures 5	INST NY	and by	12169	(6 50)	0-61	-
buffer 01 12/13	TOP MICH. 3	urray 1	WYW F.F.	Mora	<i>/</i> (<i>4/</i> ((
QUALITY CONTROL ACTIVITIES (INCLUDING FIELD C. Metal defector tested on metal ~	ALIBRATIONS):	5 main	. lat				
Paths taken were tracked with hand	held GPS w	nit	uttj				
HEALTH AND SAFETY LEVELS AND ACTIVITIES:							
Safety tailgate at the beginning of the	dan wan	n doth					
	**************************************	•	ð				
PROBLEMS ENCOUNTERED/CORRECTIVE ACTION TAKE No DYDIOLOGYS.	CEN:						
TO PICOLOGY VIS.							
SPECIAL NOTES:					-		
	e frae. It i	MIS FORZ	en in t	hi a	mm	nd	
Found only I anomaly that could be a could not tell if it was a lock or	frago If fr	ae like	ly piece	o	A - [55.	
	σ	0 '					
TOMORROW'S EXPECTATIONS: Pegin work in the open field south of D	aule Rd. Cl	PAY AMPA	nvect a	P D0	tilio	Treas	
Begin work in the open field south of D Their whove to work in areas past of t	he road that	is east	of L2	113	Wo	Ac in	
from there.							
BY Catue	rin Kelly		E Field	Proje	ect N	/gcr	

FIGURE 10-1	DATE	3/3/0	9			
	21112		·			
MMRP: (Installation name) DAILY QUALITY CONTROL REPORT	DAY	S M	Ů w	TH F	s	
USACE PROJECT MGR. Travis McCoun	WEATHER	BRIGHT SUN	CLEAR	OVERCAST	RAIN	SNOW
PROJECT Joliet AAP	TEMPERATURE	(32)	32 - 50	50 - 70	70-85	>85
JOB NO. 2118 · 145	WIND	STILL	MODERATE	HIGH	REPO:	RT NO
CONTRACT NO.	HUMIDITY	DRY	MODERATE	HUMID		
	·					
SUBCONTRACTORS ON-SITE: WAVE		· · · · · · · · · · · · · · · · · · ·				
EQUIPMENT ON SITE:						
Hand held all metals detector, H	and help Go	PS unit				
WORK PERFORMED (INCLUDING SAMPLING):	· · · · · · · · · · · · · · · · · · ·					
instrument assisted visual survey	South of Day	le Drud	1 Meet	- of Don	50 C	y n E
South of road below L3, I east of i	and east of	L2/L3		. G Fize	10.0	(A.C.)
,					-	
QUALITY CONTROL ACTIVITIES (INCLUDING FIELD C.	ALIBRATIONS):					
Calibrated metal defector ~ every	5 MINIOUS					
HEALTH AND SAFETY LEVELS AND ACTIVITIES:						
Safety tailgate, warm clothing						
· · · · · · · · · · · · · · · · · · ·						
PROBLEMS ENCOUNTERED/CORRECTIVE ACTION TAI	KEN:					
SPECIAL NOTES:						
TOMORROW'S EXPECTATIONS:						
Beam West of road that I've east of	13 Clear 1	nat hos	1 l Th	ow langua	Som	<u></u>
of 13 Will be working min another	contractor o	Y) SID 1	Clean	ana	ia	V.
for well installation						
ny (Ain.	Pollo	Тити	R Fine	I Pains	Δ.	

FIGURE 10-1	DATE 314109						
MMRP: (Installation name) DAILY QUALITY CONTROL REPORT	DAY	S M	T W	TH F	S		
USACE PROJECT MGR. Trans McCom	•	RIGHT SUP		OVERCAST	RAIN	SNOW	
PROJECT Jolief AAP ST Addendum	TEMPERATURE WIND		32 - 50 MODERATE	50 70 HIGH	70-85 REPO	>85 RT NO	
JOB NO. CONTRACT NO.	нимпріту	DRY	MODERATE	HUMID			
SUBCONTRACTORS ON-SITE:							
EQUIPMENT ON SITE: Hand held all metals	detector. T	rimble	Havelhe	ld Gres u	nit.		
WORK PERFORMED SINCE UPING GALLEN INC.							
WORK PERFORMED (INCLUDING SAMPLING): VISUAL INSTRUMENT ASSISTED SURVEY 1.3. Cleared 2 areas for well insta	s of land Si	uface.	Norked a	ceas s, s	W, E	OυF	
1.3. Cleared 2 areas for well insta	llation						
QUALITY CONTROL ACTIVITIES (INCLUDING FIELD C. TESTED / Calibrated metal defector ~	ALIBRATIONS):	ا مل					
TOTAL TOTAL TOTAL IN THE TOTAL		, , , , , , , , , , , , , , , , , , ,					
HEALTH AND SAFETY LEVELS AND ACTIVITIES: Safety tailgate							
PROBLEMS ENCOUNTERED/CORRECTIVE ACTION TAK	(EN:						
100100							
SPECIAL NOTES: Met Mark From MWH (SUB For Tol)	rest) to clear	n al are	LAS MOD	n Prair	ie		
creek for well installation.							
TOMORROW'S EXPECTATIONS:							
area East of 13 to better delineate	o to be clur	ed. Wil MEC/r	1 Cover	more of	for	<u></u>	
completion of SI field activities							

BY Catherne Kelly THE Field Project Myr

FIGURE 10-1	DATE	3/5/	09			
MMRP: (Installation name) DAILY QUALITY CONTROL REPORT	DAY	S M	T W	TH) F	s	
USACE PROJECTMOR Trans McCoun		BNIGHT SUP		OVERCAST	RAIN	SNOW
PROJECT Joliet AAP	TEMPERATURE	< 32	32 - 50	50 - 70	70-85	>85
JOB NO. 2118-145	WIND	STILL	MODERATE	HIGH	REPO	RT NO
CONTRACT NO.	HUMIDITY	DRY	MODERATE	HUMID		
	'		•			
SUBCONTRACTORS ON-SITE:						
		·				
EQUIPMENT ON SITE:		_				
All metals hand-held defector, Tri	nble Geo XH	t GPS h	andhe	ld unit	,	
WORK PERFORMED (INCLUDING SAMPLING):						
Walked 50 ft transcots in field east	of 13. Walk	ed woo	ds off e	1st side	of L	3 k
SW of 13.						
QUALITY CONTROL ACTIVITIES (INCLUDING FIELD CA	A I TDD A TTONICY.					
Metal defector checked wevery 5	5 minutes					
HEALTH AND SAFETY LEVELS AND ACTIVITIES:		•				
Safety tailgate.						
U						
BRODI FMC ENCOUNTEDER/CONNECTRIE A OTTON TAIL	7 T ? B. I .					
PROBLEMS ENCOUNTERED/CORRECTIVE ACTION TAK	LEN					
SPECIAL NOTES:		.				
Completed field activities. DeBrief	Fod Avt Holz	on find	s. No	MEC IS	uted	
I surface MD items found & logg	ld.					
TOMODDOWN EVDECT LINES						
TOMORROW'S EXPECTATIONS:						

BY Catherine Kelly TITLE Field Project Mgr

SITE SAFETY TAILGATE MEETING

MALCOLM PIRNIE

	Joliet Army		USACE—Baltimore			
PROJECT NAME:	Ammunition Plant	CLIENT NAME:				
	2118-145		Courtney Incomedi			
PROJECT	2110-143	DROTTOT	Courtney Ingersoll			
1		PROJECT				
NUMBER:		LEADER:				
	Catherine Kelly		01.1.0			
PREPARED BY:		DATE:	3/2/09 - 3/5/09			
ON-SITE SAFET	Y MEETING RECOR	ID .				
	AAP, Illinois					
Task to be Perfori	ned: Instrument	assisted visual su	(very			
I. Purpose for	r meeting: (check all t	hat apply)	9			
V 1	DAILY SAFETY BRIEFI	NG				
V	D : 37					
<u> </u>	<u>Begin New Task. Task:</u>		ted site survey			
	Periodic Safety Meeting					
	Vew Site Procedures					
v 1	Vew Site Conditions / I	nformation				
v 1	Vew Site Workers					
MEETING ATTEND	EES					
	·					
NAME (Print) SIGNATI	URE	COMPANY			
1. Catherine Ke	ily Catherine t	Elle Mpi				
2. COREG PETER	Son Italy	1 MPI				
3.						
4.			-			
5.						

Topic (check all that apply) Site Safety Personnel Work Area Description Site characterization Equipment Hazard(s) Biological Hazard(s) Chemical Hazard(s) Physical Hazard(s) Heat Stress Cold Stress Cold Stress Directions to Hospital Site Control Work and Support Zones PPE Medical Monitoring Safe Work Practices Decontamination Decontamination Decontamination Emergency Response Hazard Communication On-site Emergency Don-site Injuries Evacuation Procedures Peractions to Hospital Emergency Equipment Drug and Alcohol Policies PPE Medical Monitoring Task Training Safe Work Practices Unexploded Ordnance (UXO)		EETING RECOR	RD	
Work Area Description Site characterization Equipment Hazard(s) Biological Hazard(s) Chemical Hazard(s) Physical Hazard(s) Heat Stress Cold Stress Site Control Work and Support Zones PPE Medical Monitoring Emergency Response Hazard Communication On-site Emergency Evacuation Procedures Evacuation Procedures Evacuation Procedures Drug and Alcohol Policies PDE Medical Monitoring Task Training				
Site characterization Equipment Hazard(s) Diological Hazard(s) Chemical Hazard(s) Physical Hazard(s) Heat Stress Cold Stress Cold Stress Directions to Hospital Site Control Work and Support Zones PE Medical Monitoring Air Monitoring	· · · · · · · · · · · · · · · · · · ·			Decontamination
Equipment Hazard(s) Biological Hazard(s) Chemical Hazard(s) Physical Hazard(s) Heat Stress Cold Stress Cold Stress Directions to Hospital Site Control Work and Support Zones PE Medical Monitoring Air Monitoring On-site Emergency Evacuation Procedures Evacuation Procedures Pauly Point Emergency Communications Directions to Hospital Emergency Equipment Drug and Alcohol Policies Medical Monitoring Task Training	Work Area De	scription	V	Emergency Response
Biological Hazard(s) Chemical Hazard(s) Physical Hazard(s) Heat Stress Cold Stress Directions to Hospital Site Control Work and Support Zones PE Medical Monitoring Air Monitoring On-site Injuries Evacuation Procedures Evacuation Procedures Directions to Hospital Emergency Equipment Drug and Alcohol Policies Medical Monitoring Task Training	Site characteriz	zation	V	Hazard Communication
Chemical Hazard(s) Physical Hazard(s) Heat Stress Cold Stress Directions to Hospital Site Control Work and Support Zones PPE Medical Monitoring Evacuation Procedures Rally Point Emergency Communications Directions to Hospital Emergency Equipment Drug and Alcohol Policies PPE Medical Monitoring Task Training	Equipment Haz	zard(s)	V	On-site Emergency
Physical Hazard(s) Heat Stress Cold Stress Directions to Hospital Site Control Work and Support Zones PE Medical Monitoring Air Monitoring Rally Point Emergency Communications Directions to Hospital Emergency Equipment Drug and Alcohol Policies Medical Monitoring Task Training	Biological Haz	ard(s)	V	On-site Injuries
Heat Stress Cold Stress Directions to Hospital Site Control Emergency Equipment Work and Support Zones Drug and Alcohol Policies PPE Medical Monitoring Air Monitoring Task Training	Chemical Haza	rd(s)	/	Evacuation Procedures
Cold Stress Directions to Hospital Site Control Emergency Equipment Work and Support Zones Drug and Alcohol Policies PPE Medical Monitoring Air Monitoring Task Training	Physical Hazar	d(s)	V	Rally Point
Site Control Emergency Equipment Work and Support Zones Drug and Alcohol Policies PPE Medical Monitoring Air Monitoring Task Training	Heat Stress		~	Emergency Communications
Work and Support Zones PPE Medical Monitoring Air Monitoring Task Training	Cold Stress		/	Directions to Hospital
PPE Medical Monitoring Air Monitoring Task Training	Site Control			Emergency Equipment
Air Monitoring Task Training	Work and Supp	ort Zones		Drug and Alcohol Policies
	PPE			Medical Monitoring
Safe Work Practices Unexploded Ordnance (UXO)	Air Monitoring			Task Training
	Safe Work Prac	tices	V	Unexploded Ordnance (UXO)
Remarks	Remarks			

Final Health and Safety Plan Joliet Army Ammunition Plant Wilmington, Illinois

V.	Verification
l certify attendir	that the personnel listed on this roster received the briefing described above. Site personnel not gethis meeting will be briefed before beginning their assigned duties.

UXO Health and Safety Supervisor Date

Appendix B: Field Forms and Photographic Log

Munitions and Explosives of Concern/Multiple Anomaly Discovery Forms Photographic Log

M	A	IC	O	ĻМ
		R۱		

MEC/MULTIPLE ANOMALY DISCOVERY FORM

Installation: Joliet Army Ammunition Plant UXO Team Leader Supervisor: Greg Peterson		: L2-L3 Ext	ended Buffer Area			Grid: N/A Date: <u>03/02/09</u>	
Anomaly ID No. (i.e. F.	AR A-001)	MD001					
Anomaly Longitude X/L	atitude Y (UTM)	4580108.833			408426.057		
Object length					·		
Object Diameter/Thickne	ess	5"/2.5"					
Object Weight (Estimate	d)	unknown					
Slope of terrain (Check	one box)	□ <10°	☑ 10° to 30°	□ >30			
Vegetation cover (Check	one box)	Clear	✓ Vegetation	Swamp			
Soil type (Check one box	x)	☐ Sand	Clay	Rock			
Inclination		□ 0° [☐ 45°	$\boxtimes 90^{\mathrm{o}}$	☐ 135°	□ 180	0
Orientation		□N [□ NW-S	☐ E-W	☐ SW-NE		
Item Description/Justif	ication/Comments						
1/3 of the base portion fr	om a 155-mm projectile						
Anomaly type categorie	es (Select Appropriate Bo	ox)					
□UXO	☐ DMM	Munitions Debri	s Pra	actice Ordnance			
☐ Inert Ordnance	Other	☐ Metal Waste					
Was photo taken?	X Yes	□ No File Name: JOAAP-05, JOAAP-06					
Ordnance Positive Iden	tification (If known, reco		ze condition)				
Quantity: 1 Ordnance Item: portion of a 155-projectile base		Nose Fuze	: n/a		Tail Fuz	ze: n/a	
	Mark/Mod:		Mark/Mod:			Mark/Mod:	
Ordnance Filler:	☐ Explosive	☐ Propellant	☐ Pyrotechnic		Other	Other N.E.W.:	
Ordnance Category:	_	_					
Bombs	Grenades	Guided Missile	_ 1				
Land Mines	☐ Mortars	Projectiles	Misc. Explosive Devices				
Rockets	☐ Small Arms	Underwater Ord	dnance 📙	Pyrotechnics and Fla	ares		
Fuzing Types			_				
☐ Piezo-Electric	Proximity (VT)	☐ Impact		Base Detonating	All-ways Ac	eting	☐ Electric
☐ Influence	☐ Mech long delay	Mechanical Ti		MT Superquick	Pressure		
Powder Train Time F	uze (PTTF)	☐ Point-initiating			☐ Point Deton	ating (PD)	
Status of MEC/UXO	Declare On an	Armed		Unarmed	□ C-:1 C1	Talaan	□ Intent
Physical Condition FOR SUXOS USE	☐ Broken Open	☐ Filler Visible		Soil Staining	☐ Soil Sample	такеп	☐ Intact
	dar Damarka)	Transport	<u> </u>	Lagra In Diago	Othor		Data
Disposition: (Clarify Under Remarks)					Date:		
Notifications To Installation By: Transported By:			Signature:			Date:	
			Signature:				Date:
Transfer			Signature:				Date:
Destroy	Neu By:		Signature				Date:
Remarks:	WHA						
Signature:	SUXOS						



MEC/MULTIPLE ANOMALY DISCOVERY FORM

Installation: Joliet Army Ammunition Plant Site: L2-L3 Extended Buffer Area Grid: N/A **UXO Team Leader Supervisor: Greg Peterson Date:** <u>03/04/09</u> Anomaly ID No. (i.e. FAR A-001) MD002 Anomaly Longitude X/Latitude Y (UT) 4579551.914 408094.097 Object length 5" Object Diameter/Thickness Object Weight (Estimated) <10° ☐ 10° to 30° □ >30 Slope of terrain (Check one box) Clear ✓ Vegetation ☐ Swamp Vegetation cover (Check one box) Sand Rock Soil type (Check one box) ■ 135° Inclination $\boxtimes 0^{\rm o}$ ☐ 45° ☐ 90° ■ 180° Orientation \square N ☐ NW-S E-W ☐ SW-NE Item Description/Justification/Comments 155mm-projectile APERS Ogive Anomaly type categories (Select Appropriate Box) ☐ UXO \square DMM Munitions Debris ☐ Practice Ordnance ☐ Inert Ordnance Other ☐ Metal Waste Was photo taken? X Yes ☐ No File Name: JOAAP-09, JOAAP-10 Ordnance Positive Identification (If known, record below and note fuze condition) Ordnance Item: Nose Fuze: n/a Tail Fuze: n/a Quantity: 1 Mark/Mod: Mark/Mod: Mark/Mod: Ordnance Filler: ■ Explosive ☐ Propellant ☐ Pyrotechnic Other N.E.W.: n/a Ordnance Category: ☐ Bombs ☐ Grenades ☐ Guided Missiles ☐ Clusters/Dispensers ☐ Land Mines ■ Mortars □ Projectiles ☐ Misc. Explosive Devices ☐ Rockets ☐ Small Arms ☐ Underwater Ordnance ☐ Pyrotechnics and Flares **Fuzing Types** Piezo-Electric ☐ Proximity (VT) ☐ Impact ☐ Base Detonating ☐ All-ways Acting ☐ Electric ☐ Influence ☐ Pressure ☐ Mech long delay ☐ Mechanical Time ☐ MT Superquick ☐ Powder Train Time Fuze (PTTF) ☐ Point-initiating, Base-detonating ☐ Point Detonating (PD) Status of MEC/UXO Armed □ Unarmed Physical Condition ☐ Broken Open ☐ Filler Visible ☐ Soil Staining ☐ Soil Sample Taken ☐ Intact FOR SUXOS USE Disposition: (Clarify Under Remarks) ☐ Transport ☐ Other Date: Notifications To Installation By: Signature: Date: Transported By: Signature: Date: Signature: Transferred To: Date: Storage Location: Destroyed By: Date: Signature Remarks: Signature: \$UXOS



MEC/MULTIPLE ANOMALY DISCOVERY FORM

		DISCO		CIXIVI			
Installation: Joliet Arn UXO Team Leader Sup		Site:	L2-L3 Exten	ded Buffer Area			Grid: N/A Date: 03/04/09
Anomaly ID No. (i.e. F.	AR A-001)	MD003					
Anomaly Longitude X/L	atitude Y (UTM)	4579325.965			408171.291		
Object length		4"					
Object Diameter/Thickne	ess	1.5"					
Object Weight (Estimate	d)						
Slope of terrain (Check	one box)	⊠ <10°] 10° to 30°	□ >30			
Vegetation cover (Check	one box)	☐ Clear 🗵	Vegetation	Swamp			
Soil type (Check one box	x)	☐ Sand	Clay	Rock			
Inclination		⊠ 0° □] 45°	☐ 90°	☐ 135°	☐ 180°)
Orientation		□ N □	NW-S	⊠ E-W	☐ SW-NE		
Item Description/Justifi	ication/Comments						
Not Identifiable – Appea	ars to be the remains of a l	PD or Impact Projectil	e fuze				
Anomaly type categorie	es (Select Appropriate Bo	x)					
UXO	DMM	Munitions Debris	☐ Pract	ice Ordnance			
☐ Inert Ordnance	Other	☐ Metal Waste					
Was photo taken?	⊠ Yes	□ No	File Name: J	OAAP-11, JOAAP-	12		
Ordnance Positive Iden	tification (If known, reco	ord below and note fuz	e condition)				
Quantity: 1	Ordnance Item:		Nose Fuze: r	ı/a		Tail Fuz	e: n/a
	Mark/Mod:	Mark/Mod: Mark/Mod:		d:			
Ordnance Filler:	☐ Explosive	Propellant	□ Руг	rotechnic	Other	N.E.W.:	n/a
Ordnance Category:							
Bombs	Grenades	☐ Guided Missiles	Cl	usters/Dispensers			
☐ Land Mines	Mortars	☐ Projectiles	☐ Misc. Explosive Devices				
Rockets	☐ Small Arms	Underwater Ord	lnance	rotechnics and Flare	es		
Fuzing Types							
☐ Piezo-Electric	☐ Proximity (VT)		□Ba	se Detonating	☐ All-ways Ac	ting	☐ Electric
☐ Influence	☐ Mech long delay	☐ Mechanical Tin	ne	T Superquick	☐ Pressure		
Powder Train Time F	uze (PTTF)	☐ Point-initiating,	Base-detonatir	ng	Point Deton	ating (PD)	
Status of MEC/UXO		Armed	⊠ U	narmed			
Physical Condition	☐ Broken Open	☐ Filler Visible	□ Sc	oil Staining	☐ Soil Sample	Taken	☐ Intact
FOR SUXOS USE							
Disposition: (Clarify Un	der Remarks)	Transport	⊠ Le	eave In Place	Other		Date:
Notifications To Installation By:			Signature:				Date:
Transpor	rted By:		Signature:			Date:	
Transfer	red To:		Signature:				Date:
Destroy	ved By:		Signature				Date:
Remarks: Signature:	SUXOS						

M	ALCOLM
	ÞIRNIF

MEC/MULTIPLE ANOMALY DISCOVERY FORM

I III VIL		DISCO	VERY 1	OKM			
Installation: Joliet Arn UXO Team Leader Sup		Site	: L2-L3 Exten	ded Buffer Area			Grid: N/A Date: <u>03/05/09</u>
Anomaly ID No. (i.e. F.	AR A-001)	MD004					
Anomaly Longitude X/L	atitude Y (UTM)	4579242.662			408042.844	ļ	
Object length							
Object Diameter/Thickne	ess	5"					
Object Weight (Estimate	d)						
Slope of terrain (Check	one box)	□ <10°	10° to 30°	□ >30			
Vegetation cover (Check	one box)	☐ Clear	Vegetation	Swamp			
Soil type (Check one box	x)	☐ Sand	Clay	Rock			
Inclination		□ 0° □	☐ 45°	☐ 90°	☐ 135°	☐ 180°)
Orientation		□ N [NW-S	☐ E-W	☐ SW-NE		
Item Description/Justifi	ication/Comments						
155mm-projectile APER	RS Ogive						
Anomaly type categorie	es (Select Appropriate Bo	ox)					
□UXO	DMM	Munitions Debris	s Pract	ice Ordnance			
☐ Inert Ordnance	Other	☐ Metal Waste					
Was photo taken?	⊠ Yes	☐ No	File Name: J	OAAP-13, JOAAP	-14		
Ordnance Positive Iden	tification (If known, reco	ord below and note fuz	e condition)				
Quantity: 1	Ordnance Item:		Nose Fuze: 1	n/a		Tail Fuz	e: n/a
	Mark/Mod:		Mark/Mod:			Mark/Mo	d:
Ordnance Filler:	☐ Explosive	☐ Propellant	☐ Pyr	rotechnic	Other	N.E.W.: 1	n/a
Ordnance Category:							
Bombs	Grenades	☐ Guided Missiles	s 🔲 Cl	usters/Dispensers			
☐ Land Mines	Mortars	□ Projectiles	☐ Misc. Explosive Devices				
Rockets	☐ Small Arms	Underwater Ord	dnance Py	rotechnics and Flar	es		
Fuzing Types							
☐ Piezo-Electric	☐ Proximity (VT)	☐ Impact	☐ Ва	se Detonating	☐ All-ways Ac	ting	☐ Electric
☐ Influence	☐ Mech long delay	☐ Mechanical Tir	me	T Superquick	☐ Pressure		
Powder Train Time F	uze (PTTF)	☐ Point-initiating	, Base-detonatii	ng	Point Deton	ating (PD)	
Status of MEC/UXO		Armed	⊠ U	narmed			
Physical Condition	☐ Broken Open	☐ Filler Visible	□ Sc	oil Staining	Soil Sample	Taken	☐ Intact
FOR SUXOS USE							
Disposition: (Clarify Un	der Remarks)	Transport	⊠ L	eave In Place	Other		Date:
Notifications To Installation By:			Signature:				Date:
Transpor	ted By:		Signature:				Date:
Transfer	rred To:		Signature:				Date:
Destroy	ved By:		Signature				Date:
Remarks: Signature:	SUXOS						

M	ALCOLM
	ÞIRNIF

MEC/MULTIPLE ANOMALY DISCOVERY FORM

Grid: N/A Installation: Joliet Army Ammunition Plant Site: L2-L3 Extended Buffer Area UXO Team Leader Supervisor: Greg Peterson **Date:** 03/05/09 Anomaly ID No. (i.e. FAR A-001) MD005 Anomaly Longitude X/Latitude Y (UTM) 408115.694 4579347.78 Object length 0.5" Object Diameter/Thickness Object Weight (Estimated) <10° \square 10° to 30° □ >30 Slope of terrain (Check one box) Vegetation cover (Check one box) ☐ Vegetation ☐ Swamp ⊠ Clay Soil type (Check one box) ☐ Sand ☐ Rock $\boxtimes 0^{\rm o}$ ☐ 45° ☐ 90° □ 135° Inclination ■ 180° Orientation \square N □ NW-S E-W ☐ SW-NE **Item Description/Justification/Comments** 76mm steel shot from canister projectile Anomaly type categories (Select Appropriate Box) ☐ UXO ☐ DMM Munitions Debris ☐ Practice Ordnance ☐ Inert Ordnance ☐ Other ☐ Metal Waste Was photo taken? ✓ Yes ☐ No File Name: JOAAP-20 Ordnance Positive Identification (If known, record below and note fuze condition) Quantity: 1 Ordnance Item: Nose Fuze: n/a Tail Fuze: n/a Mark/Mod: Mark/Mod: Mark/Mod: Ordnance Filler: □ Explosive ☐ Propellant ☐ Pyrotechnic Other N.E.W.: n/a Ordnance Category: ☐ Clusters/Dispensers ☐ Bombs ☐ Grenades ☐ Guided Missiles ☐ Land Mines ■ Mortars □ Projectiles ☐ Misc. Explosive Devices Rockets ☐ Small Arms Underwater Ordnance ☐ Pyrotechnics and Flares **Fuzing Types** ☐ Piezo-Electric ☐ Electric ☐ Proximity (VT) ☐ Impact ☐ Base Detonating ☐ All-ways Acting ☐ Influence ☐ Mech long delay ☐ Mechanical Time Pressure ☐ Powder Train Time Fuze (PTTF) ☐ Point-initiating, Base-detonating ☐ Point Detonating (PD) Status of MEC/UXO Armed ✓ Unarmed Physical Condition ☐ Broken Open ☐ Filler Visible ☐ Soil Staining ☐ Soil Sample Taken ☐ Intact FOR SUXOS USE Disposition: (Clarify Under Remarks) ☐ Transport □ Leave In Place ☐ Other Date: Notifications To Installation By: Signature: Date: Transported By: Signature: Date: Transferred To: Signature: Date: Destroyed By: Signature Date: Remarks: Signature: **S**UXOS



MEC/MULTIPLE ANOMALY DISCOVERY FORM

Installation: Joliet Army Ammunition Plant Site: L2-L3 Extended Buffer Area Grid: N/A **UXO Team Leader Supervisor: Greg Peterson Date:** <u>03/05/09</u> Anomaly ID No. (i.e. FAR A-001) MD006 Anomaly Longitude X/Latitude Y (UT) 408001.705 4579273.664 Object length Object Diameter/Thickness 1.5"/1" Object Weight (Estimated) ■ 10° to 30° Slope of terrain (Check one box) □ <10° □ >30 ☐ Clear Vegetation cover (Check one box) ✓ Vegetation ☐ Swamp Sand ⊠ Clay Soil type (Check one box) Rock $\prod 0^{\rm o}$ X 45° □ 90° ☐ 135° □ 180° Inclination ☐ SW-NE \square N ☐ NW-S E-W Orientation **Item Description/Justification/Comments** Nose Fuze Adaptor Anomaly type categories (Select Appropriate Box) ☐ UXO \square DMM Munitions Debris ☐ Practice Ordnance ☐ Metal Waste ☐ Inert Ordnance Other Was photo taken? X Yes ☐ No File Name: JOAAP-21 Ordnance Positive Identification (If known, record below and note fuze condition) Ordnance Item: Nose Fuze: n/a Tail Fuze: n/a Quantity: 1 Mark/Mod: Mark/Mod: Mark/Mod: ☐ Other ☐ Pyrotechnic Ordnance Filler: ☐ Explosive ☐ Propellant N.E.W.: n/a Ordnance Category: ☐ Bombs ☐ Grenades ☐ Guided Missiles ☐ Clusters/Dispensers ☐ Land Mines ■ Mortars ☐ Projectiles ☐ Misc. Explosive Devices Rockets ☐ Small Arms ☐ Underwater Ordnance ☐ Pyrotechnics and Flares **Fuzing Types** ☐ Piezo-Electric ☐ Proximity (VT) ☐ Electric Impact ☐ Base Detonating ☐ All-ways Acting ☐ Influence ☐ Mech long delay ☐ Mechanical Time ☐ MT Superquick Pressure ☐ Powder Train Time Fuze (PTTF) ☐ Point-initiating, Base-detonating ☐ Point Detonating (PD) Status of MEC/UXO ✓ Unarmed Armed Physical Condition ☐ Broken Open ☐ Filler Visible ☐ Soil Staining ☐ Soil Sample Taken ☐ Intact FOR SUXOS USE Disposition: (Clarify Under Remarks) ☐ Transport ■ Leave In Place Other Date: Notifications To Installation By: Signature: Date: Transported By: Signature: Date: Transferred To: Signature: Date: Destroyed By: Signature Date: Remarks: Signature: SUXOS

MALCOLM PIRNIE

SITE INVESTIGATION PHOTOGRAPHIC LOG

Installation Name:

Joliet Army Ammunition Plant

Site Name:

Site Name:

Location:

L2-L3 Extended Buffer Area

Wilmington, Illinois



03/02/09

Date:

Description:

Preparing the GPS unit and all-metals detector for the visual survey.



MALCOLM PIRNIE

SITE INVESTIGATION PHOTOGRAPHIC LOG

Location:

Installation Name:

Joliet Army Ammunition Plant

Photo ID Date: JOAAP-02 03/02/09

Description:

Beginning the instrument-assisted visual survey west of L2.



MALCOLM PIRNIE

SITE INVESTIGATION PHOTOGRAPHIC LOG

Installation Name:

Joliet Army Ammunition Plant

Site Name:

Site Name:

L2-L3 Extended Buffer Area

Location:

Wilmington, Illinois

Photo ID JOAAP-03 **Date:** 03/02/09

Description:

Field west of L2 where visual survey was conducted. No items were discovered.



MALCOLM PIRNIE

SITE INVESTIGATION PHOTOGRAPHIC LOG

Location:

Installation Name:

Joliet Army Ammunition Plant

Photo ID Date: JOAAP-04 03/02/09

Description:

Wooded area north of L2.



MALCOLM PIRNIE

SITE INVESTIGATION PHOTOGRAPHIC LOG

Installation Name:

Joliet Army Ammunition Plant

Date: 03/02/09

JOAAP-05

Description:
MD001

Photo ID

Top view of 1/3 of a base portion from a 155-mm projectile. Size shown relative to a screwdriver. Item found in grassy field east of L2.

Site Name:

Site Name:

L2-L3 Extended Buffer Area

Location:

Wilmington, Illinois



MALCOLM PIRNIE

SITE INVESTIGATION PHOTOGRAPHIC LOG

Location:

Installation Name:

Joliet Army Ammunition Plant

Photo ID. **Date:** JOAAP-06 03/02/09

Description:

MD001.

Side view of a partial base portion from a 155-mm projectile. Size shown relative to the handheld GPS unit. L2-L3 Extended Buffer Area Wilmington, Illinois



SITE INVESTIGATION PHOTOGRAPHIC LOG

Installation Name:

Joliet Army Ammunition Plant

Photo ID JOAAP-07

Date: 03/03/09

Description:

Conducting the instrument-assisted visual survey through the wooded area southeast of L3.

Location: Site Name:

L2-L3 Extended Buffer Area Wilmington, Illinois



MALCOLM PIRNIE

SITE INVESTIGATION PHOTOGRAPHIC LOG

Installation Name:

Joliet Army Ammunition Plant

Photo ID Date: JOAAP-08 03/03/09

Description:

Old foundations in the wooded area located in the southeast edge of the L2-L3 Extended Buffer Area below L3.

Site Name:

L2-L3 Extended Buffer Area

Location:

Wilmington, Illinois



SITE INVESTIGATION PHOTOGRAPHIC LOG

Installation Name:

Joliet Army Ammunition Plant

Site Name:

Location:

L2-L3 Extended Buffer Area

Wilmington, Illinois

Photo ID Date: JOAAP-09 03/04/09

Description: MD002. 155-mm Projectile APERS Ogive. Scale shown relative to handheld GPS unit. Item found in agricultural field east of L3.



MALCOLM PIRNIE

SITE INVESTIGATION PHOTOGRAPHIC LOG

Installation Name:

Joliet Army Ammunition Plant

Site Name:

Location:

L2-L3 Extended Buffer Area

Wilmington, Illinois

Photo ID Date: JOAAP-10 03/04/09

Description:

MD002. Closer view of the 155-mm Projectile APERS Ogive.



SITE INVESTIGATION PHOTOGRAPHIC LOG

Installation Name:

Site Name:

Location:

Joliet Army Ammunition Plant

L2-L3 Extended Buffer Area

Wilmington, Illinois

Photo ID Date: JOAAP-11 03/04/09

Description: MD003. Not Identifiable – Appears to be the remains of a PD or Impact Projectile fuze. Size shown relative to the handheld GPS unit. Item found in agricultural field east of L3.



MALCOLM PIRNIÉ

SITE INVESTIGATION PHOTOGRAPHIC LOG

Installation Name:

Joliet Army Ammunition Plant

Site Name:

Location:

L2-L3 Extended Buffer Area

Wilmington, Illinois

Photo ID Date: JOAAP-12 03/04/09 **Description:**

MD003. Not Identifiable - Appears to be the remains of a PD or Impact Projectile fuze. Size relative to the handheld GPS unit.



SITE INVESTIGATION PHOTOGRAPHIC LOG

Installation Name:

Joliet Army Ammunition Plant

Photo ID JOAAP-13 **Date:** 03/04/09

Description:

MD004. 155-mm
Projectile APERS
Ogive. Size shown
relative to a handheld
GPS unit. Item found
in wooded area east of
L3.

Site Name: Location:

L2-L3 Extended Buffer Area

Site Name:

L2-L3 Extended Buffer Area

Wilmington, Illinois



MALCOLM PIRNIE

SITE INVESTIGATION PHOTOGRAPHIC LOG

Location:

Wilmington, Illinois

Installation Name:

Joliet Army Ammunition Plant

Photo ID JOAAP-14

ID Date: 03/04/09

Description:

MD004. Closer view of the 155-mm Projectile APERS Ogive.



SITE INVESTIGATION PHOTOGRAPHIC LOG

Installation Name:


Joliet Army Ammunition Plant

Site Name:

Location:

L2-L3 Extended Buffer Area

Wilmington, Illinois



Description: Anomaly 001. Unidentified pipe. Located near junk pile along a creek southeast of L3. Size shown relative to the handheld GPS unit.



MALCOLM PIRNIE

SITE INVESTIGATION PHOTOGRAPHIC LOG

Installation Name:

Joliet Army Ammunition Plant

Site Name:

L2-L3 Extended Buffer Area


Location:

Wilmington, Illinois

Photo ID Date: JOAAP-16 03/04/09

Description:

Anomaly 001. Grooves visible on the unidentified pipe. Stick is pointing at a groove.



SITE INVESTIGATION PHOTOGRAPHIC LOG

Installation Name:

Joliet Army Ammunition Plant

Site Name:

Location:

L2-L3 Extended Buffer Area

Wilmington, Illinois



Date: 03/04/09

Description:

Anomaly 001. Another groove located near the end of the unidentified pipe.



MALCOLM PIRNIE

SITE INVESTIGATION PHOTOGRAPHIC LOG

Installation Name:

Site Name:

Location:

Joliet Army Ammunition Plant

L2-L3 Extended Buffer Area

Wilmington, Illinois

Photo ID Date: JOAAP-18 03/04/09

Description: Anomaly 002. Unidentified funnel located in vicinity of other junk in the area. Located south of L3. Size shown relative to handheld GPS unit.



SITE INVESTIGATION PHOTOGRAPHIC LOG

Installation Name:

Joliet Army Ammunition Plant

Date: 03/04/09

JOAAP-19 **Description:**

Photo ID

Anomaly 002. Sideview of the unidentified funnel located south of L3. Size shown relative to handheld GPS unit.

Site Name: Location:

L2-L3 Extended Buffer Area Wilmington, Illinois



SITE INVESTIGATION PHOTOGRAPHIC LOG

Location:

Installation Name:

Joliet Army Ammunition Plant

Photo ID Date: JOAAP-20

Description: 03/05/09

MD005. 76-mm Steel **Shot from Canister** Projectile. Located in agricultural field east of L3. Size shown relative to handheld GPS unit.



Site Name:

SITE INVESTIGATION PHOTOGRAPHIC LOG

Installation Name:

Joliet Army Ammunition Plant

Site Name:

Location:

L2-L3 Extended Buffer Area

Wilmington, Illinois

Photo ID JOAAP-21

Date: 03/05/09

Description:

MD005. Nose Fuze Adapter. Size shown relative to Chap stick tube. Found in wooded area east of L3.



MALCOLM PIRNIE

SITE INVESTIGATION PHOTOGRAPHIC LOG

Installation Name:

Joliet Army Ammunition Plant

Photo ID Date: JOAAP-22 03/03/09

Description:

Old foundations found in wooded area west of L3.

Site Name:

L2-L3 Extended Buffer Area

Location:

Wilmington, Illinois



SITE INVESTIGATION PHOTOGRAPHIC LOG

Installation Name:

Site Name:

Location:

Joliet Army Ammunition Plant

L2-L3 Extended Buffer Area

Wilmington, Illinois

Photo ID JOAAP-23

Date: 03/03/09

Description:

Old foundations found in woods west of L3.



MALCOLM PIRNIE

SITE INVESTIGATION PHOTOGRAPHIC LOG

Location:

Wilmington, Illinois

Installation Name:

Joliet Army Ammunition Plant

Photo ID Date: JOAAP-24 03/03/09

Description: Another view of foundations found in

woods west of L3.

Site Name:

L2-L3 Extended Buffer Area



SITE INVESTIGATION PHOTOGRAPHIC LOG

Installation Name:

Joliet Army Ammunition Plant

Site Name:

Location:

L2-L3 Extended Buffer Area

Wilmington, Illinois



Date: 03/03/09

Description:

Old piping found near foundations in woods west of L3.



Appendix C: Geographic Information Systems Data

Appendix C Geographic Information Systems Data Items Logged in L2-L3 Extended Buffer Area

		Coordinates		
Description	Location	X	Y	
Points of Interest				
Unidentified Metallic Object	SW of L3 – Woods	4579219.32	407932.638	
Unidentified Metallic Object	SW of L3 – Woods	4579193.212	408083.634	
Former Foundations	W if L3 – Woods	4579537.801	407160.155	
Former Foundations	SW of L3 – Woods	4579117.924	407147.252	
Former Foundations	SE of L3 – Woods	4579096.311	407956.203	
Junk Pile	SE of L3 – Woods	4579194.292	408086.294	
Munitions Debris – Discov	ered During SI Adden	dum		
MD001 – Partial Base Plate (155mm Projectile)	E of L2 – Ag Field	4580108.833	408426.057	
MD002 – 155mm-projectile APERS Ogive	E of L3 – Ag Field	4579551.914	408094.097	
MD003 – Possibly partial PD or Impact Projectile fuze	SE of L3 – Ag Field	4579325.965	408171.291	
MD004 – 155mm-projectile APERS Ogive	SE of L3 - Woods	4579242.662	408042.844	
MD005 – 76mm steel shot from canister projectile	SE of L3 – Ag Field	4579347.78	408115.694	
MD006 – Nose Fuze Adaptor	SE of L3 - Woods	4579273.664	408001.705	
MEC/Munitions Debris – Di	scovered by USACE in	n 2007		
MD	E of L3	4579587.239	407866.663	
MD	E of L3	4579550.188	407838.874	
MD	E of L3	4579525.487	407869.75	
MD	SE of L3	4579408.159	408014.867	
MD SE of L3		4579389.633	407912.977	
MD	SE of L3	4579374.195	408033.393	
MD SE of L3		4579346.407	408058.094	
MD	SE of L3	4579263.042	407996.342	
MD	S of L3	4579176.589	407801.823	
MD SW	of L3	4579293.918	407622.742	
MD SW	of L3	4579241.428	407471.45	
MD SW	of L3	4579303.18	407418.961	
MD SW	of L3	4579290.83	407520.852	
MD SW	of L3	4579330.969	407548.64	
MD SW	of L3	4579352.582	407557.903	
MD SW	of L3	4579374.195	407579.516	
MD SW	of L3	4579368.02	407536.29	
MD SW	of L3	4579352.582	407616.567	
MD SW	of L3	4579330.969	407607.304	
MD SW	of L3	4579324.794	407607.304	
MD SW	of L3	4579324.633	407489.976	
MD SW	of L3	4579398.896	407483.8	

Appendix C
Geographic Information Systems Data
Items Logged in L2-L3 Extended Buffer Area

MD SW	of L3	4579401.983	407545.552
MD SW	of L3	4579429.772	407536.29
MD SW	of L3	4579448.297	407523.939
MD SW	of L3	4579432.859	407514.676
MD SW	of L3	457914.334	407539.377
MEC	E of L3	4579629.007	407913.992
MEC	E of L3	4579613.132	407865.838
MEC	E of L3	4579517.882	407828.267
MEC	E of L3	4579517.882	407838.321
MEC	E of L3	4579513.648	407840.967
MEC	E of L3	4579511.003	407845.73
MEC	E of L3	4579511.003	407854.196
MEC	E of L3	4579494.069	407867.426
MEC	E of L3	4579535.344	407988.076
MEC	SE of L3	4579378.975	408048.93
MEC	SE of L3	4579359.925	407974.847
MEC	SE of L3	4579372.625	407964.263
MEC	SE of L3	4579362.042	407962.147
MEC	SE of L3	4579372.625	407950.505
MEC	SE of L3	4579351.459	407932.513
MEC	SE of L3	4579342.992	407951.563
MEC	SE of L3	4579334.525	407951.563
MEC	SE of L3	4579404.375	407838.321
MEC	SE of L3	4579377.917	407825.621
MEC	SE of L3	4579373.684	407819.271
MEC	SE of L3	4579331.35	407798.105
MEC	SE of L3	4579298.542	407755.771
MEC	SE of L3	4579223.4	407791.755
MEC SW	of L3	4579345.109	407603.371

Note: Data is in presented meters as recorded in WGS 1984 UTM 16N

Appendix D: Technical Project Planning Meeting Minutes

Kickoff Meeting: 27 June 2008
Technical Project Planning Meeting: 15 October 2008
Tehnical Project Planning Meeting: 20 July 2009



MEETING MINUTES

Purpose: Joliet Army Ammunition Plant Site Inspection Kickoff Meeting

Stakeholders Meeting 1:30pm – 3:00pm

Location: Wilmington, Illinois

Date: 27 June 2008

Attendees	Organization	Phone	Email
Andrew Maly	USAEC	410-436-1611	andrew.maly@us.army.mil
Kim Gross	USACE-Baltimore	410-962-6735	kimberly.u.gross@usace.army.mil
Christopher Inlow	USACE-Louisville	502-315-6802	chris.inlow@usace.army.mil
Mark Freuh	USACE-Louisville	815-423-5642	mark.m.frueh@usace.army.mil
Nicole Wilson	IEPA	217-785-8729	nicole.wilson@illinois.gov
Art Holz	JOAAP	815-423-2870	arthur.m.holz@us.army.mil
Delores Kaitschuck	USDA	815-423-6370	dKaitschuck@fs.fed.us
Logan Lee	USDA	815-423-6370	<u>llee@fs.fed.us</u>
Kurt Adams	MWH	773-391-4236	kurt.adams@mwhglobal.com
Kathleen Anthony	MKM	916-920-9146	kanthony@mkmengineers.com
Courtney Ingersoll	Malcolm Pirnie	757-873-4415	cingersoll@pirnie.com
Catherine Kelly	Malcolm Pirnie	757-873-4386	ckelly@pirnie.com

The 11 June 2008 kick off meeting for the Military Munitions Response Program (MMRP) Site Inspection (SI) of the L2-L3 Extended Buffer Area for Joliet Army Ammunition Plant (JOAAP), Wilmington, Illinois was conducted by the United States Army Environmental Command (USAEC), United States Army Corps of Engineers (USACE), Baltimore District and Malcolm Pirnie, Inc at JOAAP in Wilmington, Illinois.

The following summarizes discussions held at the JOAAP MMRP SI kick off meeting. These notes do not include a summary of every discussion held, nor do they quote exact words used. Rather, this document is intended to be used by the group in attendance to reference previously held conversations and decisions.

Introduction

The meeting convened at approximately 1330. All meeting attendees provided personal introductions and explained their role as it relates to the project. This kick off meeting was an agenda item on the JOAAP monthly project management meeting. These minutes encompass all discussions during the meeting.

Kick Off Briefing

The kick off briefing was given by Ms. Courtney MS Ingersoll and Ms. Catherine Kelly, both of Malcolm Pirnie, Inc. Handouts included a copy of the briefing, and a list of acronyms, and definitions. A copy of the briefing is included in the minutes as Attachment 1.

Comments and discussion generated from the briefing are described below.

- Ms. Ingersoll summarized the MMRP to include a programmatic overview, discussions of definitions and acronyms, description of the MMRP SI implementation, process, and expectations of the stakeholders. Also, results of the Closed, Transferred, Transferring (CTT) Range/Site Inventory and previous MMRP SI were recapped to establish history for the new MMRP SI. What is known to date about the L2-L3 Extended Buffer Area Munitions Response Site (MRS) was discussed.
- Ms. Logan Lee, USDA, suggested the following as additional sources of information:
 - Heritage Group (worked extensively at the cemetery)
 - Science Club came across munitions debris while on the site
 - Environmental Ecologist with U.S. Forest Service came across munitions debris downstream of L4.
- ➤ Ms. Lee and Ms. Delores Kaitschuck mentioned they would be having a monthly meeting with some of the aforementioned potential sources of information on 17 June 2008. During the meeting they would ask the meeting participants about the area and if any had encounters with potential Munitions and Explosives of Concern (MEC). Both agreed to a phone interview by Malcolm Pirnie, Inc following the meeting. Malcolm Pirnie proposed Thursday, 19 June 2008, for the interview. Ms. Lee and Ms. Kaitshcuck stated that they would be available.

Concerns about Public Access

Although liability ultimately is with the Army, the USDA expressed concerns about public access to the sites. USDA asked if the Army had any specific guidance or rules regarding access to sites such as the L2-L3 Extended Buffer Area MRS. USDA is aware people wander in the area north of Paradise Creek, which lies within the buffer zone, roaming throughout the area and walking down to the road. There was a discussion about what educational material might be readily available from

the Army for public education with regard to the potential MEC hazard at the MRS.

 Mr. Maly will investigate availability for public outreach material from the USAEC for use by USDA.

Rights of Entry (ROE)

- Language in the Finding of Suitability for Transfer (FOST) states an open access agreement between the Army and USDA for remedial actions.
 The FOST most likely covers entry to the MRS for the MMRP SI activities.
- Although Ms. Lee did not see the need for right of entry on paper, she agreed to sign a form permitting access if requested by the USACE, Baltimore District. Per Ms. Lee, Mr. Bill Mains (wmains@fs.fed.us) is the main Point of Contact (POC) for the USDA.
- Ms. Gross will work with both the USACE Louisville and Baltimore Real Estate Managers to determine need for an ROE.

Project Schedule

Dates on the proposed schedule may change based on timing of Malcolm Pirnie deliverable submissions and how quickly government and stakeholder reviews are completed. Field work is currently scheduled for 11-19 May 2009. JOAAP suggested Malcolm Pirnie be in the field by late March or April 2009 due to vegetation growth and agricultural land use.

Previous Site Work Performed by Others

- Ms. Anthony, MKM, suggested Mr. Troy Pfurtish (phone number: 281-932-8531) as a contact to discuss previous findings from the MMRP Interim Removal Action (IRA) in L2 and L3. Ms. Anthony requested she be contacted before calling to give Mr. Pfurtish a heads up as to the purpose of the call.
- Ms. Anthony offered GIS data and any other data that might be useful for the L2-L3 Extended Buffer Area SI. This includes their photo log.
- Ms. Anthony noted MKM found BLU 26's at L3; photographs are included in their photo log.

Documents Collected

The following documents were collected by Malcolm Pirnie, Inc for use in preparing the Historical Records Review (HRR) for the L2-L3 Extended Buffer Area SI.

- Engineering Evaluation/Cost Analysis Site L2, L3, L11, L16, L21, L34
 (U.S. Army Engineering and Support Center, Huntsville, October 1999)
- Final Report for the Ordnance Removal and Site Characterization (EODT, September 2001)
- Final Five-Year Review Report Soils Operable Unit (MWH, April 2004)
- Final Site Inspection Report (e²M, 25 May 2005)

- Final Remedial Design/Remedial Action Work Plan Phase 2, Volume II of II (MWH, October 2005)
- Final Work Plan MEC Removal Action of Sites L2 and L3 (MWH, May 2006)
- Draft Explosives Safety Submission Amendment for the MMRP Sites L3, L2, and L34 (MKM, July 10, 2006)
- Final Remedial Action Work Plan for the MMRP Sites L3, L2, and L34 (MKM, October 2006)
- Draft 2006 Semi-Annual Report for the GW Operable Unit LTM (MKM, March 2008)
- Draft Site-Specific Final Report MMRP Site L2 (MKM, March 2008)
- Draft Site-Specific Final Report MMRP Site L3 (MKM, April 2008)
- In addition, three CDs with numerous documents were obtained from e²M to include in research conducted by Malcolm Pirnie, Inc.

MRSPP Scores

 Mr. Gross asked if the previous MRSPP scores had been advertised for public comment. Both Mr. Maly and Mr. Holz were unsure of the status.
 Mr. Maly offered to follow up with USAEC on the status and check procedure on public comment solicitation for the new MRS.

Next Steps

- Malcolm Pirnie, Inc will proceed with the HRR. A stakeholder draft will be submitted no later than 7 October 2008.
- Meeting concluded at 1500.

The following action items resulted from this meeting:

- Malcolm Pirnie will provide meeting minutes to all attendees.
- Malcolm Pirnie will conduct a phone interview with USDA on 19 June 2008.
- Mr. Maly will provide public education information for USDA.
- Ms. Gross will check FOST language for the ROE.
- Mr. Maly will check the MRSPP public notice status and procedure.

Attachment 1
Military Munitions Response Program Site Inspection
L2-L3 Extended Buffer Area
Joliet Army Ammunition Plant, Wilmington, Illinois
Kick Off Meeting Attendees
(13 pages)



MEETING MINUTES

Purpose: Joliet Army Ammunition Plant Site Inspection Technical Project Planning

Meeting

Stakeholders Meeting 10:00am - 12:00pm

Location: Wilmington, Illinois

Date: 15 October 2008

Attendees	Organization	Phone	Email
Tom Barounis	USEPA	312-353-5577	barounis.thomas@epa.gov
Kim Gross	USACE-Baltimore	410-962-6735	kimberly.u.gross@usace.army.mil
Art Holz	JOAAP	815-423-2870	arthur.m.holz@us.army.mil
Courtney Ingersoll	Malcolm Pirnie	757-873-4415	cingersoll@pirnie.com
Catherine Kelly	Malcolm Pirnie	757-873-4386	ckelly@pirnie.com
Delores Kaitschuck	USDA	815-423-6370	dkaitschuck@fs.fed.us
Bill Mains	USDA	815-423-6370	wmains@fs.fed.us
Andrew Maly	USAEC	410-436-1611	andrew.maly@us.army.mil
Greg Peterson	Malcolm Pirnie	760-888-7400	gpeterson@pirnie.com
Nicole Wilson	IEPA	217-785-8729	nicole.wilson@illinois.gov

The 15 October 2008 Technical Project Planning (TPP) Meeting for the Military Munitions Response Program (MMRP) Site Inspection (SI) of the L2-L3 Extended Buffer Area for Joliet Army Ammunition Plant (JOAAP), Wilmington, Illinois was conducted by the United States Army Environmental Command (USAEC), United States Army Corps of Engineers (USACE), Baltimore District and Malcolm Pirnie, Inc. at JOAAP.

The following summarizes discussions held at the JOAAP MMRP TPP meeting. These notes do not include a summary of every discussion held, nor do they quote exact words used. Rather, this document is intended to be used by the stakeholders in attendance to reference previously-held conversations and decisions. Handouts including slides, glossary, and maps were provided to all attendees. Information not presented in the slides and additional discussions are included in the meeting minutes. The following issues were discussed:

Introduction

The meeting convened at approximately 10:00. All meeting attendees provided personal introductions. ➤ Mike Saffran will be filling in for Chris Inlow (USACE—Louisville) while Chris is on detail until approximately February 2009.

> SI Briefing

The SI briefing was led by Ms. Courtney Ingersoll of Malcolm Pirnie. Handouts included a copy of the briefing and a copy of relevant maps from the Historical Records Review (HRR). A copy of the briefing and sign in sheet is included in the minutes as Attachment 1.

Comments and discussion generated from the briefing are described below.

- Ms. Ingersoll summarized the meeting goals, the SI goals, and the TPP Process, including the TPP Phases, and where the JOAAP SI project falls in the process. Currently, JOAAP is determining data needs and developing data collection methods. Within the MMRP SI framework, munitions of explosive concern (MEC) has been confirmed on site, and data will be collected to determine if an Interim Removal Action is necessary and/or if the site should proceed to a Remedial Investigation/Feasibility Study (RI/FS).
- Mr. Tom Barounis, USEPA, proposed the possibility of conducting an Engineering Evaluation/Cost Analysis (EE/CA) as opposed to an RI later in the MMRP process. Mr. Andrew Maly, USAEC, and Mr. Art Holz, JOAAP, said that an EE/CA has been considered, but future funding will play a large role in how the site is handled. Without the SI data, it is too early to determine how the site will be addressed. However, all avenues will be considered in order to provide the most efficient way to provide appropriate clean-up within the budget. Mr. Maly will be working to get funding for JOAAP as quickly as possibly in order to complete the MMRP clean-up.
- Ms. Ingersoll provided a brief summary of the results of the HRR. Mr. Greg Peterson, Malcolm Pirnie, suggested the extended buffer boundary created after the 2007 USACE site walk was likely the radius from the blasting point to the location of the outermost MEC find, whereas the boundary for the extended buffer proposed following the 2007 Removal Action (RA) was determined by the Munitions of Greatest Fragmentation Distance.

ICM Waiver

- Mr. Peterson discussed the need for an ICM Waiver when working on site because of previous finds. An ICM Waiver is already in place (approved February 2001), so an amendment will be prepared by Malcolm Pirnie and submitted by the Army prior to conducting field work in Spring 2009.
- Ms. Kim Gross, USACE, asked Malcolm Pirnie to coordinate with Mr. Paul Greene, USACE, in the submission of an ICM Waiver Amendment.
- The previously approved ICM Waiver and Amendment will be included as an appendix in the SI Work Plan.

- Rights of Entry (ROE)
 - Ms. Logan Lee, USDA, has previously expressed she has little concern regarding ROEs. However, Ms. Gross will draft a formal ROE request in order to have a record of access permission.

Proposed Field Activities

- MEC Survey
 - Mr. Peterson presented proposed field activities to include a magnetometer-assisted MEC visual survey of 10% of the site, covering approximately 40 acres.
 - o Mr. Peterson then discussed the field survey in further detail showing a map of an example of what visual survey transects could look like (see Attachment 1), but stressed that transects will be adapted in the field as necessary. Topography as well as MEC finds will dictate where transects are located. Malcolm Pirnie's suggestion is to conduct visual survey transects out to the currently proposed boundary (e.g. L2 and L3 Extended Buffer Area), and if MEC is still being encountered, extend the transects past the buffer area until MEC is no longer found.
 - At each MEC find, a GPS waypoint will be collected, notes on the MEC item will be recorded, and a photograph taken.
 - The areas surveyed by the USACE in 2007 will not be included in the survey.
 - Ms. Dolores Kaitschuck, USDA, expressed concern for the areas of USDA property being leased to farmers. The land was leased before the possibility of MEC was known, but the status of the land has now changed given the possibility of MEC. Ms. Ingersoll and Mr. Holz responded that this is part of the reasoning for making efforts to conduct the survey before Spring 2009 agricultural practices begin. Mr. Peterson confirmed that upon completing the field activities, it will be known if a potential MEC threat exists. This information will be shared with the Army to determine if a revision to the lease is required.
 - Ms. Kaitschuck will communicate with the Army and Malcolm Pirnie regarding priority areas for conducting the survey.
 - Mr. Holz expressed particular concern for the area immediately east of L3.

MC Sampling

 Ms. Ingersoll discussed the potential for 15 surface soil samples during the SI and proposed eliminating these sampling efforts so the funds would be better used to cover more acreage in the MEC survey. This recommendation was supported with the fact that MC sampling would be part of an RI, therefore Malcolm Pirnie believes surface sampling in the SI is inconsequential as presence of MEC has been determined and the MRS will be recommended for further investigation at completion of the SI. Further, the sites have been sufficiently characterized in previous soil sampling efforts.

- Mr. Holz did not believe sampling of any kind is warranted in the RI since sampling has been conducted previously. Per the 2004 ROD, NFA was received for soil.
- o Ms. Ingersoll raised the question of sampling in the instance that certain areas contained no MEC. Would collecting samples in that area give rise to concluding NFA for that parcel of land provided MC constituents fell below RGs? Would IEPA and USEPA accept NFA without chemical sampling?
- o Ms. Nicole Wilson, IEPA, does not believe sampling of any kind necessary in this instance since a formal boundary has yet to be established. This SI field work is for the purpose of determining the boundary. Therefore, if no MEC is found, no MC is present and the extended buffer area will not include this area. Ms. Wilson confirmed the suggested boundary is flexible and open to change given the results of the SI field activities.
- Mr. Holz confirmed the original IRP site is the only area that previously contained MC concentrations greater than previously established RGs (2004 Record of Decision). Earlier sampling results in the 200 foot buffer area and the extended buffer area showed MC concentrations in these areas were below RGs.

Field Approach

MEC Survey

- The TPP attendees concluded that the new Munitions Response Site (MRS) does not have to be contiguous. If MEC is not found in a particular area, it will not be included in the MRS.
- Mr. Holz recommended that the stakeholders meet post-field work to examine the data collected during the SI to determine the best method for setting the L2-L3 Extended Buffer Area boundary, and there was stakeholder consensus on this suggestion.

MC Data

 Ms. Ingersoll discussed the need for data to complete the Munitions Response Site Prioritization Protocol (MRSPP) forms. She asked if data should be used from the original IRP sites, or should a small number of samples be collected from the extended buffer area for

- these forms only (not to be used in characterization).
- Mr. Holz confirmed samples were collected in this area prior to transfer of the lands to USDA. He suggested referencing this data instead of collecting new data. Ms. Ingersoll agreed to review the data and determine if the analytical data are sufficient for purposes of completing MRSPPs.

Handling MEC finds

- Ms. Wilson expressed concern over the procedure for reporting MEC finds. Fort McCoy has been contacted on other sites, and they are not pleased with receiving multiple calls for Army sites. The Sheriff's Office has also been contacted but does not have the training for how to handle and remove MEC.
- Ms. Gross suggested working with Paul Greene in establishing a protocol for MEC finds.
- o Mr. Peterson suggested using data that is presently available to develop a visual survey approach that starts field efforts in areas of the site expected to be the least probable of encountering MEC, and work to the areas where MEC is known to exist. This approach should minimize work stoppages at the start of the field effort allowing this effort to be completed as efficiently as possible. Some work stoppages, however, are anticipated due to MEC/ICM discoveries, procedures to report MEC/ICM finds will be coordinated with USACE, Baltimore District Mr. Greene.

Next Steps

- Malcolm Pirnie will proceed with the SI Work Plan. A stakeholder draft will be submitted no later than 1 December 2008.
- Meeting concluded at 11:45.

The following action items resulted from this meeting:

- Malcolm Pirnie will provide meeting minutes to all attendees.
- Malcolm Pirnie will look at data collected from within the L2-L3 Extended Buffer Area to determine if it is sufficient for completing MRSPPs.
- ➤ Malcolm Pirnie will work with USACE to submit an ICM Waiver Amendment.
- Malcolm Pirnie will work with USACE to propose a procedure for notifying the appropriate authorities is MEC/ ICMs is encountered.
- Ms. Gross will submit an ROE request to USDA.
- USDA will communicate with Malcolm Pirnie regarding particular areas of concern for the MEC survey.



MEETING MINUTES

Purpose: Joliet Army Ammunition Plant Site Inspection Technical Project Planning

Meeting

Stakeholders Meeting 10:00am – 2:30pm

Location: Wilmington, Illinois

Date: 20 July 2009

Attendees	Organization	Phone	Email
Tom Barounis	USEPA	312-353-5577	barounis.thomas@epa.gov
Travis McCoun	USACE-Baltimore	410-962-6728	Travis.Mccoun@usace.army.mil
Art Holz	JOAAP	815-423-2870	arthur.m.holz@us.army.mil
Courtney Ingersoll	Malcolm Pirnie	757-873-4415	cingersoll@pirnie.com
Catherine Kelly	Malcolm Pirnie	757-873-4386	ckelly@pirnie.com
Delores Kaitschuck	USDA	815-423-6370	dkaitschuck@fs.fed.us
Bill Mains	USDA	815-423-6370	wmains@fs.fed.us
Andrew Maly	USAEC	410-436-1611	andrew.maly@us.army.mil
Greg Peterson	Malcolm Pirnie	760-888-7400	gpeterson@pirnie.com
Nicole Wilson	IEPA	217-785-8729	nicole.wilson@illinois.gov

The 20 July 2009 Technical Project Planning (TPP) Meeting for the Military Munitions Response Program (MMRP) Site Inspection (SI) of the L2-L3 Extended Buffer Area for Joliet Army Ammunition Plant (JOAAP), Wilmington, Illinois was conducted by the United States Army Environmental Command (USAEC), United States Army Corps of Engineers (USACE), Baltimore District and Malcolm Pirnie, Inc. at JOAAP.

The following summarizes discussions held at the JOAAP MMRP TPP meeting. These notes do not include a summary of every discussion held, nor do they quote exact words used. Rather, this document is intended to be used by the stakeholders in attendance to reference previously-held conversations and decisions. Handouts including slides and maps were provided to all attendees. Information not presented in the slides and additional discussions are included in the meeting minutes. The following issues were discussed:

- > Introduction
- The meeting convened at approximately 10:00. All meeting attendees provided personal introductions.
- > SI Briefing
- The SI briefing was led by Ms. Courtney Ingersoll (Malcolm Pirnie). Handouts included a copy of the briefing and a copy of relevant maps from the Stakeholder Draft SI Addendum and Historic Records Review (HRR) Report Addendum. A copy of the briefing and sign in sheet is included in the minutes as Attachment 1.

Comments and discussion generated from the briefing are described below.

- ➤ Ms. Ingersoll summarized the meeting goals, the SI goals, and the TPP Process, including the TPP Phases and where the JOAAP SI project falls in the process. Within the MMRP SI framework, munitions of explosive concern (MEC) have been confirmed on site. Data was collected during the SI Addendum field work to determine if an Interim Removal Action is necessary and/or if the site should proceed to a Remedial Investigation/Feasibility Study (RI/FS). Analysis of the data suggests further investigation via RI/FS is recommended.
- Mr. Tom Barounis (USEPA) presented some of the comments generated by USEPA. The comment requiring discussion regarded whether 10% of the site was visually surveyed during the field work. Ms. Ingersoll, Mr. Greg Peterson, and Ms. Catherine Kelly (Malcolm Pirnie) explained the site visual survey occurred along the transects presented in the October 2008 TPP meeting and subsequent Final SI Report Addendum Work Plan. Acreage surveyed by the summery 2007 USACE survey was not included in the SI Addendum field work since it had previously been surveyed. Text will be clarified to better explain coverage of the site.
 - o Mr. Barounis will email USEPA comments on 21 July 2009.
- ➤ Ms. Ingersoll led the discussion presenting the field work completed in March 2009, as well as findings and recommendations. Mr. Peterson described items located in the field. The map with the new proposed boundary for the L2-L3 Extended Buffer Area was discussed.
 - Mr. Bill Mains (USDA) requested that the inner border of the L2-L3 Extended Buffer Area be drawn to connect with the 200-foot buffers so there are no gaps between the two MRSs. Malcolm Pirnie will make the correction.
 - Mr. Mains also requested that the dam be labeled on the map to assist with orientation.
- > The proposed MRS boundary was agreed upon by the stakeholders with the above-mentioned modifications.

- Clarification was needed for the symbol denoting "Edge of Contacts" on Figure 4-4. Malcolm Pirnie will clarify the symbol which denotes the point at which contacts were no longer being made on the west side of the MRS by the all-metals detector during the instrument-assisted visual survey. East of this point, several contacts were made, but as the survey continued along the transect moving west of the "Edge of Contacts" point to the MRS boundary, the all-metals did not detect any additional anomalies.
- Mr. Andrew Maly requested an explanation as to why certain areas were excluded from the proposed L2-L3 Extended Buffer Area when contacts were made by the all-metals detector in the vicinity.
 - Mr. Peterson explained that the "blue dot" (Figure 4-4) west of L2 was along a fence line and is likely associated with the fence or machinery used in agriculture. Nothing else was found in the area except for scrap associated with the fence.
 - Mr. Peterson explained that the "blue dot" located southwest of L3 was surrounded by former foundations, pipes, and other junk. Since nothing else was found in vicinity, the contact was likely related to this abandoned material.
- Mr. Peterson explained that areas excluded due to swampy nature looked to always be wet. They did not appear to be seasonally wet.
- Mr. Art Holz (JOAAP) confirmed the L2 and L3 MRSs (areas inside the 200-foot buffer of the IRP sites) have not been transferred.
- Mr. Travis McCoun (USACE) recommended renaming the MRSs to minimize confusion. Ms. Ingersoll responded this could be done and was a good idea; however, it is USAEC's decision. General consensus is the current naming convention is acceptable.

AFTERNOON SESSION

Discussion of MRSPPs

Attendees: USEPA, IEPA, JOAAP, USAEC, USACE, Baltimore, and Malcolm Pirnie.

(USDA was invited and chose not to attend the afternoon session)

- ➤ Ms. Ingersoll presented MRSPP tables for the L2-L3 Extended Buffer Area.
 - o Changes to be made to tables:
 - Add "5" to Table 8 since there are residential and commercial establishments within 2 miles of the site
 - Add "5" to Table 9 since both ecological and cultural establishments are present on the site.
 - Update Table 10 accordingly

- Language from Table 5 for the L2-L3 Extended Buffer Area will be edited to match language in Table 5 from the other JOAAP sites (Training Area 7, L34, L2, L3).
- Mr. Maly presented MRSPPs for Training Area 7, L34, L2, and L3.
- ➤ Ms. Ingersoll will send Mr. Maly the list of ecological resources (threatened and engendered species).
- ➤ Discussion regarding MC at L34: According to the 2005 SI, sampling at L34 occurred in 1981 and 1991. In 1981, concentrations > RGs; in 1991, concentrations < RGs. The MRSPP tables should reflect the 1991 sampling event (Phase I RI). Tables will be updated accordingly. Language from the 2005 SI will be included in the MC tables as appropriate.</p>
- Agreed that the SI Addendum will include the updated MRSPPs from all JOAAP sites since this is an Addendum to the original SI, and the tables have been updated.
- ➤ Ms. Ingersoll will send Mr. Maly the MRSPP for the L2-L3 Extended Buffer Area so he can update tables for the other sites as necessary.
- Meeting concluded at 3:30 PM.

The following action items resulted from this meeting:

✓ Malcolm Pirnie will provide meeting minutes to all attendees.

- ✓ Mr. Barounis will send USEPA comments to the Army.
- ✓ Malcolm Pirnie will send a Response to Comments table for approval by all stakeholders.
- ✓ Malcolm Pirnie will update MRSPP for L2-L3 Extended Buffer Area according to discussions at the meeting.
- ✓ Mr. Maly will update MRSPPs for Training Area 7, L34, L2, and L3 according to discussions at the meeting.
- ✓ Malcolm Pirnie will send Mr. Maly a list of ecological resources at JOAAP.
- ✓ Malcolm Pirnie will address all comments and issue the Final SI Addendum on or about 19 August 2009.

Joliet Army Ammunition Plant – L2-L3 Extended Buffer Area Military Munitions Response Program (MMRP) Site Inspection (SI) Technical Project Planning Meeting Sign-In Sheet 20 July 2009

Present Name	Organization	Title	Telephone	Email
Mark Frueh	USACE—Louisville		815-423-5642 Cell: 815-483-9137	mark.m.frueh@usace.army.mil
Travis McCoun	USACE—Baltimore		410-436-1611	Travis.Mccoun@usace.army.mil
Art Holz	JOAAP		815-423-2870	arthur.m.holz@us.army.mil
Courtney Ingersoll	Malcolm Pirnie, Inc.		757-873-4415	cingersoll@pirnie.com
Christopher Inlow	USACE-Louisville		502-315-6802	chris.inlow@usace.army.mil
Catherine Kelly	Malcolm Pirnie, Inc.		757-873-4386	ckelly@pirnie.com
	Midewin			
Tom Barounis	USEPA		312-353-5577	parounis.thomas@epa.gov
Andrew Maly	USAEC		410-436-1611	andrew.maly@us.army.mil
Nicole Wilson	IEPA		217-785-8729	nicole.wilson@illinois.gov
Greg Peterson	Malcolm Pirnie		760-602-3804	gpeterson@pirnie.com
Dolores Kni	tschuck Midewi	<i>y M</i>	815-423-216	1 dkaitschuckOfs for
- BILL /	MAINS Mide	via R9 R	0 81542	36370 wminspfe. 45

Military Munitions Response Program (MMRP) Site Inspection (SI) Technical Project Planning Meeting

Joliet Army Ammunition Plant Wilmington, IL 20 July 2009









Agenda

Introductions / Meeting Goals
Review of Site Inspection (SI) Goals and TPP Process
Results, Conclusions, Recommendations of Site Inspection
Break
Review and Discussion of Recommendations
Summary of TPP Results / Project Status / Questions
Discussion of Draft MRSPP Scoring – All MRSs





olutions for Life PIRNIE

MMRP SI Technical Project Planning Meeting

Joliet Army Ammunition Plant

PART ONE: Introductions, Meeting Goals







Introduction

- Program Manager US Army Environmental Command (USAEC)
- Executing Agent –USACE, Baltimore District
- Contractor Team Malcolm Pirnie
- Installation POC Art Holz
- USAEC Program Manager Mary Ellen Maly
- USACE Project Manager Travis McCoun
- USAEC Environmental Restoration Manager Andrew Maly
- Pirnie Program Manager Heather Polinsky
- Pirnie Project Manager Courtney Ingersoll
- Pirnie Field Project Manager Catherine Kelly
- Pirnie UXOSO Greg Peterson
- USACE, Louisville District Chris Inlow
- EPA Region 5 Representative Tom Barounis
- Illinois EPA Nicole Wilson
- USDA Teresa Chase





Solutions for Life



Meeting Goals

- Review objectives of project / Site Inspection
- Review results / conclusions of Site Inspection
- Identify concerns
- Review recommendations of Site Inspection
- Review MRSPPs from all MMRP sites
- Comments on the MRSPPs
- Achieve consensus on next action if applicable









MMRP SI Technical Project Planning Meeting

Joliet Army Ammunition Plant

PART TWO: Review of TPP Process & Summary of MMRP SI Goals





Solutions for Life




TPP Process

- Developed by US Army Corps of Engineers
- Comprehensive systematic planning tool
 - Type, quality, and quantity of data
 - Meet project objectives
 - 4 phase program
 - Iterative









MMRP Summary

- MMRP is directed by:
 - Law
 - OSD
 - Army
- MMRP provides for the investigation and response at sites with:
 - MEC (UXO / DMM)
 - MC







MMRP SI Project Goals

- Primary Goal
 - Collect information necessary to make a decision if the following actions are warranted at the site:
 - MMRP Remedial Investigation/Feasibility Study (RI/FS);
 - Interim Response Emergency or Time Critical (Removal Action) Required; or
 - · No Further Action Determination.
- Secondary Goals
 - Collect necessary information required to improve Cost to Complete (CTC) estimate; and
 - Complete draft Munitions Response Site (MRS) Prioritization Protocol.






MMRP SI Steps

- √ Stakeholder identification
- √ Historic records search
- > Technical project planning
- ✓ Site Inspection



olutions for Life






MMRP SI Technical Project Planning Meeting

Joliet Army Ammunition Plant

PART THREE: Results, Conclusions, and Recommendations







Summary of TPP Decisions

- SI tasks were determined during the TPP session held on 15 October 2008.
- The results of the TPP session dictated both the MEC/MD field activities and decision not to collect MC samples.
- The results of the TPP session dictated the basis for NFA or RI recommendations.
- Additional communications after the TPP session resulted in the decision no addendum to the ICM waiver was needed.







Summary of TPP 2 Decisions

- Stakeholders agreed the purpose of the SI was for refinement of the L2-L3 Extended Buffer Area boundary.
- Stakeholders concurred if no MEC/MD is discovered during the SI, the site boundary will be refined to reflect the SI field results. As such, no MEC/ MD, no MC. Therefore stakeholders agreed MC sampling would not be necessary in the SI. Should additional MC sampling be necessary, it would occur in the RI.
- Stakeholders concluded the L2-L3 Extended Buffer Area boundary does not need to be contiguous.





MALCO PIRN

Summary of MEC TPP 2 Decision

MRS	MEC SI Activities		
IVIKS	Activity	Purpose	
L2-L3 Extended Buffer Area	Instrument-assisted surface sweep / visual survey of approximately 40 acres (10% of site acreage)	To support MEC NFA or RI/FS determination. If no MEC are identified, the site qualifies for NFA. If MEC are encountered, the site will move to an RI/FS. The site will be surveyed in a manner to better define a boundary of the extent of MEC on the MRS.	








Summary of MC TPP 2 Decision

MRS	MC SI Activities		
IVIKS	Activity	Purpose	
L2-L3 Extended Buffer Area	No field work will be completed in association with MC. Samples were previously collected in this area, which then received an NFA designation with regard to soil during the 2004 Record of Decision.	Data previously collected will be referenced as appropriate in the SI Report.	











HRR Findings – 2001 Ordnance Removal and Site Characterization Report

- L2
 - MEC occasionally kicked out during burning activities
 - Only fragments of a BLU-26/B were found outside the fence line
 - 92 MEC items found inside the fence line (IRP site) near boundary – therefore RA recommended for 200' perimeter
- L3
 - MEC occasionally kicked out during burning activities
 - Only one-half of one BLU-26/B was found outside the fence line
 - 30 MEC items found inside the fence line (IRP site) near boundary – therefore RA recommended for 200' perimeter










HRR Findings - 2007 Site Walk L3 MEC Finds

- USACE OESS and a contractor led team conducted a site walk outside L3 during the Summer 2007.
- Locations of MEC finds are marked by blue and red circles. Paths walked are seen by red lines.
- MEC is found up to the estimated extended buffer boundary.







Solutions for Life




HRR Findings – 2007 – RA - Conclusions


- EE/CA was implemented and recommendations carried through initial MMRP SI (200' buffer around IRP sites JAAP-0L2 and JAAP-0L3 = MRSs)
- MRSs not inclusive of MEC
- New MRS result of physical observation of MEC beyond boundaries of JAAP-001-R-01 and JAAP-002-R-01.
- Site is approximately 396 Ac
- Former Demolition Area and Explosive Burning Ground.
- Current land use is agricultural/recreational









Solutions for Life MAI





CMSI1 Courtney MS Ingersoll, 6/9/2009



SI Conclusions and Recommendations

Conclusions

The findings of the MEC SI field activities indicate MEC and MD evidence in the L2-L3 Extended Buffer Area (JAAP-001-R-02) MRS. This evidence indicates that a percentage of the L2-L3 Extended Buffer Area (JAAP-001-R-02) MRS to the east and southeast has moderate to heavy MEC and/or MD present and the south and southwest portions have light to moderate MEC and/or MD present.

Recommendations

 Further investigation via a Remedial Investigation is recommended.







JOAAP MMRP SI Project Schedule

- ✓ Kick off and Site Visit 11 Jun 2008
- ✓ Data Collection Trip Report & Meeting Minutes 8 Jul 2008
- ✓ Stakeholder Draft HRR 15 Sep 2008
- ✓ DQO Planning Session (TPP) 15 Oct 2008
- ✓ Final HRR 13 Nov 2008
- ✓ Stakeholder Draft SI Work Plan 18 Dec 2008
- ✓ Final SI Work Plan 13 Feb 2009
- ✓ MMRP SI MEC/MC Field Work 1-6 Mar 2009
- ✓ Stakeholder Draft SI Report 22 Jun 2009
- ✓ TPP Session 2 20 Jul 2009
- Final TPP Session 2 Meeting Minutes 5 Aug 2009
- Final SI Report 19 Aug 2009
- ERIS Upload and GIS Deliverable 7 Sep 2009

Schedule dates are tentative

Schedule Assumes: Internal Army reviews 20 working days; Stakeholder reviews 45 days.





Solutions for Life



Questions?







Solutions for Life



MMRP SI Technical Project Planning Meeting

Joliet Army Ammunition Plant

PART FOUR: **MRSPPs**









MRSPP Stakeholder Notification

Requirements:

- Notify stakeholders of the opportunity to participate in the Protocol application. The Army shall notify the stakeholders seeking their involvement prior to beginning prioritization.
- > Publish an announcement, prior to beginning the prioritization, in local community publications requesting information pertinent to prioritization or sequencing decisions of the MRS, to ensure the local community is aware of the opportunity to participate in the application of the rule.

See 32 CFR § 179.5 for specific regulatory language







MRSPP Stakeholder Notification

Process:

- Notification letter to be sent and public announcement published by Installation prior to finalization of the HRR, or as soon as feasible.
 - Environmental Protection Agency
 - Other federal agencies
 - · State regulatory agencies,
 - · Local restoration advisory boards
 - Technical review committees
 - · Local community stakeholders
 - · Current land owners (if the land is outside of DOD control)
- If requested, a meeting can be conducted to allow participation in the scoring process.
- Stakeholders will have the opportunity to review and comment on the draft MRSPP scores within the Draft SI Report.
- If no requests for a meeting and/or comments on the initial scores within 30-days of submittal of the Draft SI Report -- Scores will be final within the Final SI Report.





Solutions for Lif



MMRP SI Technical Project Planning Meeting

Joliet Army Ammunition Plant

Back Up Slides





Calutiana for Life



Acronym List

A/I	Active/ Inactive	MEC	Munitions and Explosives of Concern
BRAC	Base Realignment and Closure	MRA	Munitions Response Area
BD/DR	Building Demolition/ Debris Removal	MRS	Munitions Response Site
CERCLA	Comprehensive Environmental Response, Compensation and Liability Act	MRSPP	Munitions Response Site Prioritization Protocol
СТС	Cost to Complete	OE	Ordnance and Explosives
CTT	Closed, Transferred, and Transferring	PE	Preliminary Assessment
DERP	Defense Environmental Restoration Program	POC	Point of Contact
DMM	Discarded Military Munitions	RAC	Risk Assessment Code
DoD	Department of Defense	RCRA	Resource Conservation and Recovery Act
FUDS	Formerly Used Defense Site	SI	Site Inspection
HRR	Historical Records Review	TPP	Technical Project Planning
IRP	Installation Restoration Program	UXO	Unexploded Ordnance
MC	Munitions Constituents	USACE	U.S. Army Corps of Engineers
MMRP	Military Munitions Response Program	USAEC	U.S. Army Environmental Command









Presentation References

- 1. FY02 DERP Annual Report to Congress
- 2. USAEC, MMRP Public Affairs Package
- 3. DERP Management Guidance, Sept 2001
- 4. USACE, Program Management Plan MMRP SI
- 5. USACE, EM 200-1-2, Technical Planning Process, 31 Aug 1998
- 6. 32 CFR Part 179, Munitions Response Site Prioritization Protocol





Solutions for Life



MMRP Overview

Military Readiness:

- The level of military readiness necessary to deter adversaries and defend our nation require the Department of Defense (DoD) to develop, test, and deploy weapons systems and military munitions, and then train its personnel to use and maintain these systems
- The U.S. Armed Forces are the most well- trained, well equipped Military fighting forces in the world, because they train as they fight, under realistic battle conditions

Explosives Contamination:

 As a result, some former DoD defense sites historically used to accomplish the Defense mission may contain unexploded ordnance (UXO), discarded military munitions (DMM), and munitions constituents (MC)

DoD Response to Concerns: MMRP

 In 2001, Congress and DoD created the MMRP to address human health, safety, and environmental concerns at defense sites





Solutions for Life



Definitions

UXO (Unexploded Ordnance) – Ordnance that was fired, but did not function properly and remains unexploded.

DMM (Discarded Military Munitions) – Munitions that have been improperly abandoned or disposed. Generally buried.

MC (Munitions Constituents) – Chemical residues originating from UXO or DMM. Does not include production wastes (lagoons, spills, contaminated production buildings, etc.).

MEC (Munitions and Explosives of Concern) – Includes UXO, DMM, and MC (at high enough concentrations [10%] to pose an explosive hazard).

MRA (Munitions Response Area) – Property known or suspected to contain MEC or MC.

MRS (Munitions Response Site) – A discrete location within a Munitions Response Area (MRA) requiring a munitions response.





Solutions for Life



Definitions (continued)

Range:

A designated land or water area set aside, managed, and used to conduct research on, develop, and evaluate military munitions and explosives, other ordnance, or weapons systems, or to train military personnel in their use and handling. Ranges include firing lines and positions, maneuver areas, firing lanes, test pads, detonation pads, impact areas, and buffer zones with restricted access and exclusionary areas.

Other than Operational Range:

Closed, Transferred, Transferring (CTT) Range

Operational Range:

Range under control of DoD used for range activities, or if not used, is considered by DoD to be a range and has not been put to use for activities incompatible with range activities







Definitions (continued)

Military Munitions Response:

Response actions to address UXO, DMM, MC

Defense Site:

- Is or was owned by, leased to, or possessed by DoD
- Not including sites with releases after 30 September 2002 or:

Operational	Munitions in an	Facility used for or was
Ranges	operating storage or	permitted for the treatment
	manufacturing	or disposal of military
	facility	munitions







Definitions (continued)

Military Munitions:

 Includes munitions ranging from small arms to large bombs, and other items such as chemical warfare agents, but not inert items and nuclear devices.

All ammunition products and components produced for or used by the armed forces for national defense and security, including ammunition products or components under the control of the Department of Defense, the Coast Guard, the Department of Energy, and the National Guard. The term includes confined gaseous, liquid, and solid propellants, explosives, pyrotechnics, chemical and riot control agents, smokes, and incendiaries, including bulk explosives and chemical warfare agents, chemical munitions, rockets, guided and ballistic missiles, bombs, warheads, mortar rounds, artillery ammunition, small arms ammunition, grenades, mines, torpedoes, depth charges, cluster munitions and dispensers, demolition charges, and devices and components thereof. The term does not include wholly inert items, improvised explosive devices, and nuclear weapons, nuclear devices, and nuclear components, except that the term does include non nuclear components of nuclear devices that are managed under the nuclear weapons program of the Department of Energy after all required sanitization operations under the Atomic Energy Act of 1954 (42 U.S.C. 2011 et seq.) have been compoleted.

Complete definition can be found in 32 CFR Part 179, Munitions Response Site Prioritization Protocol





Solutions for Life



MMRP Programmatic Overview

Background:

- Defense Environmental Restoration Program (DERP) is DoD's cleanup program.
- Sep 2001 DoD DERP Management Guidance
 - designated the MMRP as a new program element
 - provides information and guidance on implementation
- MMRP was established to address human health, safety, and environmental concerns at defense sites with:
 - Munitions and explosives of concern (MEC), which include
 - Unexploded ordnance (UXO) and
 - Discarded military munitions (DMM)
 - Munitions constituents (MC)
- FY02 Defense Authorization Act modified the DERP Guidance
 - Required the Services to complete an inventory of defense sites with MEC or MC
 - Required DoD to develop a Prioritization Protocol to assign cleanup priority to sites

Note – At FUDS and BRAC sites, munitions have historically been addressed, but this is a very new area for Active Installations!





Solutions for Life



MMRP Programmatic Overview Cont.

Army Completed their Range Inventory Program from 2000 - 2003

- Phase 1 Electronic survey: late 2000, operational and other than operational ranges, US & overseas, "range complexes"
- Phase 2 Operational Range Inventory: Oct 2000 to Jan 2003
- Phase 3 Other than Operational Ranges & Defense Sites Inventory: Oct 2001 to Dec 2003, resulting in:
 - 183 Installations w/ Munitions Response Sites
 - 937 Munitions Response sites
 - Joliet AAP Other than Operational Range Inventory September 2002





MMRP Programmatic Overview Cont.

DoD MMRP Goals:

- In 2004, DoD established 2 MMRP goals for the Services:
 - Complete all Preliminary Assessments (PAs) by 2007
 - Complete all Site Inspections (SIs) by 2010
- PA goal met in Dec 2003 through completion of the Phase 3 Range Inventory
- SIs began in FY03 to be completed in FY10





MMRP Programmatic Overview Cont.

MMRP Eligibility:

- > Releases before 30 Sep 02
- > Not an operational range
- > Not a permitted munitions disposal facility
- ➤ Site not in AEDB-R or, if site is in AEDB-R as IRP site, its CTC doesn't include all costs for UXO, DMM or MC

Note - Release for munitions means shooting, firing, or placement









MMRP Programmatic Overview Cont.

Similarities/Difference Between MMRP & IRP

Similar

- ➤ Follows CERCLA or RCRA
- Same Funding Source (ER,A)
- ► IAPs
- Stakeholder Participation
- DSMOA

Different

- Centrally managed by USAEC through the SI Phase – AEDB-R & CTCs
- ➤ Risk Assessment for MEC
- Explosive Safety Submittals
- > MRS Prioritization Protocol
- > Funding Priorities
- Program Goals





Calutions for Life



MMRP Programmatic Overview Summary

- The September 2001 DERP Management Guidance and the National Defense Authorization Act of FY02 established the MMRP to address MEC and MC at defense sites. The MMRP:
 - is a new program element of the DERP.
 - follows CERCLA and the National Contingency Plan (may also be implemented under RCRA Corrective Action).
 - only applies to other than operational ranges where MEC and MC is known or suspected and the release occurred prior to 30 Sep 02.
- The Phase 3 Army Range Inventory:
 - Identified MMRP eligible sites
 - Is considered the PA
 - Is the starting point for the SI



Solutions for Life



Appendix E: Military Munitions Response Site Prioritization Protocol (MRSPP)

MRSPPs for all Munitions Response Sites (MRSs) have been included in this Final SI Report Addendum. MRSPPs previously submitted for JAAP-001-R-01, JAAP-002-R-01, JAAP-003-R-01, and JAAP-004-R-01 were updated in August 2009 based on new site data from the 2007 Removal Action.

Munitions Response Sites Include:

Demolition Area (L3): JAAP-001-R-01 L2-L3 Extended Buffer Area: JAAP-001-R-02 Explosive Burning Ground 1 (L2): JAAP-002-R-01 Training Area 7: JAAP-003-R-01 Former Burning Area (L34): JAAP-004-R-01

Table A

MRS Background Information

DIRECTIONS: Record the background information below for the MRS to be evaluated. Much of this information is available from Service and DoD databases. If the MRS is located on a FUDS property, the suitable FUDS property information should be substituted. In the MRS Summary, briefly describe the UXO, DMM, or MC that are known or suspected to be present, the exposure setting (the MRS's physical environment), any other incidental nonmunitions-related contaminants (e.g., benzene, trichloroethylene) found at the MRS, and any potentially exposed human and ecological receptors. If possible, include a map of the MRS.

Mun	Munitions Response Site Name: Demolition Area (L3)						
	nponent: <u>Army, Non-l</u>	·					
Insta	allation/Property Na	me: Joliet Army Amm	nunition Plan	t			
Loca	ation (City, County,	State): Wilmington, V	Vill County, II	llinois			
Poin	it of Contact/Phone	No.: Art Holz; 815-42	23-2870				
Site	Name/Project Name	e (Project No.): <u>JAAP</u>	<u>2-001-R-01</u>				
MRS	SPP Score (Date Sco	ored): <u>14 August 2009</u>	9				
Prep	oarer's Name (Organ	nization): <u>Andrew Ma</u>	ly (USAEC)				
MRS	SPP Rating: 3						
Date Information Entered/Updated: 14 August 2009; Information contained within this scoring was obtained from sources within the Joliet AAP Administrative Record. Point of Contact (Name/Phone): Andrew Maly, 410.436.1611 Project Phase (check only one): □ RI □ FS □ RD □ RA-C □ RIP □ RA-O □ RC ✓ LTM					<u>n</u>		
Media Evaluated (check all that apply): ✓ Groundwater □ Sediment (human receptor) ✓ Surface soil □ Surface Water (ecological receptor) □ Sediment (ecological receptor) □ Surface Water (human receptor)							

MRS Summary:

MRS Description: Describe the munitions-related activities that occurred at the installation, the dates of operation, and the UXO, DMM, or MC known or suspected to be present. When possible, identify munitions, CWM, and MC by type:

Ammunition manufacturing, load, assemble, and packaging occurred between 1941 and 1977. The plant made many types of munitions, including ICM and up to 8-inch Howitzer HE projectiles. This MRS is a boundary around a former demolition area, used for the disposal of off-spec items. Remedial action,

Table A

MRS Background Information

DIRECTIONS: Record the background information below for the MRS to be evaluated. Much of this information is available from Service and DoD databases. If the MRS is located on a FUDS property, the suitable FUDS property information should be substituted. In the MRS Summary, briefly describe the UXO, DMM, or MC that are known or suspected to be present, the exposure setting (the MRS's physical environment), any other incidental nonmunitions-related contaminants (e.g., benzene, trichloroethylene) found at the MRS, and any potentially exposed human and ecological receptors. If possible, include a map of the MRS.

consisting of clearance to 1' depth was conducted in 2007 (HRR Addendum, 2008—Section 2).

Description of Pathways for Human and Ecological Receptors:

Soil is considered to be a complete pathway for Human and Ecological Receptors. MC data was reevaluated to include data from the MRS and not the adjacent IRP site.

Description of Receptors (Human and Ecological):

Human access to the site is limited. The only threatened or endangered species potentially inhabiting JOAAP are grassland birds, including bobolinks, upland sandpipers, and Henslow's sparrows (SI Addendum, 2009-Section 4.1.4.4.3).

EHE Module: Munitions Type Data Element Table

DIRECTIONS: Below are 11 classifications of munitions and their descriptions. Circle the scores that correspond with <u>all</u> the munitions types known or suspected to be present at the MRS.

Note: The terms *practice munitions, small arms ammunition, physical evidence,* and *historical evidence* are defined in Appendix C of the Primer.

Classification	Description	Score
Sensitive	 UXO that are considered most likely to function upon any interaction with exposed persons (e.g., submunitions, 40mm high-explosive [HE] grenades, white phosphorus [WP] munitions, high-explosive antitank [HEAT] munitions, and practice munitions with sensitive fuzes, but excluding all other practice munitions). Hand grenades containing energetic filler. Bulk primary explosives, or mixtures of these with environmental media, such that the mixture poses an explosive hazard. 	30
High explosive (used or damaged)	 UXO containing a high-explosive filler (e.g., RDX, Composition B), that are not considered "sensitive." DMM containing a high-explosive filler that have: Been damaged by burning or detonation Deteriorated to the point of instability. 	25
Pyrotechnic (used or damaged)	 UXO containing a pyrotechnic filler other than white phosphorus (e.g., flares, signals, simulators, smoke grenades). DMM containing a pyrotechnic filler other than white phosphorus (e.g., flares, signals, simulators, smoke grenades) that have: Been damaged by burning or detonation Deteriorated to the point of instability. 	20
High explosive (unused)	 DMM containing a high-explosive filler that: Have not been damaged by burning or detonation Are not deteriorated to the point of instability. 	15
Propellant	 UXO containing mostly single-, double-, or triple-based propellant, or composite propellants (e.g., a rocket motor). DMM containing mostly single-, double-, or triple-based propellant, or composite propellants (e.g., a rocket motor) that are: Damaged by burning or detonation Deteriorated to the point of instability. 	15
Bulk secondary high explosives, pyrotechnics, or propellant	 DMM containing mostly single-, double-, or triple-based propellant, or composite propellants (e.g., a rocket motor). DMM that are bulk secondary high explosives, pyrotechnic compositions, or propellant (not contained in a munition), or mixtures of these with environmental media such that the mixture poses an explosive hazard. 	10
Pyrotechnic (not used or damaged)	 DMM containing a pyrotechnic filler (i.e., red phosphorus), other than white phosphorus filler, that: Have not been damaged by burning or detonation Are not deteriorated to the point of instability. 	10
Practice	 UXO that are practice munitions that are not associated with a sensitive fuze. DMM that are practice munitions that are not associated with a sensitive fuze and that have not: Been damaged by burning or detonation Deteriorated to the point of instability. 	5
Riot control	UXO or DMM containing a riot control agent filler (e.g., tear gas).	3
Small arms	 Used munitions or DMM that are categorized as small arms ammunition. (Physical evidence or historical evidence that no other types of munitions [e.g., grenades, subcaliber training rockets, demolition charges] were used or are present on the MRS is required for selection of this category.) 	2
Evidence of no munitions	Following investigation of the MRS, there is physical evidence that there are no UXO or DMM present, or there is historical evidence indicating that no UXO or DMM are present.	0
MUNITIONS TYPE	DIRECTIONS: Record the single highest score from above in the box to the right (maximum score = 30).	30

EHE Module: Munitions Type Data Element Table

DIRECTIONS: Below are 11 classifications of munitions and their descriptions. Circle the scores that correspond with all

the munitions types known or suspected to be present at the MRS.

Note: The terms practice munitions, small arms ammunition, physical evidence, and historical evidence are defined in

Appendix C of the Primer.

Classification Description Score

DIRECTIONS: Document any MRS-specific data used in selecting the *Munitions Type* classifications in the space

provided.

The site is a 200-foot buffer zone surrounding the IRP site JAAP-0L3, Demolition Area. The Demolition Area consisted of "U" and "L" shaped bermed areas and a burning cage, which was a concrete pad surrounded by a steel mesh cage used to contain the burning debris. Based on work performed c. 1999, a 200-foot buffer was established around the Demolition Area based on the maximum estimated blast radius of items suspected to have been destroyed at the Area.

Work to clear the site to 1' depth was put under contract 2005, and work began and was completed in 2007. The site-specific final report for this site (currently draft) indicates the type and quantity of MEC items recovered. The most significant items were BLU 26 and BLU 32, which are the basis for increasing the score for this Table (Draft Final Site-Specific Report MMRP Site L3, 2008).

EHE Module: Source of Hazard Data Element Table

DIRECTIONS: Below are 11 classifications describing sources of explosive hazards. Circle the scores that correspond with <u>all</u> the sources of explosive hazards known or suspected to be present at the MRS.

Note: The terms former range, practice munitions, small arms range, physical evidence, and historical evidence are defined in Appendix C of the Primer.

Classification	Description	Score
Former range	 The MRS is a former military range where munitions (including practice munitions with sensitive fuzes) have been used. Such areas include impact or target areas and associated buffer and safety zones. 	10
Former munitions treatment (i.e., OB/OD) unit	 The MRS is a location where UXO or DMM (e.g., munitions, bulk explosives, bulk pyrotechnic, or bulk propellants) were burned or detonated for the purpose of treatment prior to disposal. 	$\bigcirc \infty$
Former practice munitions range	The MRS is a former military range on which only practice munitions without sensitive fuzes were used.	6
Former maneuver area	 The MRS is a former maneuver area where no munitions other than flares, simulators, smokes, and blanks were used. There must be evidence that no other munitions were used at the location to place an MRS into this category. 	5
Former burial pit or other disposal area	The MRS is a location where DMM were buried or disposed of (e.g., disposed of into a water body) without prior thermal treatment.	5
Former industrial operating facilities	The MRS is a location that is a former munitions maintenance, manufacturing, or demilitarization facility.	4
Former firing points	The MRS is a firing point, where the firing point is delineated as an MRS separate from the rest of a former military range.	4
Former missile or air defense artillery emplacements	 The MRS is a former missile defense or air defense artillery (ADA) emplacement not associated with a military range. 	2
Former storage or transfer points	The MRS is a location where munitions were stored or handled for transfer between different modes of transportation (e.g., rail to truck, truck to weapon system).	2
Former small arms range	 The MRS is a former military range where only small arms ammunition was used. (There must be evidence that no other types of munitions [e.g., grenades] were used or are present to place an MRS into this category.) 	1
Evidence of no munitions	 Following investigation of the MRS, there is physical evidence that no UXO or DMM are present, or there is historical evidence indicating that no UXO or DMM are present. 	0
SOURCE OF HAZARD	DIRECTIONS: Record <u>the single highest score</u> from above in the box to the right (maximum score = 10).	8

DIRECTIONS: Document any MRS-specific data used in selecting the **Source of Hazard** classifications in the space provided.

Historical records indicate this site is in the kick-out boundary of an area used for demolition of UXO and DMM (SI Report, 2005—Section 4.1).

EHE Module: Location of Munitions Data Element Table

DIRECTIONS: Below are eight classifications of munitions locations and their descriptions. Circle the scores that correspond with **all** the locations where munitions are known or suspected to be present at the MRS.

Note: The terms *confirmed, surface, subsurface, small arms ammunition, physical evidence,* and *historical evidence* are defined in Appendix C of the Primer.

Classification	Description	Score
Confirmed surface	 Physical evidence indicates that there are UXO or DMM on the surface of the MRS. Historical evidence (i.e., a confirmed report such as an explosive ordnance disposal [EOD], police, or fire department report that an incident or accident that involved UXO or DMM occurred) indicates there are UXO or DMM on the surface of the MRS. 	25
Confirmed subsurface, active	 Physical evidence indicates the presence of UXO or DMM in the subsurface of the MRS, and the geological conditions at the MRS are likely to cause UXO or DMM to be exposed, in the future, by naturally occurring phenomena (e.g., drought, flooding, erosion, frost heave, tidal action), or intrusive activities (e.g., plowing, construction, dredging) at the MRS are likely to expose UXO or DMM. Historical evidence indicates that UXO or DMM are located in the subsurface of the MRS and the geological conditions at the MRS are likely to cause UXO or DMM to be exposed, in the future, by naturally occurring phenomena (e.g., drought, flooding, erosion, frost heave, tidal action), or intrusive activities (e.g., plowing, construction, dredging) at the MRS are likely to expose UXO or DMM. 	20
Confirmed subsurface, stable	 Physical evidence indicates the presence of UXO or DMM in the subsurface of the MRS and the geological conditions at the MRS are not likely to cause UXO or DMM to be exposed, in the future, by naturally occurring phenomena, or intrusive activities at the MRS are not likely to cause UXO or DMM to be exposed. Historical evidence indicates that UXO or DMM are located in the subsurface of the MRS and the geological conditions at the MRS are not likely to cause UXO or DMM to be exposed, in the future, by naturally occurring phenomena, or intrusive activities at the MRS are not likely to cause UXO or DMM to be exposed. 	15
Suspected (physical evidence)	 There is physical evidence (e.g., munitions debris such as fragments, penetrators, projectiles, shell casings, links, fins), other than the documented presence of UXO or DMM, indicating that UXO or DMM may be present at the MRS. 	10
Suspected (historical evidence)	There is historical evidence indicating that UXO or DMM may be present at the MRS.	5
Subsurface, physical constraint	 There is physical or historical evidence indicating that UXO or DMM may be present in the subsurface, but there is a physical constraint (e.g., pavement, water depth over 120 feet) preventing direct access to the UXO or DMM. 	2
Small arms (regardless of location)	 The presence of small arms ammunition is confirmed or suspected, regardless of other factors such as geological stability. (There must be evidence that no other types of munitions [e.g., grenades] were used or are present at the MRS to place an MRS into this category.) 	1
Evidence of no munitions	 Following investigation of the MRS, there is physical evidence that there are no UXO or DMM present, or there is historical evidence indicating that no UXO or DMM are present. 	0
LOCATION OF MUNITIONS	DIRECTIONS: Record the single highest score from above in the box to the right (maximum score = 25).	20

DIRECTIONS: Document any MRS-specific data used in selecting the *Location of Munitions* classifications in the space provided.

In 2007, MKM and PIKA International performed a 1' surface clearance of the site. During the clearance operations, the site was subject to flooding, and this resulted in the exposure of previously buried items (which were also cleared). The site will be subject to regular flooding due to its proximity to Prairie Creek. The clearance is documented in the site specific report (Draft Final Site-Specific Final Report MMRP Site L3, 2008).

EHE Module: Ease of Access Data Element Table

DIRECTIONS: Below are four classifications of barrier types that can surround an MRS and their descriptions. The

barrier type is directly related to the ease of public access to the MRS. Circle the score that corresponds

with the ease of access to the MRS.

Note: The term *barrier* is defined in Appendix C of the Primer.

Classification	Description	Score
No barrier	There is no barrier preventing access to any part of the MRS (i.e., all parts of the MRS are accessible).	10
Barrier to MRS access is incomplete	There is a barrier preventing access to parts of the MRS, but not the entire MRS.	8
Barrier to MRS access is complete but not monitored	There is a barrier preventing access to all parts of the MRS, but there is no surveillance (e.g., by a guard) to ensure that the barrier is effectively preventing access to all parts of the MRS.	5
Barrier to MRS access is complete and monitored	There is a barrier preventing access to all parts of the MRS, and there is active, continual surveillance (e.g., by a guard, video monitoring) to ensure that the barrier is effectively preventing access to all parts of the MRS.	0
EASE OF ACCESS	DIRECTIONS: Record the single highest score from above in the box to the right (maximum score = 10).	5

DIRECTIONS: Document any MRS-specific data used in selecting the *Ease of Access* classification in the space provided.

The public has no access to this site; the site is surrounded by a fence with a locked gate, and only two keys exist for the lock. All visitors must be accompanied by facility personnel; however, the area is not monitored to prevent trespassers from gaining access (HRR Addendum, 2008—Section 5.3.2).

Table 5EHE Module: Status of Property Data Element Table

DIRECTIONS: Below are three classifications of the status of a property within the Department of Defense (DoD) and their descriptions. Circle the score that corresponds with the status of property at the MRS.

Classification	Description	Score
Non-DoD control	 The MRS is at a location that is no longer owned by, leased to, or otherwise possessed or used by DoD. Examples are privately owned land or water bodies; land or water bodies owned or controlled by state, tribal, or local governments; and land or water bodies managed by other federal agencies. The MRS is at a location that is owned by DoD, but that DoD has leased to another entity and for which DoD does not control access 24 hours per day. 	5
Scheduled for transfer from DoD control	The MRS is on land or is a water body that is owned, leased, or otherwise possessed by DoD, and DoD plans to transfer that land or water body to the control of another entity (e.g., a state, tribal, or local government; a private party; another federal agency) within 3 years from the date the Protocol is applied.	3
DoD control	The MRS is on land or is a water body that is owned, leased, or otherwise possessed by DoD. With respect to property that is leased or otherwise possessed, DoD must control access to the MRS 24 hours per day, every day of the calendar year.	0
STATUS OF PROPERTY	DIRECTIONS: Record the single highest score from above in the box to the right (maximum score = 5).	3

DIRECTIONS: Document any MRS-specific data used in selecting the *Status of Property* classification in the space provided.

The planned future use for this site is open space for the USDA Midewin National Tallgrass Prairie (HRR Addendum, 2008—Section 5.3.2).

EHE Module: Population Density Data Element Table

DIRECTIONS: Below are three classifications for population density and their descriptions. Determine the population density per square mile that most closely corresponds with the population of the MRS, including the area within a two-mile radius of the MRS's perimeter. Circle the most appropriate score.

Note: Use the U.S. Census Bureau tract data available to capture the <u>highest</u> population density within a two-mile radius of the perimeter of the MRS.

Classification	Description	Score
> 500 persons per square mile	There are more than 500 persons per square mile in the U.S. Census Bureau tract in which the MRS is located.	5
100–500 persons per square mile	 There are 100 to 500 persons per square mile in the U.S. Census Bureau tract in which the MRS is located. 	3
< 100 persons per square mile	 There are fewer than 100 persons per square mile in the U.S. Census Bureau tract in which the MRS is located. 	1
POPULATION DENSITY	DIRECTIONS: Record the single highest score from above in the box to the right (maximum score = 5).	3

DIRECTIONS: Document any MRS-specific data used in selecting the *Population Density* classification in the space provided.

U.S. Census Bureau 2000 data, Will County = 296 - 600 persons per square mile. The maximum data class of persons per square mile in the town of Wilmington, which is the closest town to the site is 367.

EHE Module: Population Near Hazard Data Element Table

DIRECTIONS: Below are six classifications describing the number of inhabited structures near the MRS. The number of inhabited buildings relates to the potential population near the MRS. Determine the number of inhabited structures within two miles of the MRS boundary and circle the score that corresponds with the number

of inhabited structures.

Note: The term *inhabited structures* is defined in Appendix C of the Primer.

Classification	Description	Score
26 or more inhabited structures	There are 26 or more inhabited structures located up to 2 miles from the boundary of the MRS, within the boundary of the MRS, or both.	5
16 to 25 inhabited structures	 There are 16 to 25 inhabited structures located up to 2 miles from the boundary of the MRS, within the boundary of the MRS, or both. 	4
11 to 15 inhabited structures	There are 11 to 15 inhabited structures located up to 2 miles from the boundary of the MRS, within the boundary of the MRS, or both.	3
6 to 10 inhabited structures	There are 6 to 10 inhabited structures located up to 2 miles from the boundary of the MRS, within the boundary of the MRS, or both.	2
1 to 5 inhabited structures	There are 1 to 5 inhabited structures located up to 2 miles from the boundary of the MRS, within the boundary of the MRS, or both.	1
0 inhabited structures	There are no inhabited structures located up to 2 miles from the boundary of the MRS, within the boundary of the MRS, or both.	0
POPULATION NEAR HAZARD	DIRECTIONS: Record the single highest score from above in the box to the right (maximum score = 5).	5

DIRECTIONS: Document any MRS-specific data used in selecting the *Population Near Hazard* classification in the space provided.

Homes, offices, a feed mill, and agricultural lands are located within 2 miles of this site. Recent development has increased the number of inhabited structures located up to 2 miles from the boundary of the MRS (HRR Addendum, 2008—Section 5.3.2).

EHE Module: Types of Activities/Structures Data Element Table

DIRECTIONS: Below are five classifications of activities and/or inhabited structures and their descriptions. Review the

types of activities that occur and/or structures that are present within two miles of the MRS and circle the

scores that correspond with all the activities/structure classifications at the MRS.

Note: The term *inhabited structure* is defined in Appendix C of the Primer.

Classification	Description	Score
Residential, educational, commercial, or subsistence	 Activities are conducted, or inhabited structures are located up to two miles from the MRS's boundary or within the MRS's boundary, that are associated with any of the following purposes: residential, educational, child care, critical assets (e.g., hospitals, fire and rescue, police stations, dams), hotels, commercial, shopping centers, playgrounds, community gathering areas, religious sites, or sites used for subsistence hunting, fishing, and gathering. 	5
Parks and recreational areas	 Activities are conducted, or inhabited structures are located up to two miles from the MRS's boundary or within the MRS's boundary, that are associated with parks, nature preserves, or other recreational uses. 	4
Agricultural, forestry	Activities are conducted, or inhabited structures are located up to two miles from the MRS's boundary or within the MRS's boundary, that are associated with agriculture or forestry.	3
Industrial or warehousing	Activities are conducted, or inhabited structures are located up to two miles from the MRS's boundary or within the MRS's boundary, that are associated with industrial activities or warehousing.	2
No known or recurring activities	There are no known or recurring activities occurring up to two miles from the MRS's boundary or within the MRS's boundary.	1
TYPES OF ACTIVITIES/STRUCTURES	DIRECTIONS: Record the single highest score from above in the box to the right (maximum score = 5).	5

DIRECTIONS: Document any MRS-specific data used in selecting the *Types of Activities/Structures* classifications in the space provided.

Homes, offices, a feed mill, and agricultural lands are located within 2 miles of this site. The planned future use for this site is open space for the USDA Midewin National Tallgrass Prairie which is also presently located within 2 miles of the site. Recent development has increased the number of residences located within 2 miles of the MRS (HRR Addendum, 2008—Section 5.3.2).

EHE Module: Ecological and/or Cultural Resources Data Element Table

DIRECTIONS: Below are four classifications of ecological and/or cultural resources and their descriptions. Review the

types of resources present and circle the score that corresponds with the ecological and/or cultural

resources present on the MRS.

Note: The terms ecological resources and cultural resources are defined in Appendix C of the Primer.

Classification	Description	Score
Ecological and cultural resources present	There are both ecological and cultural resources present on the MRS.	5
Ecological resources present	There are ecological resources present on the MRS.	3
Cultural resources present	There are cultural resources present on the MRS.	3
No ecological or cultural resources present	There are no ecological resources or cultural resources present on the MRS.	0
ECOLOGICAL AND/OR CULTURAL RESOURCES	DIRECTIONS: Record <u>the single highest score</u> from above in the box to the right (maximum score = 5).	3

DIRECTIONS: Document any MRS-specific data used in selecting the *Ecological and/or Cultural Resources* classification in the space provided.

This site is adjacent to Prairie Creek and Kemery Lake. An ecologist at Midewin Tallgrass Prairie confirmed that grassland birds are the only threatened and endangered species at JOAAP. These birds include bobolinks, upland sandpipers, and Henslow's sparrows (HRR Addendum, 2008—Section 5.3.3.2).

Table 10Determining the EHE Module Rating

DIRECTIONS:

- 1. From Tables 1–9, record the data element scores in the **Score** boxes to the right.
- 2. Add the **Score** boxes for each of the three factors and record this number in the **Value** boxes to the right.
- Add the three Value boxes and record this number in the EHE Module Total box below.
- 4. Circle the appropriate range for the **EHE Module Total** below.
- 5. Circle the **EHE Module Rating** that corresponds to the range selected and record this value in the **EHE Module Rating** box found at the bottom of the table.

Note:

An alternative module rating may be assigned when a module letter rating is inappropriate. An alternative module rating is used when more information is needed to score one or more data elements, contamination at an MRS was previously addressed, or there is no reason to suspect contamination was ever present at an MRS.

	Source	Score	Value	
Explosive Hazard Factor Data Ele	ements			
Munitions Type	Table 1	30	30	
Source of Hazard	Table 2	8	38	
Accessibility Factor Data Elemen	nts			
Location of Munitions	Table 3	20	28	
Ease of Access	Table 4	5		
Status of Property	Table 5	3		
Receptor Factor Data Elements		_	_	
Population Density	Table 6	3		
Population Near Hazard	Table 7	5		
Types of Activities/Structures	Table 8	5	16	
Ecological and/or Cultural Resources	Table 9	3	•	
EHE MODULE TOTAL 82				
EHE Module Total	EHE Module Rating		ating	
92 to 100		Α		
82 to 91	(B)			
71 to 81	С			
60 to 70	D			
48 to 59	Е			
38 to 47	F			
less than 38	G			
	Evaluation Pending			
Alternative Module Ratings	No Longer Required			
	No Known or Suspected Explosive Hazard			
EHE MODULE RATING	В			

CHE Module: CWM Configuration Data Element Table

DIRECTIONS: Below are seven classifications of CWM configuration and their descriptions. Circle the scores that

correspond with <u>all</u> the CWM configurations known or suspected to be present at the MRS. **Note:** The terms *CWM/UXO*, *CWM/DMM*, *physical evidence*, and *historical evidence* are defined in Appendix C of the

Primer.

Classification	Description	Score
CWM, that are either UXO, or explosively configured damaged DMM	 The CWM known or suspected of being present at the MRS are: CWM that are UXO (i.e., CWM/UXO) Explosively configured CWM that are DMM (i.e., CWM/DMM) that have been damaged. 	30
CWM mixed with UXO	The CWM known or suspected of being present at the MRS are undamaged CWM/DMM or CWM not configured as a munition that are commingled with conventional munitions that are UXO.	25
CWM, explosive configuration that are undamaged DMM	The CWM known or suspected of being present at the MRS are explosively configured CWM/DMM that have not been damaged.	20
CWM/DMM, not explosively configured or CWM, bulk container	 The CWM known or suspected of being present at the MRS are: Nonexplosively configured CWM/DMM either damaged or undamaged Bulk CWM (e.g., ton container). 	15
CAIS K941 and CAIS K942	The CWM/DMM known or suspected of being present at the MRS are CAIS K941-toxic gas set M-1 or CAIS K942-toxic gas set M-2/E11.	12
CAIS (chemical agent identification sets)	CAIS, other than CAIS K941 and K942, are known or suspected of being present at the MRS.	10
Evidence of no CWM	Following investigation, the physical evidence indicates that CWM are not present at the MRS, or the historical evidence indicates that CWM are not present at the MRS.	0
CWM CONFIGURATION	DIRECTIONS: Record <u>the single highest score</u> from above in the box to the right (maximum score = 30).	0

DIRECTIONS: Document any MRS-specific data used in selecting the *CWM Configuration* classifications in the space provided.

The historical use of the site did not include CWM (HRR Addendum, 2008—Section 4.3.3). EODT performed a site characterization for this area in 2001 and no CWM was found. Site clearance to 1' depth conducted in 2007 did not find any CWM (Draft Final Site-Specific Final Report MMRP Site L3, 2008).

Tables 12 - 19

CHE Module: Sources of CWM Data Element Table

DIRECTIONS: Below are 11 sources of CWM hazards and their descriptions. Review these classifications and circle

the scores that correspond with all the sources of CWM hazards known or suspected to be present at

the MRS.

Note: The terms CWM/UXO, CWM/DMM, CAIS/DMM, surface, subsurface, physical evidence, and historical evidence

are defined in Appendix C of the Primer.

Classification Description Score

No known or suspected CWM hazard is expected at this site. Therefore, Tables 12 through 19 have been intentionally omitted according to Active Army Guidance.

Table 20 Determining the CHE Module Rating

DIRECTIONS:

- From Tables 11–19, record the data element scores in the Score boxes to the right.
- Add the **Score** boxes for each of the three factors and record this number in the **Value** boxes to the right.
- Add the three Value boxes and record this number in the CHE Module Total box below.
- 4. Circle the appropriate range for the **CHE Module Total** below.
- 5. Circle the **CHE Module Rating** that corresponds to the range selected and record this value in the **CHE Module Rating** box found at the bottom of the table.

Note:

An alternative module rating may be assigned when a module letter rating is inappropriate. An alternative module rating is used when more information is needed to score one or more data elements, contamination at an MRS was previously addressed, or there is no reason to suspect contamination was ever present at an MRS.

	Source	Score	Value
CWM Hazard Factor Data Elemer	nts		
CWM Configuration	Table 11	0	0
Sources of CWM	Table 12	-	0
Accessibility Factor Data Elemen	nts		
Location of CWM	Table 13		
Ease of Access	Table 14		
Status of Property	Table 15		
Receptor Factor Data Elements			
Population Density	Table 16		
Population Near Hazard	Table 17		
Types of Activities/Structures	Table 18		
Ecological and/or Cultural Resources	Table 19		
CHE MODULE TOTAL 0			
CHE Module Total	CHE Module Rating		
92 to 100		Α	
82 to 91	В		
71 to 81	С		
60 to 70	D		
48 to 59	Е		
38 to 47	F		
less than 38	G		
	Evaluation Pending		
Alternative Module Ratings	No Longer Required		
	No Known or Suspected CWM Hazard		
CHE MODULE RATING	NO KNOWN OR SUSPECTED CWM HAZARD		

HHE Module: Groundwater Data Element Table

Contaminant Hazard Factor (CHF)

DIRECTIONS: Record the maximum concentrations of all contaminants in the MRS's groundwater and their comparison values (from Appendix B of the Primer) in the table below. Additional contaminants can be recorded on Table 27. Calculate and record the ratios for each contaminant by dividing the maximum concentration by the comparison value. Determine the CHF by adding the contaminant ratios together, including any additional groundwater contaminants recorded on Table 27. Based on the CHF, use the CHF Scale to determine and record the CHF Value. If there is no known or suspected MC hazard present in the groundwater, select the box at the bottom of the table.

Contaminant	Maximum Concentration (μg/L)	Comparison Value (μg/L)	Ratios
CHF Scale	CHF Value	Sum The Ratios	
CHF > 100	H (High)	CHF = [Maximum Concentration of Concentr	ontaminantl
100 > CHF > 2	M (Medium)	[Comparison Value for Conta	minantl
2 > CHF	L (Low)	• '	minantj
CONTAMINANT HAZARD FACTOR	DIRECTIONS: Record the CHF Value (maximum value = H).	from above in the box to the right	
DIRECTIONS: Circle to	Migratory Pathw he value that corresponds most closely to	ray Factor the groundwater migratory pathway at the I	MRS.
Classification	Description		Value
Evident	Analytical data or observable evidence indicates that contamination in the groundwater is present at, moving toward, or has moved to a point of exposure.		Η
Potential	Contamination in groundwater has moved only slightly beyond the source (i.e., tens of feet), could move but is not moving appreciably, or information is not sufficient to make a determination of Evident or Confined.		М
Confined	Information indicates a low potential for contaminant migration from the source via the groundwater to a potential point of exposure (possibly due to the presence of geological structures or physical controls).		L
MIGRATORY PATHWAY FACTOR	DIRECTIONS: Record <u>the single highest value</u> from above in the box to the right (maximum value = H).		
DIRECTIONS: Circle to	Receptor Face that corresponds most closely to		
Classification	Des	cription	Value
Identified	There is a threatened water supply well downgradient of the source and the groundwater is a current source of drinking water or source of water for other beneficial uses such as irrigation/agriculture (equivalent to Class I or IIA aquifer).		I
Potential	There is no threatened water supply well downgradient of the source and the groundwater is currently or potentially usable for drinking water, irrigation, or agriculture (equivalent to Class I, IIA, or IIB aquifer).		M
Limited	There is no potentially threatened water supply well downgradient of the source and the groundwater is not considered a potential source of drinking water and is of limited beneficial use (equivalent to Class IIIA or IIIB aquifer, or where perched aquifer exists only).		
RECEPTOR FACTOR	DIRECTIONS: Record <u>the single highest value</u> from above in the box to the right (maximum value = H).		
	No Kno	wn or Suspected Groundwater MC Hazard	X

HHE Module: Surface Water - Human Endpoint Data Element Table

Contaminant Hazard Factor (CHF)

DIRECTIONS: Record the maximum concentrations of all contaminants in the MRS's surface water and their comparison values (from Appendix B of the Primer) in the table below. Additional contaminants can be recorded on Table 27. Calculate and record the ratios for each contaminant by dividing the maximum concentration by the comparison value. Determine the CHF by adding the contaminant ratios together, including any additional surface water contaminants recorded on Table 27. Based on the CHF, use the CHF Scale to determine and record the CHF Value. If there is no known or suspected MC hazard with human endpoints present in the surface water, select the box at the bottom of the table.

Contaminant	Maximum Concentration (μg/L)	Comparison Value (μg/L)	Ratios	
CHF Scale	CHF Value	Sum The Ratios		
CHF > 100	H (High)	IManimum Cananatation of C	(
100 > CHF > 2	M (Medium)	CHF = [Maximum Concentration of Co	ontaminantj	
2 > CHF	L (Low)	[Comparison Value for Conta	minant]	
CONTAMINANT HAZARD FACTOR	DIRECTIONS: Record the CHF Value (maximum value = H).	from above in the box to the right		
DIRECTIONS: Circle t	Migratory Pathw the value that corresponds most closely to	ray Factor to the surface water migratory pathway at the	MRS.	
Classification	Description			
Evident	Analytical data or observable evidence indicates that contamination in the surface water is present at, moving toward, or has moved to a point of exposure.			
Potential	Contamination in surface water has moved only slightly beyond the source (i.e., tens of feet), could move but is not moving appreciably, or information is not sufficient to make a determination of Evident or Confined.			
Confined	Information indicates a low potential for contamina a potential point of exposure (possibly due to the controls).	ant migration from the source via the surface water to presence of geological structures or physical	L	
MIGRATORY PATHWAY FACTOR	DIRECTIONS: Record the single high right (maximum value =			
	· · ·	the surface water receptors at the MRS.		
Classification		cription	Value	
Identified	Identified receptors have access to surface water	to which contamination has moved or can move.	Н	
Potential	Potential for receptors to have access to surface water to which contamination has moved or can move.			
Limited	Little or no potential for receptors to have access to surface water to which contamination has moved or can move.			
RECEPTOR FACTOR	DIRECTIONS: Record the single high the right (maximum value)			

No Known or Suspected Surface Water (Human Endpoint) MC Hazard

 \times

HHE Module: Sediment – Human Endpoint Data Element Table

Contaminant Hazard Factor (CHF)

FACTOR

DIRECTIONS: Record the **maximum concentrations** of all contaminants in the MRS's sediment and their **comparison** values (from Appendix B of the Primer) in the table below. Additional contaminants can be recorded on Table 27. Calculate and record the ratios for each contaminant by dividing the maximum concentration by the comparison value. Determine the CHF by adding the contaminant ratios together, including any additional sediment contaminants recorded on Table 27. Based on the CHF, use the CHF Scale to determine and record the CHF Value. If there is no known or suspected MC hazard with human endpoints present in the sediment, select the box at the bottom of the table.

Contaminant	Maximum Concentration (mg/kg)	Comparison Value (mg/kg)	Ratios	
CHF Scale	CHF Value	Sum The Ratios		
CHF > 100	H (High)	— Maximum Concentration of C	ontaminantl	
100 > CHF > 2	M (Medium)	CHF = [Maximum Concentration of C		
2 > CHF	L (Low)	[Comparison Value for Conta	aminant]	
CONTAMINANT HAZARD FACTOR	DIRECTIONS: Record the CHF Value maximum value = H).	from above in the box to the right		
DIRECTIONS: Circle the Classification	· ·	the sediment migratory pathway at the MR	S. Value	
	Description Analytical data or observable evidence indicates that contamination in the sediment is present at,		- value H	
Evident	moving toward, or has moved to a point of expos	moving toward, or has moved to a point of exposure.		
Potential	Contamination in sediment has moved only slightly beyond the source (i.e., tens of feet), could move but is not moving appreciably, or information is not sufficient to make a determination of Evident or Confined.			
Confined		Information indicates a low potential for contaminant migration from the source via the sediment to a potential point of exposure (possibly due to the presence of geological structures or physical controls).		
MIGRATORY PATHWAY FACTOR	DIRECTIONS: Record the single high right (maximum value =	nest value from above in the box to the H).		
DIRECTIONS: Circle to	Receptor Face value that corresponds most closely to	actor_		
Classification		cription	Value	
Identified	Identified receptors have access to sediment to v	which contamination has moved or can move.	Ι	
Potential	Potential for receptors to have access to sediment to which contamination has moved or can move.			
Limited	Little or no potential for receptors to have access to sediment to which contamination has moved or can move.			
RECEPTOR	DIRECTIONS: Record the single high			

the right (maximum value = H).

No Known or Suspected Sediment (Human Endpoint) MC Hazard

 \boxtimes

HHE Module: Surface Water - Ecological Endpoint Data Element Table

Contaminant Hazard Factor (CHF)

DIRECTIONS: Record the maximum concentrations of all contaminants in the MRS's surface water and their comparison values (from Appendix B of the Primer) in the table below. Additional contaminants can be recorded on Table 27. Calculate and record the ratios for each contaminant by dividing the maximum concentration by the comparison value. Determine the CHF by adding the contaminant ratios together, including any additional surface water contaminants recorded on Table 27. Based on the CHF, use the CHF Scale to determine and record the CHF Value. If there is no known or suspected MC hazard with ecological endpoints present in the surface water, select the box at the bottom of the table.

Contaminant	Maximum Concentration (μg/L)	Comparison Value (μg/L)	Ratios	
CHF Scale	CHF Value	Sum the Ratios		
CHF > 100	H (High)	CHF = [Maximum Concentration of Co	ontaminantl	
100 > CHF > 2	M (Medium)	[Comparison Value for Conta	minantl	
2 > CHF	L (Low)		ırıırıarııj	
CONTAMINANT HAZARD FACTOR	DIRECTIONS: Record the CHF Value (maximum value = H).	from above in the box to the right		
		the surface water migratory pathway at the		
Classification		cription that contamination in the surface water is present at,	Value	
Evident	moving toward, or has moved to a point of expos		Н	
Potential	Contamination in surface water has moved only slightly beyond the source (i.e., tens of feet), could move but is not moving appreciably, or information is not sufficient to make a determination of Evident or Confined.			
Confined	Information indicates a low potential for contamir to a potential point of exposure (possibly due to t controls).	nant migration from the source via the surface water he presence of geological structures or physical	L	
MIGRATORY PATHWAY FACTOR	DIRECTIONS: Record the single high right (maximum value =	nest value from above in the box to the = H).		
DIRECTIONS: Circle to	Receptor Face value that corresponds most closely to	actor the surface water receptors at the MRS.		
Classification	Des	cription	Value	
Identified	Identified receptors have access to surface water	r to which contamination has moved or can move.	Н	
Potential	Potential for receptors to have access to surface water to which contamination has moved or can move.		М	
Limited	Little or no potential for receptors to have access to surface water to which contamination has moved or can move.			
RECEPTOR FACTOR	DIRECTIONS: Record the single high right (maximum value =	nest value from above in the box to the = H).		
	No Known or Suspected Surface	ce Water (Ecological Endpoint) MC Hazard	X	

HHE Module: Sediment - Ecological Endpoint Data Element Table

Contaminant Hazard Factor (CHF)

DIRECTIONS: Record the maximum concentrations of all contaminants in the MRS's sediment and their comparison values (from Appendix B of the Primer) in the table below. Additional contaminants can be recorded on Table 27. Calculate and record the ratios for each contaminant by dividing the maximum concentration by the comparison value. Determine the CHF by adding the contaminant ratios together, including any additional sediment contaminants recorded on Table 27. Based on the CHF, use the CHF Scale to determine and record the CHF Value. If there is no known or suspected MC hazard with ecological endpoints present in the sediment, select the box at the bottom of the table.

Contaminant	Maximum Concentration (mg/kg)	Comparison Value (mg/kg)	Ratios		
CHF Scale	CHF Value	Sum the Ratios			
CHF > 100	H (High)	[Maximum Concentration of Co	ntominant]		
100 > CHF > 2	M (Medium)	CHF = [Maximum Concentration of Co	mammanıj		
2 > CHF	L (Low)	[Comparison Value for Conta	minant]		
CONTAMINANT HAZARD FACTOR	DIRECTIONS: Record the CHF Value (maximum value = H).				
DIDECTIONS: Circle t	Migratory Path	way Factor to the sediment migratory pathway at the MRS	2		
	ne value that corresponds most closely	to the sediment migratory patriway at the wirk	J.		
Classification		scription	Value		
Evident	Analytical data or observable evidence indicates that contamination in the sediment is present at, moving toward, or has moved to a point of exposure.				
Potential	Contamination in sediment has moved only slightly beyond the source (i.e., tens of feet), could move but is not moving appreciably, or information is not sufficient to make a determination of Evident or Confined.				
Confined		inant migration from the source via the sediment to a presence of geological structures or physical controls).	L		
MIGRATORY PATHWAY FACTOR	DIRECTIONS: Record the single highest value from above in the box to the right (maximum value = H).				
DIRECTIONS: Circle to	Receptor he value that corresponds most closely				
Classification		scription	Value		
Identified	Identified receptors have access to sediment to which contamination has moved or can move.				
Potential	Potential for receptors to have access to sediment to which contamination has moved or can move.				
Limited	Little or no potential for receptors to have access to sediment to which contamination has moved or can move.				
RECEPTOR FACTOR	DIRECTIONS: Record the single highest value from above in the box to the right (maximum value = H).				

No Known or Suspected Sediment (Ecological Endpoint) MC Hazard

 \times

HHE Module: Surface Soil Data Element Table

Contaminant Hazard Factor (CHF)

DIRECTIONS: Record the maximum concentrations of all contaminants in the MRS's surface soil and their comparison values (from Appendix B of the Primer) in the table below. Additional contaminants can be recorded on Table 27. Calculate and record the ratios for each contaminant by dividing the maximum concentration by the comparison value. Determine the CHF by adding the contaminant ratios together, including any additional surface soil contaminants recorded on Table 27. Based on the CHF, use the CHF Scale to determine and record the CHF Value. If there is no known or suspected MC hazard present in the surface soil, select the box at the bottom of the table.

	process in the current configuration of	ox at the bottom of the table.			
Contaminant	Maximum Concentration (mg/kg)	Comparison Value (mg/kg)	Ratio		
CHF Scale	CHF Value	Sum the Ratios			
CHF > 100	H (High)	CHF = [Maximum Concentration of Con	ntaminantl		
100 > CHF > 2	M (Medium)	CHF = \(\sum_{[National Control of Co	-'		
2 > CHF	L (Low)	[Comparison Value for Contam	ninantj		
CONTAMINANT HAZARD FACTOR	DIRECTIONS: Record the CHF Value (maximum value = H	ue from above in the box to the right).			
Migratory Pathway Factor DIRECTIONS: Circle the value that corresponds most closely to the surface soil migratory pathway at the MR					
Classification	De	escription	Value		
Evident	moving toward, or has moved to a point of exp	Analytical data or observable evidence indicates that contamination in the surface soil is present at, moving toward, or has moved to a point of exposure.			
Potential	Contamination in surface soil has moved only slightly beyond the source (i.e., tens of feet), could move but is not moving appreciably, or information is not sufficient to make a determination of Evident or Confined.				
Confined		ninant migration from the source via the surface soil to he presence of geological structures or physical	L		
MIGRATORY PATHWAY FACTOR	DIRECTIONS: Record the single hi right (maximum value	ghest value from above in the box to the e = H).			
DIRECTIONS: Circle 4	Receptor				
	·	to the surface soil receptors at the MRS.			
Classification		escription	Value		
Identified	identified receptors have access to surface so	il to which contamination has moved or can move.	Н		
Potential	Potential for receptors to have access to surface soil to which contamination has moved or can move.		М		
Limited	Little or no potential for receptors to have access to surface soil to which contamination has moved or can move.		L		
RECEPTOR FACTOR	DIRECTIONS: Record the single hi right (maximum value	ghest value from above in the box to the e = H).			
	No K	Cnown or Suspected Surface Soil MC Hazard			

HHE Module: Supplemental Contaminant Hazard Factor Table

Contaminant Hazard Factor (CHF)

DIRECTIONS: Only use this table if there are more than five contaminants in any given medium present at the

MRS. This is a supplemental table designed to hold information about contaminants that do not fit in the previous tables. Indicate the **media** in which these contaminants are present. Then record all **contaminants**, their **maximum concentrations** and their **comparison values** (from Appendix B of the Primer) in the table below. Calculate and record the **ratio** for each contaminant by dividing the **maximum concentration** by the **comparison value**. Determine the **CHF** for each medium on the appropriate media-specific tables.

Note: Do not add ratios from different media.

Media	Contaminant	Maximum Concentration	Comparison Value	Ratio

Table 28 Determining the HHE Module Rating

DIRECTIONS:

- 1. Record the letter values (H, M, L) for the **Contaminant Hazard**, **Migration Pathway**, and **Receptor Factors** for the media (from Tables 21–26) in the corresponding boxes below.
- 2. Record the media's three-letter combinations in the **Three-Letter Combination** boxes below (three-letter combinations are arranged from Hs to Ms to Ls).
- 3. Using the **HHE Ratings** provided below, determine each media's rating (A–G) and record the letter in the corresponding **Media Rating** box below.

Media (Source)	Contaminant Hazard Factor Value	Migratory Pathway Factor Value	Receptor Factor Value	Three-Letter Combination (Hs-Ms-Ls)	Media Rating (A-G)
Groundwater (Table 21)					
Surface Water/Human Endpoint (Table 22)					
Sediment/Human Endpoint (Table 23)					
Surface Water/Ecological Endpoint (Table 24)					
Sediment/Ecological Endpoint (Table 25)					
Surface Soil (Table 26)					

DIRECTIONS (cont.):

4. Select the single highest Media Rating (A is highest; G is lowest) and enter the letter in the **HHE Module Rating** box.

Note:

An alternative module rating may be assigned when a module letter rating is inappropriate. An alternative module rating is used when more information is needed to score one or more media, contamination at an MRS was previously addressed, or there is no reason to suspect contamination was ever present at an MRS.

HHE MODULE RATING

HHE Ratings (for reference only)					
Combination	Rating				
ННН	Α				
ННМ	В				
HHL					
НММ	С				
HML	1				
MMM	D				
HLL	_				
MML	E				
MLL	F				
LLL	G				
	Evaluation Pending				
Alternative Module Ratings	No Longer Required				
(()	No Known or Suspected MC Hazard				

Table 29 **MRS Priority**

DIRECTIONS: In the chart below, circle the letter rating for each module recorded in Table 10 (EHE), Table 20 (CHE), and Table 28 (HHE). Circle the corresponding numerical priority for each module. If information to determine the module rating is not available, choose the appropriate alternative module rating. The MRS Priority is the single highest priority; record this relative priority in the MRS Priority or Alternative MRS Rating at the bottom of the table.

Note: An MRS assigned Priority 1 has the highest relative priority; an MRS assigned Priority 8 has the lowest relative priority. Only an MRS with CWM known or suspected to be present can be assigned Priority 1; an MRS that has CWM known or suspected to be present cannot be assigned Priority 8.

EHE Rating	Priority	CHE Rating	Priority	HHE Rating	Priority
		Α	1		
Α	2	В	2	Α	2
В	3	С	3	В	3
С	4	D	4	С	4
D	5	E	5	D	5
E	6	F	6	E	6
F	7	G	7	F	7
G	8			G	8
Evaluation	Pending	Evaluation Pending		Evaluation Pending	
No Longer Required		No Longer Required		No Longe	r Required
No Known or Suspected Explosive Hazard No Known or Suspected CWM Hazard			No Known or Susp	pected MC Hazard	
MRS PRIORITY or ALTERNATIVE MRS RATING				3	3

Table A

MRS Background Information

DIRECTIONS: Record the background information below for the MRS to be evaluated. Much of this information is available from Service and DoD databases. If the MRS is located on a FUDS property, the suitable FUDS property information should be substituted. In the MRS Summary, briefly describe the UXO, DMM, or MC that are known or suspected to be present, the exposure setting (the MRS's physical environment), any other incidental nonmunitions-related contaminants (e.g., benzene, trichloroethylene) found at the MRS, and any potentially exposed human and ecological receptors. If possible, include a map of the MRS.

Munit	Munitions Response Site Name: <u>JAAP-001-R-02, L2-L3 Extended Buffer Area</u>						
Comp	ponent: Active Army	1					
Instal	Ilation/Property Na	me: Joliet Army Amm	<u>านnition Plan</u>	<u>t</u>			
Locat	tion (City, County,	State): Wilmington, W	Vill County, II	llinois			
Point	of Contact/Phone	No.: Art Holz; 815-42	<u>23-2870</u>				
Site N	Name/Project Name	e (Project No.): JAAP	'-001-R-02_				
MRSP	PP Score (Date Sco	ored): 14 August 2009	9				
Prepa	arer's Name (Organ	nization): Catherine K	Celly (Malcolr	m Pirnie)			
MRSP	PP Rating: 3						
within Point Project	Date Information Entered/Updated: May 2009; Information contained within this scoring was obtained from sources within the Joliet AAP Administrative Record. Point of Contact (Name/Phone): JOAAP Commander's Representative Art Holz (815) 423-2870 Project Phase (check only one): □ PA ✓ SI □ RI □ FS □ RD □ RA-C □ RIP □ RA-O □ RC □ LTM						
Media Evaluated (check all that apply): Groundwater Sediment (human receptor) Surface soil Surface Water (ecological receptor) Surface Water (human receptor)							

MRS Summary:

MRS Description: Describe the munitions-related activities that occurred at the installation, the dates of operation, and the UXO, DMM, or MC known or suspected to be present. When possible, identify munitions, CWM, and MC by type:

Ammunition manufacturing, load, assemble, and packaging occurred between 1941 and 1977. The plant made many types of munitions, including ICM and up to 8-inch Howitzer HE projectiles. At L2, the Explosives Burning Ground 1, open burning and detonation occurred on three gravel pads and a popping furnace. Waste

Table A

MRS Background Information

DIRECTIONS: Record the background information below for the MRS to be evaluated. Much of this information is available from Service and DoD databases. If the MRS is located on a FUDS property, the suitable FUDS property information should be substituted. In the MRS Summary, briefly describe the UXO, DMM, or MC that are known or suspected to be present, the exposure setting (the MRS's physical environment), any other incidental nonmunitions-related contaminants (e.g., benzene, trichloroethylene) found at the MRS, and any potentially exposed human and ecological receptors. If possible, include a map of the MRS.

oil was burned in three pits. L3, the Demolition Area, was used for burning, demolition, and a fire training area. This MRS was in the kick-out area for both L2 and L3 (HRR Addendum—Section 2).

Description of Pathways for Human and Ecological Receptors:

Potentially complete pathways exist for all human and ecological receptors (SI Addendum – Section 4.1.4.6).

Description of Receptors (Human and Ecological):

Human access to the site is limited. The only threatened or endangered species potentially inhabiting the L2-L3 Extended Buffer Area are grassland birds including bobolinks, upland sandpipers, and Henslow's sparrows (SI Addendum—Section 4.1.4.4.3).

EHE Module: Munitions Type Data Element Table

DIRECTIONS: Below are 11 classifications of munitions and their descriptions. Circle the scores that correspond with <u>all</u> the munitions types known or suspected to be present at the MRS.

Note: The terms *practice munitions, small arms ammunition, physical evidence,* and *historical evidence* are defined in Appendix C of the Primer.

Classification	Description	Score
Sensitive	 UXO that are considered most likely to function upon any interaction with exposed persons (e.g., submunitions, 40mm high-explosive [HE] grenades, white phosphorus [WP] munitions, high-explosive antitank [HEAT] munitions, and practice munitions with sensitive fuzes, but excluding all other practice munitions). Hand grenades containing energetic filler. Bulk primary explosives, or mixtures of these with environmental media, such that the mixture poses an explosive hazard. 	30
High explosive (used or damaged)	 UXO containing a high-explosive filler (e.g., RDX, Composition B), that are not considered "sensitive." DMM containing a high-explosive filler that have: Been damaged by burning or detonation Deteriorated to the point of instability. 	25
Pyrotechnic (used or damaged)	 UXO containing a pyrotechnic filler other than white phosphorus (e.g., flares, signals, simulators, smoke grenades). DMM containing a pyrotechnic filler other than white phosphorus (e.g., flares, signals, simulators, smoke grenades) that have: Been damaged by burning or detonation Deteriorated to the point of instability. 	20
High explosive (unused)	DMM containing a high-explosive filler that:	15
Propellant	 UXO containing mostly single-, double-, or triple-based propellant, or composite propellants (e.g., a rocket motor). DMM containing mostly single-, double-, or triple-based propellant, or composite propellants (e.g., a rocket motor) that are: Damaged by burning or detonation Deteriorated to the point of instability. 	15
Bulk secondary high explosives, pyrotechnics, or propellant	 DMM containing mostly single-, double-, or triple-based propellant, or composite propellants (e.g., a rocket motor). DMM that are bulk secondary high explosives, pyrotechnic compositions, or propellant (not contained in a munition), or mixtures of these with environmental media such that the mixture poses an explosive hazard. 	10
Pyrotechnic (not used or damaged)	 DMM containing a pyrotechnic filler (i.e., red phosphorus), other than white phosphorus filler, that: Have not been damaged by burning or detonation Are not deteriorated to the point of instability. 	10
Practice	 UXO that are practice munitions that are not associated with a sensitive fuze. DMM that are practice munitions that are not associated with a sensitive fuze and that have not: Been damaged by burning or detonation Deteriorated to the point of instability. 	5
Riot control	UXO or DMM containing a riot control agent filler (e.g., tear gas).	3
Small arms	 Used munitions or DMM that are categorized as small arms ammunition. (Physical evidence or historical evidence that no other types of munitions [e.g., grenades, subcaliber training rockets, demolition charges] were used or are present on the MRS is required for selection of this category.) 	2
Evidence of no munitions	Following investigation of the MRS, there is physical evidence that there are no UXO or DMM present, or there is historical evidence indicating that no UXO or DMM are present.	0
MUNITIONS TYPE	DIRECTIONS: Record the single highest score from above in the box to the right (maximum score = 30).	25

EHE Module: Munitions Type Data Element Table

DIRECTIONS: Below are 11 classifications of munitions and their descriptions. Circle the scores that correspond with all

the munitions types known or suspected to be present at the MRS.

Note: The terms practice munitions, small arms ammunition, physical evidence, and historical evidence are defined in

Appendix C of the Primer.

Classification Description Score

UXO and DMM located in the MRS are a direct result of operations conducted at the former JOAAP L3 OB/OD Area. The instrument-assisted visual survey conducted during the Site Inspection did not result in any UXO, sub-munitions, 40mm HE, white phosphorus munitions, high-explosive antitank munitions, practice munitions with sensitive fuzes or DMM on the surface; however munitions debris was located. Twenty-five was selected due to a USACE survey conducted in 2007, in which UXO and DMM containing high-explosive fillers that were not considered sensitive were located on the surface (SI Addendum—Section 4.1.4.5.3).

EHE Module: Source of Hazard Data Element Table

DIRECTIONS: Below are 11 classifications describing sources of explosive hazards. Circle the scores that correspond with <u>all</u> the sources of explosive hazards known or suspected to be present at the MRS.

Note: The terms former range, practice munitions, small arms range, physical evidence, and historical evidence are defined in Appendix C of the Primer.

Classification	Description	Score
Former range	 The MRS is a former military range where munitions (including practice munitions with sensitive fuzes) have been used. Such areas include impact or target areas and associated buffer and safety zones. 	10
Former munitions treatment (i.e., OB/OD) unit	 The MRS is a location where UXO or DMM (e.g., munitions, bulk explosives, bulk pyrotechnic, or bulk propellants) were burned or detonated for the purpose of treatment prior to disposal. 	$\bigcirc \infty$
Former practice munitions range	The MRS is a former military range on which only practice munitions without sensitive fuzes were used.	6
Former maneuver area	 The MRS is a former maneuver area where no munitions other than flares, simulators, smokes, and blanks were used. There must be evidence that no other munitions were used at the location to place an MRS into this category. 	5
Former burial pit or other disposal area	The MRS is a location where DMM were buried or disposed of (e.g., disposed of into a water body) without prior thermal treatment.	5
Former industrial operating facilities	The MRS is a location that is a former munitions maintenance, manufacturing, or demilitarization facility.	4
Former firing points	The MRS is a firing point, where the firing point is delineated as an MRS separate from the rest of a former military range.	4
Former missile or air defense artillery emplacements	 The MRS is a former missile defense or air defense artillery (ADA) emplacement not associated with a military range. 	2
Former storage or transfer points	The MRS is a location where munitions were stored or handled for transfer between different modes of transportation (e.g., rail to truck, truck to weapon system).	2
Former small arms range	 The MRS is a former military range where only small arms ammunition was used. (There must be evidence that no other types of munitions [e.g., grenades] were used or are present to place an MRS into this category.) 	1
Evidence of no munitions	 Following investigation of the MRS, there is physical evidence that no UXO or DMM are present, or there is historical evidence indicating that no UXO or DMM are present. 	0
SOURCE OF HAZARD	DIRECTIONS: Record <u>the single highest score</u> from above in the box to the right (maximum score = 10).	8

DIRECTIONS: Document any MRS-specific data used in selecting the **Source of Hazard** classifications in the space provided.

Historical records indicate this site is in the kick-out boundary of an area used for demolition of UXO and DMM (HRR Addendum—4.1.1.2).

EHE Module: Location of Munitions Data Element Table

DIRECTIONS: Below are eight classifications of munitions locations and their descriptions. Circle the scores that correspond with all the locations where munitions are known or suspected to be present at the MRS.

Note: The terms confirmed, surface, subsurface, small arms ammunition, physical evidence, and historical evidence are

defined in Appendix C of the Primer.

Classification	Description	Score
Confirmed surface	 Physical evidence indicates that there are UXO or DMM on the surface of the MRS. Historical evidence (i.e., a confirmed report such as an explosive ordnance disposal [EOD], police, or fire department report that an incident or accident that involved UXO or DMM occurred) indicates there are UXO or DMM on the surface of the MRS. 	25
Confirmed subsurface, active	 Physical evidence indicates the presence of UXO or DMM in the subsurface of the MRS, and the geological conditions at the MRS are likely to cause UXO or DMM to be exposed, in the future, by naturally occurring phenomena (e.g., drought, flooding, erosion, frost heave, tidal action), or intrusive activities (e.g., plowing, construction, dredging) at the MRS are likely to expose UXO or DMM. Historical evidence indicates that UXO or DMM are located in the subsurface of the MRS and the geological conditions at the MRS are likely to cause UXO or DMM to be exposed, in the future, by naturally occurring phenomena (e.g., drought, flooding, erosion, frost heave, tidal action), or intrusive activities (e.g., plowing, construction, dredging) at the MRS are likely to expose UXO or DMM. 	20
Confirmed subsurface, stable	 Physical evidence indicates the presence of UXO or DMM in the subsurface of the MRS and the geological conditions at the MRS are not likely to cause UXO or DMM to be exposed, in the future, by naturally occurring phenomena, or intrusive activities at the MRS are not likely to cause UXO or DMM to be exposed. Historical evidence indicates that UXO or DMM are located in the subsurface of the MRS and the geological conditions at the MRS are not likely to cause UXO or DMM to be exposed, in the future, by naturally occurring phenomena, or intrusive activities at the MRS are not likely to cause UXO or DMM to be exposed. 	15
Suspected (physical evidence)	 There is physical evidence (e.g., munitions debris such as fragments, penetrators, projectiles, shell casings, links, fins), other than the documented presence of UXO or DMM, indicating that UXO or DMM may be present at the MRS. 	10
Suspected (historical evidence)	There is historical evidence indicating that UXO or DMM may be present at the MRS.	5
Subsurface, physical constraint	There is physical or historical evidence indicating that UXO or DMM may be present in the subsurface, but there is a physical constraint (e.g., pavement, water depth over 120 feet) preventing direct access to the UXO or DMM.	2
Small arms (regardless of location)	 The presence of small arms ammunition is confirmed or suspected, regardless of other factors such as geological stability. (There must be evidence that no other types of munitions [e.g., grenades] were used or are present at the MRS to place an MRS into this category.) 	1
Evidence of no munitions	Following investigation of the MRS, there is physical evidence that there are no UXO or DMM present, or there is historical evidence indicating that no UXO or DMM are present.	0
LOCATION OF MUNITIONS	DIRECTIONS: Record <u>the single highest score</u> from above in the box to the right (maximum score = 25).	25

DIRECTIONS: Document any MRS-specific data used in selecting the *Location of Munitions* classifications in the space provided.

The instrument-assisted visual survey conducted during the Site Inspection did not result in any UXO or DMM on the surface; however munitions debris was located. Twenty-five was selected due to a USACE survey conducted in 2007 in which MEC items were located on the surface (SI Addendum—Section 4.1.4.5.3).

EHE Module: Ease of Access Data Element Table

DIRECTIONS: Below are four classifications of barrier types that can surround an MRS and their descriptions. The

barrier type is directly related to the ease of public access to the MRS. Circle the score that corresponds

with the ease of access to the MRS.

Note: The term barrier is defined in Appendix C of the Primer.

Classification	Description	Score
No barrier	 There is no barrier preventing access to any part of the MRS (i.e., all parts of the MRS are accessible). 	
Barrier to MRS access is incomplete	There is a barrier preventing access to parts of the MRS, but not the entire MRS.	8
Barrier to MRS access is complete but not monitored	There is a barrier preventing access to all parts of the MRS, but there is no surveillance (e.g., by a guard) to ensure that the barrier is effectively preventing access to all parts of the MRS.	5
Barrier to MRS access is complete and monitored	There is a barrier preventing access to all parts of the MRS, and there is active, continual surveillance (e.g., by a guard, video monitoring) to ensure that the barrier is effectively preventing access to all parts of the MRS.	0
EASE OF ACCESS	DIRECTIONS: Record the single highest score from above in the box to the right (maximum score = 10).	5

DIRECTIONS: Document any MRS-specific data used in selecting the *Ease of Access* classification in the space provided.

The public has no access to this site; the site is surrounded by a fence with a locked gate, and only two keys exist for the lock. All visitors must be accompanied by facility personnel; however, the area is not monitored to prevent trespassers from gaining access (SI Addendum—Section 4.1.4.1.5).

Table 5EHE Module: Status of Property Data Element Table

DIRECTIONS: Below are three classifications of the status of a property within the Department of Defense (DoD) and their descriptions. Circle the score that corresponds with the status of property at the MRS.

Classification	Description	Score
Non-DoD control	 The MRS is at a location that is no longer owned by, leased to, or otherwise possessed or used by DoD. Examples are privately owned land or water bodies; land or water bodies owned or controlled by state, tribal, or local governments; and land or water bodies managed by other federal agencies. The MRS is at a location that is owned by DoD, but that DoD has leased to another entity and for which DoD does not control access 24 hours per day. 	5
Scheduled for transfer from DoD control	The MRS is on land or is a water body that is owned, leased, or otherwise possessed by DoD, and DoD plans to transfer that land or water body to the control of another entity (e.g., a state, tribal, or local government; a private party; another federal agency) within 3 years from the date the Protocol is applied.	3
DoD control	 The MRS is on land or is a water body that is owned, leased, or otherwise possessed by DoD. With respect to property that is leased or otherwise possessed, DoD must control access to the MRS 24 hours per day, every day of the calendar year. 	0
STATUS OF PROPERTY	DIRECTIONS: Record the single highest score from above in the box to the right (maximum score = 5).	5

DIRECTIONS: Document any MRS-specific data used in selecting the **Status of Property** classification in the space provided.

The MRS is at a location that has been transferred to the United States Department of Agriculture (SI Addendum—Section 4.1.1).

EHE Module: Population Density Data Element Table

DIRECTIONS: Below are three classifications for population density and their descriptions. Determine the population density per square mile that most closely corresponds with the population of the MRS, including the area within a two-mile radius of the MRS's perimeter. Circle the most appropriate score.

Note: Use the U.S. Census Bureau tract data available to capture the <u>highest</u> population density within a two-mile radius of the perimeter of the MRS.

Classification	Description	Score
> 500 persons per square mile	There are more than 500 persons per square mile in the U.S. Census Bureau tract in which the MRS is located.	5
100–500 persons per square mile	 There are 100 to 500 persons per square mile in the U.S. Census Bureau tract in which the MRS is located. 	3
< 100 persons per square mile	 There are fewer than 100 persons per square mile in the U.S. Census Bureau tract in which the MRS is located. 	1
POPULATION DENSITY	DIRECTIONS: Record the single highest score from above in the box to the right (maximum score = 5).	3

DIRECTIONS: Document any MRS-specific data used in selecting the *Population Density* classification in the space provided.

U.S. Census Bureau 2000 data, Will County = 296-600 persons per square mile. The maximum data class of persons per square mile in the town of Wilmington, which is the closest town to the site is 367.

EHE Module: Population Near Hazard Data Element Table

DIRECTIONS: Below are six classifications describing the number of inhabited structures near the MRS. The number of inhabited buildings relates to the potential population near the MRS. Determine the number of inhabited structures within two miles of the MRS boundary and circle the score that corresponds with the number of inhabited structures.

Note: The term *inhabited structures* is defined in Appendix C of the Primer.

Classification	Description	Score
26 or more inhabited structures	There are 26 or more inhabited structures located up to 2 miles from the boundary of the MRS, within the boundary of the MRS, or both.	5
16 to 25 inhabited structures	 There are 16 to 25 inhabited structures located up to 2 miles from the boundary of the MRS, within the boundary of the MRS, or both. 	4
11 to 15 inhabited structures	There are 11 to 15 inhabited structures located up to 2 miles from the boundary of the MRS, within the boundary of the MRS, or both.	3
6 to 10 inhabited structures	There are 6 to 10 inhabited structures located up to 2 miles from the boundary of the MRS, within the boundary of the MRS, or both.	2
1 to 5 inhabited structures	There are 1 to 5 inhabited structures located up to 2 miles from the boundary of the MRS, within the boundary of the MRS, or both.	1
0 inhabited structures	There are no inhabited structures located up to 2 miles from the boundary of the MRS, within the boundary of the MRS, or both.	0
POPULATION NEAR HAZARD	DIRECTIONS: Record <u>the single highest score</u> from above in the box to the right (maximum score = 5).	5

DIRECTIONS: Document any MRS-specific data used in selecting the *Population Near Hazard* classification in the space provided.

Homes, offices, a feed mill, and agricultural lands are located within 2 miles of this site. Recent development has increased the number of inhabited structures located up to 2 miles from the boundary of the MRS (HRR Addendum—Section 5.3.2).

EHE Module: Types of Activities/Structures Data Element Table

DIRECTIONS: Below are five classifications of activities and/or inhabited structures and their descriptions. Review the

types of activities that occur and/or structures that are present within two miles of the MRS and circle the

scores that correspond with all the activities/structure classifications at the MRS.

Note: The term *inhabited structure* is defined in Appendix C of the Primer.

Classification	Description	Score
Residential, educational, commercial, or subsistence	 Activities are conducted, or inhabited structures are located up to two miles from the MRS's boundary or within the MRS's boundary, that are associated with any of the following purposes: residential, educational, child care, critical assets (e.g., hospitals, fire and rescue, police stations, dams), hotels, commercial, shopping centers, playgrounds, community gathering areas, religious sites, or sites used for subsistence hunting, fishing, and gathering. 	5
Parks and recreational areas	Activities are conducted, or inhabited structures are located up to two miles from the MRS's boundary or within the MRS's boundary, that are associated with parks, nature preserves, or other recreational uses.	4
Agricultural, forestry	Activities are conducted, or inhabited structures are located up to two miles from the MRS's boundary or within the MRS's boundary, that are associated with agriculture or forestry.	3
Industrial or warehousing	Activities are conducted, or inhabited structures are located up to two miles from the MRS's boundary or within the MRS's boundary, that are associated with industrial activities or warehousing.	2
No known or recurring activities	There are no known or recurring activities occurring up to two miles from the MRS's boundary or within the MRS's boundary.	1
TYPES OF ACTIVITIES/STRUCTURES	DIRECTIONS: Record <u>the single highest score</u> from above in the box to the right (maximum score = 5).	5

DIRECTIONS: Document any MRS-specific data used in selecting the *Types of Activities/Structures* classifications in the space provided.

Homes, offices, a feed mill, and agricultural lands are located within 2 miles of this site. The planned future use for this site is open space for the USDA Midewin National Tallgrass Prairie which is also presently located within 2 miles of the site. Recent development has increased the number of residences located within 2 miles of the MRS (HRR Addendum—Section 5.3.2).

EHE Module: Ecological and/or Cultural Resources Data Element Table

DIRECTIONS: Below are four classifications of ecological and/or cultural resources and their descriptions. Review the

types of resources present and circle the score that corresponds with the ecological and/or cultural

resources present on the MRS.

Note: The terms ecological resources and cultural resources are defined in Appendix C of the Primer.

Classification	Description	Score
Ecological and cultural resources present	There are both ecological and cultural resources present on the MRS.	5
Ecological resources present	There are ecological resources present on the MRS.	3
Cultural resources present	There are cultural resources present on the MRS.	3
No ecological or cultural resources present	There are no ecological resources or cultural resources present on the MRS.	0
ECOLOGICAL AND/OR CULTURAL RESOURCES	DIRECTIONS: Record the single highest score from above in the box to the right (maximum score = 5).	5

DIRECTIONS: Document any MRS-specific data used in selecting the *Ecological and/or Cultural Resources* classification in the space provided.

An ecologist at Midewin National Tallgrass Prairie confirmed that grassland birds are the only threatened and endangered species at JOAAP. These birds include bobolinks, upland sandpipers, and Henslow's sparrows (SI Addendum—Section 4.1.4.4.3). An old cemetery is also located on the site (HRR Addendum—Section 2.1).

Table 10 Determining the EHE Module Rating

DIRECTIONS:

- 1. From Tables 1–9, record the data element scores in the **Score** boxes to the right.
- Add the **Score** boxes for each of the three factors and record this number in the **Value** boxes to the right.
- Add the three Value boxes and record this number in the EHE Module Total box below.
- 4. Circle the appropriate range for the **EHE Module Total** below.
- 5. Circle the **EHE Module Rating** that corresponds to the range selected and record this value in the **EHE Module Rating** box found at the bottom of the table.

Note:

An alternative module rating may be assigned when a module letter rating is inappropriate. An alternative module rating is used when more information is needed to score one or more data elements, contamination at an MRS was previously addressed, or there is no reason to suspect contamination was ever present at an MRS.

	Source	Score	Value	
Explosive Hazard Factor Data Elements				
Munitions Type	Table 1	25	33	
Source of Hazard	Table 2	8	, ,	
Accessibility Factor Data Elemen	nts			
Location of Munitions	Table 3	25		
Ease of Access	Table 4	5	35	
Status of Property	Table 5	5		
Receptor Factor Data Elements				
Population Density	Table 6	3		
Population Near Hazard	Table 7	5	40	
Types of Activities/Structures	Table 8	5	18	
Ecological and/or Cultural Resources	Table 9	5		
EHE MODULE TOTAL 8			86	
EHE Module Total	EHE Module Rating		ating	
92 to 100		Α		
82 to 91		В		
71 to 81		С		
60 to 70		D		
48 to 59	E			
38 to 47	F			
less than 38	G			
	Evaluation Pending		ding	
Alternative Module Ratings	No Longer Required			
	No Known or Suspected Explosive Hazard			
EHE MODULE RATING	EHE MODULE RATING B			

CHE Module: CWM Configuration Data Element Table

DIRECTIONS: Below are seven classifications of CWM configuration and their descriptions. Circle the scores that

correspond with <u>all</u> the CWM configurations known or suspected to be present at the MRS.

Note: The terms CWM/UXO, CWM/DMM, physical evidence, and historical evidence are defined in Appendix C of the

Primer.

Classification	Description	Score
CWM, that are either UXO, or explosively configured damaged DMM	 The CWM known or suspected of being present at the MRS are: CWM that are UXO (i.e., CWM/UXO) Explosively configured CWM that are DMM (i.e., CWM/DMM) that have been damaged. 	30
CWM mixed with UXO	The CWM known or suspected of being present at the MRS are undamaged CWM/DMM or CWM not configured as a munition that are commingled with conventional munitions that are UXO.	25
CWM, explosive configuration that are undamaged DMM	The CWM known or suspected of being present at the MRS are explosively configured CWM/DMM that have not been damaged.	20
CWM/DMM, not explosively configured or CWM, bulk container	 The CWM known or suspected of being present at the MRS are: Nonexplosively configured CWM/DMM either damaged or undamaged Bulk CWM (e.g., ton container). 	15
CAIS K941 and CAIS K942	The CWM/DMM known or suspected of being present at the MRS are CAIS K941-toxic gas set M-1 or CAIS K942-toxic gas set M-2/E11.	12
CAIS (chemical agent identification sets)	CAIS, other than CAIS K941 and K942, are known or suspected of being present at the MRS.	10
Evidence of no CWM	Following investigation, the physical evidence indicates that CWM are not present at the MRS, or the historical evidence indicates that CWM are not present at the MRS.	0
CWM CONFIGURATION	DIRECTIONS: Record <u>the single highest score</u> from above in the box to the right (maximum score = 30).	0

DIRECTIONS: Document any MRS-specific data used in selecting the *CWM Configuration* classifications in the space provided.

No CWM was handled at JOAAP (HRR Addendum—Section 4.1.1.2).

Tables 12 - 19

CHE Module: Sources of CWM Data Element Table

DIRECTIONS: Below are 11 sources of CWM hazards and their descriptions. Review these classifications and circle

the scores that correspond with all the sources of CWM hazards known or suspected to be present at

the MRS.

Note: The terms CWM/UXO, CWM/DMM, CAIS/DMM, surface, subsurface, physical evidence, and historical evidence

are defined in Appendix C of the Primer.

Description	Score
	Description

No known or suspected CWM hazard is expected at this site. Therefore, Tables 12 through 19 have been intentionally omitted according to Active Army Guidance.

Table 20 Determining the CHE Module Rating

DIRECTIONS:

- 1. From Tables 11–19, record the data element scores in the **Score** boxes to the right.
- Add the **Score** boxes for each of the three factors and record this number in the **Value** boxes to the right.
- Add the three Value boxes and record this number in the CHE Module Total box below.
- 4. Circle the appropriate range for the **CHE Module Total** below.
- 5. Circle the **CHE Module Rating** that corresponds to the range selected and record this value in the **CHE Module Rating** box found at the bottom of the table.

Note:

An alternative module rating may be assigned when a module letter rating is inappropriate. An alternative module rating is used when more information is needed to score one or more data elements, contamination at an MRS was previously addressed, or there is no reason to suspect contamination was ever present at an MRS.

	Source	Score	Value	
CWM Hazard Factor Data Elemen	nts			
CWM Configuration	Table 11	0	0	
Sources of CWM	Table 12	-	0	
Accessibility Factor Data Elemen	nts			
Location of CWM	Table 13			
Ease of Access	Table 14			
Status of Property	Table 15			
Receptor Factor Data Elements				
Population Density	Table 16			
Population Near Hazard	Table 17			
Types of Activities/Structures	Table 18			
Ecological and/or Cultural Resources	Table 19			
CHE	MODULE	TOTAL	0	
CHE Module Total	CHE Module Total CHE Module Rati		ating	
92 to 100		Α		
82 to 91		В		
71 to 81		С		
60 to 70		D		
48 to 59		E		
38 to 47	F			
less than 38	G			
	Evaluation Pending			
Alternative Module Ratings	No Longer Required			
	No Known or Suspected CWM Hazard			
CHE MODULE RATING	NO KNOWN OR SUSPECTED CWM HAZARD			

Tables 21 – 27

No environmental media (groundwater, surface water, sediment, or surface soil) samples were collected or analyzed under this SI Addendum effort, as agreed upon by stakeholders and regulators during Technical Project Planning Meeting 2. As a result the HHE Module has not been evaluated. Tables 21 – 27 have therefore been intentionally omitted per active-Army guidance, and the HHE score will remain "Evaluation Pending" until analytical data becomes available.

Table 28 Determining the HHE Module Rating

DIRECTIONS:

- 1. Record the letter values (H, M, L) for the **Contaminant Hazard**, **Migration Pathway**, and **Receptor Factors** for the media (from Tables 21–26) in the corresponding boxes below.
- 2. Record the media's three-letter combinations in the **Three-Letter Combination** boxes below (three-letter combinations are arranged from Hs to Ms to Ls).
- 3. Using the **HHE Ratings** provided below, determine each media's rating (A–G) and record the letter in the corresponding **Media Rating** box below.

Media (Source)	Contaminant Hazard Factor Value	Migratory Pathway Factor Value	Receptor Factor Value	Three-Letter Combination (Hs-Ms-Ls)	Media Rating (A-G)
Groundwater (Table 21)					
Surface Water/Human Endpoint (Table 22)					
Sediment/Human Endpoint (Table 23)					
Surface Water/Ecological Endpoint (Table 24)					
Sediment/Ecological Endpoint (Table 25)					
Surface Soil (Table 26)					

DIRECTIONS (cont.):

4. Select the single highest Media Rating (A is highest; G is lowest) and enter the letter in the **HHE Module Rating** box.

Note:

An alternative module rating may be assigned when a module letter rating is inappropriate. An alternative module rating is used when more information is needed to score one or more media, contamination at an MRS was previously addressed, or there is no reason to suspect contamination was ever present at an MRS.

HHE MODULE RATING

HHE Ratings (for reference only)			
Combination	Rating		
ННН	Α		
ННМ	В		
HHL			
НММ	С		
HML			
MMM	D		
HLL	E		
MML			
MLL	F		
LLL	G		
	Evaluation Pending		
Alternative Module Ratings	No Longer Required		
3 · · · · · · · · · · · · · · · · · · ·	No Known or Suspected MC Hazard		

Table 29 **MRS Priority**

DIRECTIONS: In the chart below, circle the letter rating for each module recorded in Table 10 (EHE), Table 20 (CHE), and Table 28 (HHE). Circle the corresponding numerical priority for each module. If information to determine the module rating is not available, choose the appropriate alternative module rating. The MRS Priority is the single highest priority; record this relative priority in the MRS Priority or Alternative MRS Rating at the bottom of the table.

Note: An MRS assigned Priority 1 has the highest relative priority; an MRS assigned Priority 8 has the lowest relative priority. Only an MRS with CWM known or suspected to be present can be assigned Priority 1; an MRS that has CWM known or suspected to be present cannot be assigned Priority 8.

EHE Rating	Priority	CHE Rating	Priority	HHE Rating	Priority
		Α	1		
A	2	В	2	Α	2
B)	3	С	3	В	3
С	4	D	4	С	4
D	5	E	5	D	5
E	6	F	6	E	6
F	7	G	7	F	7
G	8			G	8
Evaluation	Pending	Evaluation Pending		Evaluation Pending	
No Longer	No Longer Required		No Longer Required		Required
No Known or Suspected Explosive Hazard		No Known or Susp	pected MC Hazard		
MRS PRIORITY or ALTERNATIVE MRS RATING			3	3	

Table A

MRS Background Information

DIRECTIONS: Record the background information below for the MRS to be evaluated. Much of this information is available from Service and DoD databases. If the MRS is located on a FUDS property, the suitable FUDS property information should be substituted. In the MRS Summary, briefly describe the UXO, DMM, or MC that are known or suspected to be present, the exposure setting (the MRS's physical environment), any other incidental nonmunitions-related contaminants (e.g., benzene, trichloroethylene) found at the MRS, and any potentially exposed human and ecological receptors. If possible, include a map of the MRS.

Munitions Response Site Name: Explosive B	urning Grour	nd 1 (L2)			
Component: Active Army					
Installation/Property Name: Joliet Army Amm	unition Plant	t			
Location (City, County, State): Wilmington, W	/ill County, II	linois			
Point of Contact/Phone No.: Art Holz; 815-42	3-2870				
Site Name/Project Name (Project No.): <u>JAAP</u>	<u>'-002-R-01</u>				
MRSPP Score (Date Scored): 14 August 2009)				
Preparer's Name (Organization): Andrew Mal	ly (USAEC)				
MRSPP Rating: 3					
Date Information Entered/Updated: _14 Augusources within the Joliet AAP Administrative Research Point of Contact (Name/Phone): Andrew Male Project Phase (check only one): PA	ecord.		□ FS	□ RD ✓ LTM	<u>n</u>
✓ Groundwater		□ Sodin	nent (human receptor	\	
			, ,		
✓ Surface soil	☐ Surface Water (ecological receptor)				
□ Sediment (ecological receptor) □ Surface Water (human receptor)					
MRS Summary:					

MRS Description: Describe the munitions-related activities that occurred at the installation, the dates of operation, and the UXO, DMM, or MC known or suspected to be present. When possible, identify munitions, CWM, and MC by type:

Ammunition manufacturing, load, assemble, and packaging occurred between 1941 and 1977. The plant made many types of munitions, including ICM and up to 8-inch Howitzer HE projectiles. This MRS is a boundary around a former burning area which included popping furnaces used to burn waste and excess explosives. A remedial action consisting of clearance to 1' depth was conducted in 2007 (HRR Addendum, 2008—Section 2).

Table A

MRS Background Information

DIRECTIONS: Record the background information below for the MRS to be evaluated. Much of this information is available from Service and DoD databases. If the MRS is located on a FUDS property, the suitable FUDS property information should be substituted. In the MRS Summary, briefly describe the UXO, DMM, or MC that are known or suspected to be present, the exposure setting (the MRS's physical environment), any other incidental nonmunitions-related contaminants (e.g., benzene, trichloroethylene) found at the MRS, and any potentially exposed human and ecological receptors. If possible, include a map of the MRS.

Description of Pathways for Human and Ecological Receptors:

Soil is considered to be a complete pathway for Human and Ecological Receptors; however, soil contamination levels were revised to reflect results of sampling from within the MRS, and not from the adjacent IRP site.

Description of Receptors (Human and Ecological):

Human access to the site is limited. The only threatened or endangered species potentially inhabiting JOAAP are grassland birds, including bobolinks, upland sandpipers, and Henslow's sparrows (SI Addendum, 2009— Section 4.1.4.4.3).

EHE Module: Munitions Type Data Element Table

DIRECTIONS: Below are 11 classifications of munitions and their descriptions. Circle the scores that correspond with <u>all</u> the munitions types known or suspected to be present at the MRS.

Note: The terms *practice munitions, small arms ammunition, physical evidence,* and *historical evidence* are defined in Appendix C of the Primer.

Classification	Description	Score
Sensitive	 UXO that are considered most likely to function upon any interaction with exposed persons (e.g., submunitions, 40mm high-explosive [HE] grenades, white phosphorus [WP] munitions, high-explosive antitank [HEAT] munitions, and practice munitions with sensitive fuzes, but excluding all other practice munitions). Hand grenades containing energetic filler. Bulk primary explosives, or mixtures of these with environmental media, such that the mixture poses an explosive hazard. 	30
High explosive (used or damaged)	 UXO containing a high-explosive filler (e.g., RDX, Composition B), that are not considered "sensitive." DMM containing a high-explosive filler that have: Been damaged by burning or detonation Deteriorated to the point of instability. 	25
Pyrotechnic (used or damaged)	 UXO containing a pyrotechnic filler other than white phosphorus (e.g., flares, signals, simulators, smoke grenades). DMM containing a pyrotechnic filler other than white phosphorus (e.g., flares, signals, simulators, smoke grenades) that have: Been damaged by burning or detonation Deteriorated to the point of instability. 	20
High explosive (unused)	DMM containing a high-explosive filler that:	15
Propellant	 UXO containing mostly single-, double-, or triple-based propellant, or composite propellants (e.g., a rocket motor). DMM containing mostly single-, double-, or triple-based propellant, or composite propellants (e.g., a rocket motor) that are: Damaged by burning or detonation Deteriorated to the point of instability. 	15
Bulk secondary high explosives, pyrotechnics, or propellant	 DMM containing mostly single-, double-, or triple-based propellant, or composite propellants (e.g., a rocket motor). DMM that are bulk secondary high explosives, pyrotechnic compositions, or propellant (not contained in a munition), or mixtures of these with environmental media such that the mixture poses an explosive hazard. 	10
Pyrotechnic (not used or damaged)	 DMM containing a pyrotechnic filler (i.e., red phosphorus), other than white phosphorus filler, that: Have not been damaged by burning or detonation Are not deteriorated to the point of instability. 	10
Practice	 UXO that are practice munitions that are not associated with a sensitive fuze. DMM that are practice munitions that are not associated with a sensitive fuze and that have not: Been damaged by burning or detonation Deteriorated to the point of instability. 	5
Riot control	UXO or DMM containing a riot control agent filler (e.g., tear gas).	3
Small arms	 Used munitions or DMM that are categorized as small arms ammunition. (Physical evidence or historical evidence that no other types of munitions [e.g., grenades, subcaliber training rockets, demolition charges] were used or are present on the MRS is required for selection of this category.) 	2
Evidence of no munitions	Following investigation of the MRS, there is physical evidence that there are no UXO or DMM present, or there is historical evidence indicating that no UXO or DMM are present.	0
MUNITIONS TYPE	DIRECTIONS: Record the single highest score from above in the box to the right (maximum score = 30).	30

EHE Module: Munitions Type Data Element Table

DIRECTIONS: Below are 11 classifications of munitions and their descriptions. Circle the scores that correspond with all

the munitions types known or suspected to be present at the MRS.

Note: The terms practice munitions, small arms ammunition, physical evidence, and historical evidence are defined in

Appendix C of the Primer.

Classification Description Score

DIRECTIONS: Document any MRS-specific data used in selecting the *Munitions Type* classifications in the space provided.

The site is a 200-foot buffer zone surrounding the IRP site JAAP-0L2. The Explosive Burning Ground was used from approximately 1942 through the 1970s to burn explosives and associated waste. The IRP site consisted of approximately 45 acres which included six 650 foot long by 50 foot wide gravel burning pads, three popping furnaces, and three oil disposal pits.

Work to clear the site to 1' depth was put under contract in 2005, and work began and was completed in 2007. The site-specific final report for this site (currently draft) indicates the type and quantity of MEC items recovered. The most significant items were BLU 26 and BLU 32, which are the basis for increasing the score for this Table (Draft Final Site-Specific Final Report MMRP Site L2, 2008).

EHE Module: Source of Hazard Data Element Table

DIRECTIONS: Below are 11 classifications describing sources of explosive hazards. Circle the scores that correspond with <u>all</u> the sources of explosive hazards known or suspected to be present at the MRS.

Note: The terms former range, practice munitions, small arms range, physical evidence, and historical evidence are defined in Appendix C of the Primer.

Classification	Description	Score
Former range	 The MRS is a former military range where munitions (including practice munitions with sensitive fuzes) have been used. Such areas include impact or target areas and associated buffer and safety zones. 	10
Former munitions treatment (i.e., OB/OD) unit	 The MRS is a location where UXO or DMM (e.g., munitions, bulk explosives, bulk pyrotechnic, or bulk propellants) were burned or detonated for the purpose of treatment prior to disposal. 	$\bigcirc \infty$
Former practice munitions range	The MRS is a former military range on which only practice munitions without sensitive fuzes were used.	6
Former maneuver area	 The MRS is a former maneuver area where no munitions other than flares, simulators, smokes, and blanks were used. There must be evidence that no other munitions were used at the location to place an MRS into this category. 	5
Former burial pit or other disposal area	The MRS is a location where DMM were buried or disposed of (e.g., disposed of into a water body) without prior thermal treatment.	5
Former industrial operating facilities	The MRS is a location that is a former munitions maintenance, manufacturing, or demilitarization facility.	4
Former firing points	The MRS is a firing point, where the firing point is delineated as an MRS separate from the rest of a former military range.	4
Former missile or air defense artillery emplacements	 The MRS is a former missile defense or air defense artillery (ADA) emplacement not associated with a military range. 	2
Former storage or transfer points	The MRS is a location where munitions were stored or handled for transfer between different modes of transportation (e.g., rail to truck, truck to weapon system).	2
Former small arms range	The MRS is a former military range where only small arms ammunition was used. (There must be evidence that no other types of munitions [e.g., grenades] were used or are present to place an MRS into this category.)	1
Evidence of no munitions	 Following investigation of the MRS, there is physical evidence that no UXO or DMM are present, or there is historical evidence indicating that no UXO or DMM are present. 	0
SOURCE OF HAZARD	DIRECTIONS: Record the single highest score from above in the box to the right (maximum score = 10).	8

DIRECTIONS: Document any MRS-specific data used in selecting the **Source of Hazard** classifications in the space provided.

Historical records indicate this site is in the kick-out boundary of an area used for demolition of UXO and DMM (SI, 2005—Section 4.1).

EHE Module: Location of Munitions Data Element Table

DIRECTIONS: Below are eight classifications of munitions locations and their descriptions. Circle the scores that correspond with **all** the locations where munitions are known or suspected to be present at the MRS.

Note: The terms *confirmed, surface, subsurface, small arms ammunition, physical evidence,* and *historical evidence* are defined in Appendix C of the Primer.

Classification	Description	Score
Confirmed surface	 Physical evidence indicates that there are UXO or DMM on the surface of the MRS. Historical evidence (i.e., a confirmed report such as an explosive ordnance disposal [EOD], police, or fire department report that an incident or accident that involved UXO or DMM occurred) indicates there are UXO or DMM on the surface of the MRS. 	25
Confirmed subsurface, active	 Physical evidence indicates the presence of UXO or DMM in the subsurface of the MRS, and the geological conditions at the MRS are likely to cause UXO or DMM to be exposed, in the future, by naturally occurring phenomena (e.g., drought, flooding, erosion, frost heave, tidal action), or intrusive activities (e.g., plowing, construction, dredging) at the MRS are likely to expose UXO or DMM. Historical evidence indicates that UXO or DMM are located in the subsurface of the MRS and the geological conditions at the MRS are likely to cause UXO or DMM to be exposed, in the future, by naturally occurring phenomena (e.g., drought, flooding, erosion, frost heave, tidal action), or intrusive activities (e.g., plowing, construction, dredging) at the MRS are likely to expose UXO or DMM. 	20
Confirmed subsurface, stable	 Physical evidence indicates the presence of UXO or DMM in the subsurface of the MRS and the geological conditions at the MRS are not likely to cause UXO or DMM to be exposed, in the future, by naturally occurring phenomena, or intrusive activities at the MRS are not likely to cause UXO or DMM to be exposed. Historical evidence indicates that UXO or DMM are located in the subsurface of the MRS and the geological conditions at the MRS are not likely to cause UXO or DMM to be exposed, in the future, by naturally occurring phenomena, or intrusive activities at the MRS are not likely to cause UXO or DMM to be exposed. 	15
Suspected (physical evidence)	 There is physical evidence (e.g., munitions debris such as fragments, penetrators, projectiles, shell casings, links, fins), other than the documented presence of UXO or DMM, indicating that UXO or DMM may be present at the MRS. 	10
Suspected (historical evidence)	There is historical evidence indicating that UXO or DMM may be present at the MRS.	5
Subsurface, physical constraint	 There is physical or historical evidence indicating that UXO or DMM may be present in the subsurface, but there is a physical constraint (e.g., pavement, water depth over 120 feet) preventing direct access to the UXO or DMM. 	2
Small arms (regardless of location)	The presence of small arms ammunition is confirmed or suspected, regardless of other factors such as geological stability. (There must be evidence that no other types of munitions [e.g., grenades] were used or are present at the MRS to place an MRS into this category.)	1
Evidence of no munitions	Following investigation of the MRS, there is physical evidence that there are no UXO or DMM present, or there is historical evidence indicating that no UXO or DMM are present.	0
LOCATION OF MUNITIONS	DIRECTIONS: Record the single highest score from above in the box to the right (maximum score = 25).	20

DIRECTIONS: Document any MRS-specific data used in selecting the *Location of Munitions* classifications in the space provided.

In 2007, MKM and PIKA International performed a 1' surface clearance of the site. During the clearance operations, the site was subject to flooding, and this resulted in the exposure of previously buried items (which were also cleared). The site will be subject to regular flooding due to its proximity to Prairie Creek. The clearance is documented in the site specific report (Draft Final Site-Specific Final Report MMRP Site L2, 2008).

EHE Module: Ease of Access Data Element Table

DIRECTIONS: Below are four classifications of barrier types that can surround an MRS and their descriptions. The

barrier type is directly related to the ease of public access to the MRS. Circle the score that corresponds

with the ease of access to the MRS.

Note: The term *barrier* is defined in Appendix C of the Primer.

Classification	Description	Score
No barrier	There is no barrier preventing access to any part of the MRS (i.e., all parts of the MRS are accessible).	10
Barrier to MRS access is incomplete	There is a barrier preventing access to parts of the MRS, but not the entire MRS.	8
Barrier to MRS access is complete but not monitored	There is a barrier preventing access to all parts of the MRS, but there is no surveillance (e.g., by a guard) to ensure that the barrier is effectively preventing access to all parts of the MRS.	5
Barrier to MRS access is complete and monitored	There is a barrier preventing access to all parts of the MRS, and there is active, continual surveillance (e.g., by a guard, video monitoring) to ensure that the barrier is effectively preventing access to all parts of the MRS.	0
EASE OF ACCESS	DIRECTIONS: Record the single highest score from above in the box to the right (maximum score = 10).	5

DIRECTIONS: Document any MRS-specific data used in selecting the *Ease of Access* classification in the space provided.

The public has no access to this site; the site is surrounded by a fence with a locked gate, and only two keys exist for the lock. All visitors must be accompanied by facility personnel; however, the area is not monitored to prevent trespassers from gaining access (HRR Addendum, 2008—Section 5.3.2).

Table 5EHE Module: Status of Property Data Element Table

DIRECTIONS: Below are three classifications of the status of a property within the Department of Defense (DoD) and their descriptions. Circle the score that corresponds with the status of property at the MRS.

Classification	Description	Score
Non-DoD control	 The MRS is at a location that is no longer owned by, leased to, or otherwise possessed or used by DoD. Examples are privately owned land or water bodies; land or water bodies owned or controlled by state, tribal, or local governments; and land or water bodies managed by other federal agencies. The MRS is at a location that is owned by DoD, but that DoD has leased to another entity and for which DoD does not control access 24 hours per day. 	5
Scheduled for transfer from DoD control	The MRS is on land or is a water body that is owned, leased, or otherwise possessed by DoD, and DoD plans to transfer that land or water body to the control of another entity (e.g., a state, tribal, or local government; a private party; another federal agency) within 3 years from the date the Protocol is applied.	3
DoD control	The MRS is on land or is a water body that is owned, leased, or otherwise possessed by DoD. With respect to property that is leased or otherwise possessed, DoD must control access to the MRS 24 hours per day, every day of the calendar year.	0
STATUS OF PROPERTY	DIRECTIONS: Record the single highest score from above in the box to the right (maximum score = 5).	3

DIRECTIONS: Document any MRS-specific data used in selecting the *Status of Property* classification in the space provided.

The planned future use for this site is open space for the USDA Midewin National Tallgrass Prairie (HRR Addendum, 2008—Section 5.3.2).

EHE Module: Population Density Data Element Table

DIRECTIONS: Below are three classifications for population density and their descriptions. Determine the population density per square mile that most closely corresponds with the population of the MRS, including the area within a two-mile radius of the MRS's perimeter. Circle the most appropriate score.

Note: Use the U.S. Census Bureau tract data available to capture the <u>highest</u> population density within a two-mile radius of the perimeter of the MRS.

Classification	Description	Score
> 500 persons per square mile	There are more than 500 persons per square mile in the U.S. Census Bureau tract in which the MRS is located.	5
100–500 persons per square mile	There are 100 to 500 persons per square mile in the U.S. Census Bureau tract in which the MRS is located.	3
< 100 persons per square mile	There are fewer than 100 persons per square mile in the U.S. Census Bureau tract in which the MRS is located.	1
POPULATION DENSITY	DIRECTIONS: Record the single highest score from above in the box to the right (maximum score = 5).	3

DIRECTIONS: Document any MRS-specific data used in selecting the *Population Density* classification in the space provided.

U.S. Census Bureau 2000 data, Will County = 296 - 600 persons per square mile. The maximum data class of persons per square mile in the town of Wilmington, which is the closest town to the site is 367.

EHE Module: Population Near Hazard Data Element Table

DIRECTIONS: Below are six classifications describing the number of inhabited structures near the MRS. The number of inhabited buildings relates to the potential population near the MRS. Determine the number of inhabited structures within two miles of the MRS boundary and circle the score that corresponds with the number of inhabited structures.

Note: The term *inhabited structures* is defined in Appendix C of the Primer.

Classification	Description	Score
26 or more inhabited structures	There are 26 or more inhabited structures located up to 2 miles from the boundary of the MRS, within the boundary of the MRS, or both.	5
16 to 25 inhabited structures	 There are 16 to 25 inhabited structures located up to 2 miles from the boundary of the MRS, within the boundary of the MRS, or both. 	4
11 to 15 inhabited structures	There are 11 to 15 inhabited structures located up to 2 miles from the boundary of the MRS, within the boundary of the MRS, or both.	3
6 to 10 inhabited structures	There are 6 to 10 inhabited structures located up to 2 miles from the boundary of the MRS, within the boundary of the MRS, or both.	2
1 to 5 inhabited structures	There are 1 to 5 inhabited structures located up to 2 miles from the boundary of the MRS, within the boundary of the MRS, or both.	1
0 inhabited structures	There are no inhabited structures located up to 2 miles from the boundary of the MRS, within the boundary of the MRS, or both.	0
POPULATION NEAR HAZARD	DIRECTIONS: Record the single highest score from above in the box to the right (maximum score = 5).	5

DIRECTIONS: Document any MRS-specific data used in selecting the *Population Near Hazard* classification in the space provided.

Homes, offices, a feed mill, and agricultural lands are located within 2 miles of this site. Recent development has increased the number of inhabited structures located up to 2 miles from the boundary of the MRS (HRR Addendum, 2008—Section 5.3.2).

EHE Module: Types of Activities/Structures Data Element Table

DIRECTIONS: Below are five classifications of activities and/or inhabited structures and their descriptions. Review the

types of activities that occur and/or structures that are present within two miles of the MRS and circle the

scores that correspond with all the activities/structure classifications at the MRS.

Note: The term *inhabited structure* is defined in Appendix C of the Primer.

Classification	Description	Score
Residential, educational, commercial, or subsistence	 Activities are conducted, or inhabited structures are located up to two miles from the MRS's boundary or within the MRS's boundary, that are associated with any of the following purposes: residential, educational, child care, critical assets (e.g., hospitals, fire and rescue, police stations, dams), hotels, commercial, shopping centers, playgrounds, community gathering areas, religious sites, or sites used for subsistence hunting, fishing, and gathering. 	5
Parks and recreational areas	Activities are conducted, or inhabited structures are located up to two miles from the MRS's boundary or within the MRS's boundary, that are associated with parks, nature preserves, or other recreational uses.	4
Agricultural, forestry	Activities are conducted, or inhabited structures are located up to two miles from the MRS's boundary or within the MRS's boundary, that are associated with agriculture or forestry.	3
Industrial or warehousing	Activities are conducted, or inhabited structures are located up to two miles from the MRS's boundary or within the MRS's boundary, that are associated with industrial activities or warehousing.	2
No known or recurring activities	There are no known or recurring activities occurring up to two miles from the MRS's boundary or within the MRS's boundary.	1
TYPES OF ACTIVITIES/STRUCTURES	DIRECTIONS: Record <u>the single highest score</u> from above in the box to the right (maximum score = 5).	5

DIRECTIONS: Document any MRS-specific data used in selecting the *Types of Activities/Structures* classifications in the space provided.

Homes, offices, a feed mill, and agricultural lands are located within 2 miles of this site. The planned future use for this site is open space for the USDA Midewin National Tallgrass Prairie which is also presently located within 2 miles of the site. Recent development has increased the number of residences located within 2 miles of the MRS (HRR Addendum, 2008—Section 5.3.2).

EHE Module: Ecological and/or Cultural Resources Data Element Table

DIRECTIONS: Below are four classifications of ecological and/or cultural resources and their descriptions. Review the types of resources present and circle the score that corresponds with the ecological and/or cultural

resources present on the MRS.

Note: The terms ecological resources and cultural resources are defined in Appendix C of the Primer.

Classification	Description	Score
Ecological and cultural resources present	There are both ecological and cultural resources present on the MRS.	5
Ecological resources present	There are ecological resources present on the MRS.	3
Cultural resources present	There are cultural resources present on the MRS.	3
No ecological or cultural resources present	 There are no ecological resources or cultural resources present on the MRS. 	
ECOLOGICAL AND/OR CULTURAL RESOURCES	DIRECTIONS: Record the single highest score from above in the box to the right (maximum score = 5).	

DIRECTIONS: Document any MRS-specific data used in selecting the *Ecological and/or Cultural Resources* classification in the space provided.

This site is adjacent to Prairie Creek and Kemery Lake. An ecologist at Midewin Tallgrass Prairie confirmed that grassland birds are the only threatened and endangered species at JOAAP. These birds include bobolinks, upland sandpipers, and Henslow's sparrows (HRR Addendum, 2008—Section 5.3.3.2)

Table 10 Determining the EHE Module Rating

DIRECTIONS:

- 1. From Tables 1–9, record the data element scores in the **Score** boxes to the right.
- Add the **Score** boxes for each of the three factors and record this number in the **Value** boxes to the right.
- Add the three Value boxes and record this number in the EHE Module Total box below.
- 4. Circle the appropriate range for the **EHE Module Total** below.
- 5. Circle the **EHE Module Rating** that corresponds to the range selected and record this value in the **EHE Module Rating** box found at the bottom of the table.

Note:

An alternative module rating may be assigned when a module letter rating is inappropriate. An alternative module rating is used when more information is needed to score one or more data elements, contamination at an MRS was previously addressed, or there is no reason to suspect contamination was ever present at an MRS.

	Source	Score	Value
Explosive Hazard Factor Data Ele	ements		
Munitions Type	Table 1	30	38
Source of Hazard	Table 2	8	30
Accessibility Factor Data Elemen	nts		
Location of Munitions	Table 3	20	
Ease of Access	Table 4	5	28
Status of Property	Table 5	3	
Receptor Factor Data Elements			
Population Density	Table 6	3	
Population Near Hazard	Table 7	5	40
Types of Activities/Structures	Table 8	5	16
Ecological and/or Cultural Resources	Table 9	3	
EHE	MODULE	E TOTAL	82
EHE Module Total	EHE	Module R	ating
92 to 100		Α	
82 to 91		В	
71 to 81		С	
60 to 70		D	
48 to 59	E		
38 to 47	F		
less than 38	G		
	Eva	luation Pen	ding
Alternative Module Ratings	No I	_onger Requ	uired
	No Known or Suspected Explosive Hazard		
EHE MODULE RATING		В	

CHE Module: CWM Configuration Data Element Table

DIRECTIONS: Below are seven classifications of CWM configuration and their descriptions. Circle the scores that

correspond with <u>all</u> the CWM configurations known or suspected to be present at the MRS.

Note: The terms CWM/UXO, CWM/DMM, physical evidence, and historical evidence are defined in Appendix C of the

Primer.

Classification	Description	Score
CWM, that are either UXO, or explosively configured damaged DMM	 The CWM known or suspected of being present at the MRS are: CWM that are UXO (i.e., CWM/UXO) Explosively configured CWM that are DMM (i.e., CWM/DMM) that have been damaged. 	30
CWM mixed with UXO	The CWM known or suspected of being present at the MRS are undamaged CWM/DMM or CWM not configured as a munition that are commingled with conventional munitions that are UXO.	25
CWM, explosive configuration that are undamaged DMM	The CWM known or suspected of being present at the MRS are explosively configured CWM/DMM that have not been damaged.	20
CWM/DMM, not explosively configured or CWM, bulk container	 The CWM known or suspected of being present at the MRS are: Nonexplosively configured CWM/DMM either damaged or undamaged Bulk CWM (e.g., ton container). 	15
CAIS K941 and CAIS K942	The CWM/DMM known or suspected of being present at the MRS are CAIS K941-toxic gas set M-1 or CAIS K942-toxic gas set M-2/E11.	12
CAIS (chemical agent identification sets)	CAIS, other than CAIS K941 and K942, are known or suspected of being present at the MRS.	10
Evidence of no CWM	 Following investigation, the physical evidence indicates that CWM are not present at the MRS, or the historical evidence indicates that CWM are not present at the MRS. 	0
CWM CONFIGURATION	DIRECTIONS: Record <u>the single highest score</u> from above in the box to the right (maximum score = 30).	0

DIRECTIONS: Document any MRS-specific data used in selecting the *CWM Configuration* classifications in the space provided.

The historical use of the site did not include CWM (HRR Addendum, 2008—Section 4.1.1.2). EODT performed a site characterization for this area in 2001 and no CWM was found. Site clearance to 1' depth conducted in 2007 did not find any CWM (Draft Final Site-Specific Final Report MMRP Site L2, 2008).

Tables 12 - 19

CHE Module: Sources of CWM Data Element Table

DIRECTIONS: Below are 11 sources of CWM hazards and their descriptions. Review these classifications and circle

the scores that correspond with all the sources of CWM hazards known or suspected to be present at

the MRS.

Note: The terms CWM/UXO, CWM/DMM, CAIS/DMM, surface, subsurface, physical evidence, and historical evidence

are defined in Appendix C of the Primer.

Classification	Description	Coore
Classification	Description	Score

No known or suspected CWM hazard is expected at this site. Therefore, Tables 12 through 19 have been intentionally omitted according to Active Army Guidance.

Table 20 Determining the CHE Module Rating

DIRECTIONS:

- From Tables 11–19, record the data element scores in the Score boxes to the right.
- Add the **Score** boxes for each of the three factors and record this number in the **Value** boxes to the right.
- Add the three Value boxes and record this number in the CHE Module Total box below.
- 4. Circle the appropriate range for the **CHE Module Total** below.
- 5. Circle the **CHE Module Rating** that corresponds to the range selected and record this value in the **CHE Module Rating** box found at the bottom of the table.

Note:

An alternative module rating may be assigned when a module letter rating is inappropriate. An alternative module rating is used when more information is needed to score one or more data elements, contamination at an MRS was previously addressed, or there is no reason to suspect contamination was ever present at an MRS.

	Source	Score	Value
CWM Hazard Factor Data Elemer	nts		
CWM Configuration	Table 11	0	0
Sources of CWM	Table 12		0
Accessibility Factor Data Elemen	nts		
Location of CWM	Table 13		
Ease of Access	Table 14		
Status of Property	Table 15		
Receptor Factor Data Elements			
Population Density	Table 16		
Population Near Hazard	Table 17		
Types of Activities/Structures	Table 18		
Ecological and/or Cultural Resources	Table 19		
CHE	MODULE	E TOTAL	0
CHE Module Total	CHE Module Rating		ating
92 to 100		Α	
82 to 91		В	
71 to 81		С	
60 to 70		D	
48 to 59	E		
38 to 47	F		
less than 38	G		
	Evaluation Pending		
Alternative Module Ratings	No Longer Required		
	No Know	n or Suspec Hazard	ted CWM
CHE MODULE RATING	_	KNOWN PECTED (HAZARD	_

HHE Module: Groundwater Data Element Table

Contaminant Hazard Factor (CHF)

DIRECTIONS: Record the maximum concentrations of all contaminants in the MRS's groundwater and their comparison values (from Appendix B of the Primer) in the table below. Additional contaminants can be recorded on Table 27. Calculate and record the ratios for each contaminant by dividing the maximum concentration by the comparison value. Determine the CHF by adding the contaminant ratios together, including any additional groundwater contaminants recorded on Table 27. Based on the CHF, use the CHF Scale to determine and record the CHF Value. If there is no known or suspected MC hazard present in the groundwater, select the box at the bottom of the table.

Contaminant	Maximum Concentration (μg/L)	Comparison Value (μg/L)	Ratios
CHF Scale	CHF Value	Sum The Ratios	
CHF > 100	H (High)	CHF = [Maximum Concentration of Co	ontaminantl
100 > CHF > 2	M (Medium)	CHF = \(\frac{1}{2} \)	itl
2 > CHF	L (Low)	[Comparison Value for Conta	minantj
CONTAMINANT HAZARD FACTOR	DIRECTIONS: Record the CHF Value (maximum value = H).	from above in the box to the right	
	· ·	the groundwater migratory pathway at the N	MRS.
Classification		cription	Value
Evident	Analytical data or observable evidence indicates moving toward, or has moved to a point of expos	that contamination in the groundwater is present at, ure.	Н
Potential	Contamination in groundwater has moved only slightly beyond the source (i.e., tens of feet), could move but is not moving appreciably, or information is not sufficient to make a determination of Evident or Confined.		М
Confined	Information indicates a low potential for contaminant migration from the source via the groundwater to a potential point of exposure (possibly due to the presence of geological structures or physical controls).		L
MIGRATORY PATHWAY FACTOR	DIRECTIONS: Record the single high right (maximum value =	nest value from above in the box to the = H).	
DIRECTIONS: Circle to	Receptor Face that corresponds most closely to		
Classification	Des	cription	Value
Identified	There is a threatened water supply well downgra source of drinking water or source of water for ot (equivalent to Class I or IIA aquifer).	dient of the source and the groundwater is a current ner beneficial uses such as irrigation/agriculture	Н
Potential	There is no threatened water supply well downgradient of the source and the groundwater is currently or potentially usable for drinking water, irrigation, or agriculture (equivalent to Class I, IIA, or IIB aquifer).		М
Limited	There is no potentially threatened water supply well downgradient of the source and the groundwater is not considered a potential source of drinking water and is of limited beneficial use (equivalent to Class IIIA or IIIB aquifer, or where perched aquifer exists only).		L
RECEPTOR FACTOR	DIRECTIONS: Record the single high right (maximum value =	nest value from above in the box to the H).	
	No Kno	wn or Suspected Groundwater MC Hazard	X

HHE Module: Surface Water - Human Endpoint Data Element Table

Contaminant Hazard Factor (CHF)

DIRECTIONS: Record the maximum concentrations of all contaminants in the MRS's surface water and their comparison values (from Appendix B of the Primer) in the table below. Additional contaminants can be recorded on Table 27. Calculate and record the ratios for each contaminant by dividing the maximum concentration by the comparison value. Determine the CHF by adding the contaminant ratios together, including any additional surface water contaminants recorded on Table 27. Based on the CHF, use the CHF Scale to determine and record the CHF Value. If there is no known or suspected MC hazard with human endpoints present in the surface water, select the box at the bottom of the table.

Contaminant	Maximum Concentration (μg/L)	Comparison Value (μg/L)	Ratios
CHF Scale	CHF Value	Sum The Ratios	
CHF > 100	H (High)	INAccione Con contration of Co	
100 > CHF > 2	M (Medium)	CHF = [Maximum Concentration of Co	ontaminantj
2 > CHF	L (Low)	[Comparison Value for Conta	minant]
CONTAMINANT HAZARD FACTOR	DIRECTIONS: Record the CHF Value (maximum value = H).	from above in the box to the right	
DIRECTIONS: Circle t	Migratory Pathw the value that corresponds most closely to	vay Factor o the surface water migratory pathway at the	MRS.
Classification	Desc	cription	Value
Evident	Analytical data or observable evidence indicates that contamination in the surface water is present at, moving toward, or has moved to a point of exposure.		Н
Potential	Contamination in surface water has moved only slightly beyond the source (i.e., tens of feet), could move but is not moving appreciably, or information is not sufficient to make a determination of Evident or Confined.		М
Confined	Information indicates a low potential for contaminant migration from the source via the surface water to a potential point of exposure (possibly due to the presence of geological structures or physical controls).		L
MIGRATORY PATHWAY FACTOR	DIRECTIONS: Record the single high right (maximum value =		
	· ·	the surface water receptors at the MRS.	Value
Classification	Identified receptors have access to surface water	cription	Value
Identified	identified receptors have access to surface water	to which contamination has moved or can move.	Н
Potential	Potential for receptors to have access to surface water to which contamination has moved or can move.		М
Limited	Little or no potential for receptors to have access to surface water to which contamination has moved or can move.		L
RECEPTOR FACTOR	DIRECTIONS: Record the single high the right (maximum value)		

No Known or Suspected Surface Water (Human Endpoint) MC Hazard

 \times

HHE Module: Sediment – Human Endpoint Data Element Table

Contaminant Hazard Factor (CHF)

FACTOR

DIRECTIONS: Record the **maximum concentrations** of all contaminants in the MRS's sediment and their **comparison** values (from Appendix B of the Primer) in the table below. Additional contaminants can be recorded on Table 27. Calculate and record the ratios for each contaminant by dividing the maximum concentration by the comparison value. Determine the CHF by adding the contaminant ratios together, including any additional sediment contaminants recorded on Table 27. Based on the CHF, use the CHF Scale to determine and record the CHF Value. If there is no known or suspected MC hazard with human endpoints present in the sediment, select the box at the bottom of the table.

with number of apoints present in the seament, select the box at the bottom of the table.			
Contaminant	Maximum Concentration (mg/kg)	Comparison Value (mg/kg)	Ratios
CHF Scale	CHF Value	Sum The Ratios	
CHF > 100	H (High)	— Maximum Concentration of C	ontominantl
100 > CHF > 2	M (Medium)	CHF = [Maximum Concentration of C	Ontaminantj
2 > CHF	L (Low)	[Comparison Value for Conta	aminant]
CONTAMINANT HAZARD FACTOR	DIRECTIONS: Record the CHF Value maximum value = H).	from above in the box to the right	
DIRECTIONS: Circle to	·	vay Factor to the sediment migratory pathway at the MR cription	S. Value
	Analytical data or observable evidence indicates	•	
Evident	moving toward, or has moved to a point of expos	ure.	Н
Potential		tly beyond the source (i.e., tens of feet), could move ot sufficient to make a determination of Evident or	М
Confined		nant migration from the source via the sediment to a resence of geological structures or physical controls).	L
MIGRATORY PATHWAY FACTOR	DIRECTIONS: Record the single high right (maximum value =	hest value from above in the box to the = H).	
DIRECTIONS: Circle to	Receptor Face that corresponds most closely to		
Classification	Des	cription	Value
Identified	Identified receptors have access to sediment to v	which contamination has moved or can move.	Н
Potential	Potential for receptors to have access to sediment	nt to which contamination has moved or can move.	M
Limited	Little or no potential for receptors to have access can move.	to sediment to which contamination has moved or	L
RECEPTOR	DIRECTIONS: Record the single high		

the right (maximum value = H).

No Known or Suspected Sediment (Human Endpoint) MC Hazard

 \boxtimes

HHE Module: Surface Water - Ecological Endpoint Data Element Table

Contaminant Hazard Factor (CHF)

DIRECTIONS: Record the maximum concentrations of all contaminants in the MRS's surface water and their comparison values (from Appendix B of the Primer) in the table below. Additional contaminants can be recorded on Table 27. Calculate and record the ratios for each contaminant by dividing the maximum concentration by the comparison value. Determine the CHF by adding the contaminant ratios together, including any additional surface water contaminants recorded on Table 27. Based on the CHF, use the CHF Scale to determine and record the CHF Value. If there is no known or suspected MC hazard with ecological endpoints present in the surface water, select the box at the bottom of the table.

Contaminant	Maximum Concentration (μg/L)	Comparison Value (μg/L)	Ratios
CHF Scale	CHF Value	Sum the Ratios	
CHF > 100	H (High)	INAccione Consentantia e et C	
100 > CHF > 2	M (Medium)	CHF = [Maximum Concentration of Co	ontaminantj
2 > CHF	L (Low)	[Comparison Value for Conta	minant]
CONTAMINANT HAZARD FACTOR	DIRECTIONS: Record the CHF Value (maximum value = H).	from above in the box to the right	
DIRECTIONS: Circle to	Migratory Pathw he value that corresponds most closely to	vay Factor the surface water migratory pathway at the	MRS.
Classification	Des	cription	Value
Evident	Analytical data or observable evidence indicates that contamination in the surface water is present at, moving toward, or has moved to a point of exposure.		Н
Potential	Contamination in surface water has moved only slightly beyond the source (i.e., tens of feet), could move but is not moving appreciably, or information is not sufficient to make a determination of Evident or Confined.		М
Confined	Information indicates a low potential for contamir to a potential point of exposure (possibly due to t controls).	nant migration from the source via the surface water the presence of geological structures or physical	L
MIGRATORY PATHWAY FACTOR	DIRECTIONS: Record the single high right (maximum value =	hest value from above in the box to the = H).	
DIRECTIONS: Circle to	Receptor F	actor o the surface water receptors at the MRS.	
Classification	· ·	cription	Value
Identified		r to which contamination has moved or can move.	H
Potential	Potential for receptors to have access to surface move.	water to which contamination has moved or can	М
Limited	Little or no potential for receptors to have access or can move.	to surface water to which contamination has moved	L
RECEPTOR FACTOR	DIRECTIONS: Record the single high right (maximum value =	hest value from above in the box to the = H).	
	No Known or Suspected Surface	ce Water (Ecological Endpoint) MC Hazard	X

HHE Module: Sediment - Ecological Endpoint Data Element Table

Contaminant Hazard Factor (CHF)

DIRECTIONS: Record the **maximum concentrations** of all contaminants in the MRS's sediment and their **comparison** values (from Appendix B of the Primer) in the table below. Additional contaminants can be recorded on Table 27. Calculate and record the ratios for each contaminant by dividing the maximum concentration by the comparison value. Determine the CHF by adding the contaminant ratios together, including any additional sediment contaminants recorded on Table 27. Based on the CHF, use the CHF Scale to determine and record the CHF Value. If there is no known or suspected MC hazard

with ecological endpoints present in the sediment, select the box at the bottom of the table. Contaminant Maximum Concentration (mg/kg) Comparison Value (mg/kg) Ratios **CHF Scale CHF Value Sum the Ratios** CHF > 100 H (High) **CHF** = \(\sum_{\text{Maximum}} \text{Concentration of Contaminant} \) 100 > CHF > 2 M (Medium) [Comparison Value for Contaminant] 2 > CHF L (Low) **CONTAMINANT DIRECTIONS:** Record the CHF Value from above in the box to the right (maximum value = H). HAZARD FACTOR Migratory Pathway Factor **DIRECTIONS:** Circle the value that corresponds most closely to the sediment migratory pathway at the MRS.

Classification	Description	Value
Evident	Analytical data or observable evidence indicates that contamination in the sediment is present at, moving toward, or has moved to a point of exposure.	Н
Potential	Contamination in sediment has moved only slightly beyond the source (i.e., tens of feet), could move but is not moving appreciably, or information is not sufficient to make a determination of Evident or Confined.	M
Confined	Information indicates a low potential for contaminant migration from the source via the sediment to a potential point of exposure (possibly due to the presence of geological structures or physical controls).	L
MIGRATORY PATHWAY FACTOR	DIRECTIONS: Record the single highest value from above in the box to the right (maximum value = H).	

Receptor Factor

DIRECTIONS: Circle the value that corresponds most closely to the sediment receptors at the MRS.

Classification	Description			
Identified	Identified receptors have access to sediment to which contamination has moved or can move.			
Potential	Potential for receptors to have access to sediment to which contamination has moved or can move.	М		
Limited	Little or no potential for receptors to have access to sediment to which contamination has moved or can move.			
RECEPTOR FACTOR	DIRECTIONS: Record <u>the single highest value</u> from above in the box to the right (maximum value = H).			

No Known or Suspected Sediment (Ecological Endpoint) MC Hazard



HHE Module: Surface Soil Data Element Table

Contaminant Hazard Factor (CHF)

DIRECTIONS: Record the maximum concentrations of all contaminants in the MRS's surface soil and their comparison values (from Appendix B of the Primer) in the table below. Additional contaminants can be recorded on Table 27. Calculate and record the ratios for each contaminant by dividing the maximum concentration by the comparison value. Determine the CHF by adding the contaminant ratios together, including any additional surface soil contaminants recorded on Table 27. Based on the CHF, use the CHF Scale to determine and record the CHF Value. If there is no known or suspected MC hazard present in the surface soil, select the box at the bottom of the table.

Contaminant	Maximum Concentration (mg/kg) Comparison Value (mg/kg)				
CHF Scale	CHF Value	Sum the Ratios			
CHF > 100	H (High)	CHF = [Maximum Concentration of Concentr	ntaminantl		
100 > CHF > 2	M (Medium)	CHF = \(\frac{1}{2} \)	· a		
2 > CHF	L (Low)	[Comparison Value for Contan	nınantj		
CONTAMINANT HAZARD FACTOR	DIRECTIONS: Record the CHF Value (maximum value = H				
DIRECTIONS: Circle t	·	nway Factor to the surface soil migratory pathway at the Mescription	RS. Value		
		es that contamination in the surface soil is present at,			
Evident	moving toward, or has moved to a point of exposure.				
Potential	Contamination in surface soil has moved only slightly beyond the source (i.e., tens of feet), could move but is not moving appreciably, or information is not sufficient to make a determination of Evident or Confined.				
Confined		ninant migration from the source via the surface soil to he presence of geological structures or physical	L		
MIGRATORY PATHWAY FACTOR	DIRECTIONS: Record the single highest value from above in the box to the right (maximum value = H).				
	·	to the surface soil receptors at the MRS.			
Classification		escription	Value		
Identified	Identified receptors have access to surface soil to which contamination has moved or can move.				
identined					
Potential	Potential for receptors to have access to surfa	ce soil to which contamination has moved or can move.	М		
		ce soil to which contamination has moved or can move.	M L		

No Known or Suspected Surface Soil MC Hazard



HHE Module: Supplemental Contaminant Hazard Factor Table

Contaminant Hazard Factor (CHF)

DIRECTIONS: Only use this table if there are more than five contaminants in any given medium present at the

MRS. This is a supplemental table designed to hold information about contaminants that do not fit in the previous tables. Indicate the **media** in which these contaminants are present. Then record all **contaminants**, their **maximum concentrations** and their **comparison values** (from Appendix B of the Primer) in the table below. Calculate and record the **ratio** for each contaminant by dividing the **maximum concentration** by the **comparison value**. Determine the **CHF** for each medium on the appropriate media-specific tables.

Note: Do not add ratios from different media.

Media	Contaminant	Maximum Concentration	Comparison Value	Ratio

Table 28 Determining the HHE Module Rating

DIRECTIONS:

- 1. Record the letter values (H, M, L) for the **Contaminant Hazard**, **Migration Pathway**, and **Receptor Factors** for the media (from Tables 21–26) in the corresponding boxes below.
- 2. Record the media's three-letter combinations in the **Three-Letter Combination** boxes below (three-letter combinations are arranged from Hs to Ms to Ls).
- 3. Using the **HHE Ratings** provided below, determine each media's rating (A–G) and record the letter in the corresponding **Media Rating** box below.

Media (Source)	Contaminant Hazard Factor Value	Migratory Pathway Factor Value	Receptor Factor Value	Three-Letter Combination (Hs-Ms-Ls)	Media Rating (A-G)
Groundwater (Table 21)					
Surface Water/Human Endpoint (Table 22)					
Sediment/Human Endpoint (Table 23)					
Surface Water/Ecological Endpoint (Table 24)					
Sediment/Ecological Endpoint (Table 25)					
Surface Soil (Table 26)					

DIRECTIONS (cont.):

4. Select the single highest Media Rating (A is highest; G is lowest) and enter the letter in the **HHE Module Rating** box.

Note:

An alternative module rating may be assigned when a module letter rating is inappropriate. An alternative module rating is used when more information is needed to score one or more media, contamination at an MRS was previously addressed, or there is no reason to suspect contamination was ever present at an MRS.

HHE MODULE RATING

HHE Ratings (for reference only)				
Combination	Rating			
ННН	Α			
ННМ	В			
HHL				
НММ	С			
HML	2			
MMM	D			
HLL	E			
MML				
MLL	F			
LLL	G			
	Evaluation Pending			
Alternative Module Ratings	No Longer Required			
(No Known or Suspected MC Hazard			

Table 29 **MRS Priority**

DIRECTIONS: In the chart below, circle the letter rating for each module recorded in Table 10 (EHE), Table 20 (CHE), and Table 28 (HHE). Circle the corresponding numerical priority for each module. If information to determine the module rating is not available, choose the appropriate alternative module rating. The MRS Priority is the single highest priority; record this relative priority in the MRS Priority or Alternative MRS Rating at the bottom of the table.

Note: An MRS assigned Priority 1 has the highest relative priority; an MRS assigned Priority 8 has the lowest relative priority. Only an MRS with CWM known or suspected to be present can be assigned Priority 1; an MRS that has CWM known or suspected to be present cannot be assigned Priority 8.

EHE Rating	Priority	CHE Rating	Priority	HHE Rating	Priority
		Α	1		
Α	2	В	2	Α	2
В	3	С	3	В	3
С	4	D	4	С	4
D	5	E	5	D	5
E	6	F	6	E	6
F	7	G	7	F	7
G	8			G	8
Evaluation	Pending	Evaluation	Pending	Evaluation Pending	
No Longer Required		No Longer Required		No Longe	r Required
No Known or Suspected Explosive Hazard No Known or Suspected CWM Hazard			No Known or Susp	pected MC Hazard	
MRS PRIORITY or ALTERNATIVE MRS RATING				;	3

Table A

MRS Background Information

DIRECTIONS: Record the background information below for the MRS to be evaluated. Much of this information is available from Service and DoD databases. If the MRS is located on a FUDS property, the suitable FUDS property information should be substituted. In the MRS Summary, briefly describe the UXO, DMM, or MC that are known or suspected to be present, the exposure setting (the MRS's physical environment), any other incidental nonmunitions-related contaminants (e.g., benzene, trichloroethylene) found at the MRS, and any potentially exposed human and ecological receptors. If possible, include a map of the MRS.

Mui	nitions Response Si	te Name: Training Are	ea 7				
	Munitions Response Site Name: <u>Training Area 7</u> Component: Active Army						
	•	me: Joliet Army Amm	nunition Plan	t			
		State): Wilmington, V					
Poi	nt of Contact/Phone	No.: Art Holz; 815-42	23-2870				
Site	Name/Project Name	e (Project No.): JAAF	P-003-R-01_				
MR	SPP Score (Date Sco	ored): <u>14 August 200</u> 9	9				
Pre	parer's Name (Orga	nization): <u>Andrew Ma</u>	ly (USAEC)				
MR:	SPP Rating: No know	vn or suspected haza	rd				
sou Poi Pro	rces within the Joliet Ant of Contact (Name ject Phase (check of PA	AAP Administrative Re/Phone): Andrew Malenly one): SI RIP	ecord.		□ FS ✓ RC	this scoring was obtain	ned from
Med	dia Evaluated (check	call that apply):					
✓ Groundwater □ Sediment (human receptor)							
	✓ Surface soil □ Surface Water (ecological receptor)						
	☐ Sediment (ecolog	ical receptor)		□ Surfa	ce Water (huma	n receptor)	
MD	C Cummonu						

MRS Summary:

MRS Description: Describe the munitions-related activities that occurred at the installation, the dates of operation, and the UXO, DMM, or MC known or suspected to be present. When possible, identify munitions, CWM, and MC by type: Ammunition manufacturing, load, assemble, and packaging occurred between 1941 and 1977. The plant made many types of munitions, including ICM and up to 8-inch Howitzer HE projectiles. This MRS was a maneuver training area where pyrotechnics and blank, small-caliber rounds may have been used (HRR Addendum, 2008—Section 2).

Table A

MRS Background Information

DIRECTIONS: Record the background information below for the MRS to be evaluated. Much of this information is available from Service and DoD databases. If the MRS is located on a FUDS property, the suitable FUDS property information should be substituted. In the MRS Summary, briefly describe the UXO, DMM, or MC that are known or suspected to be present, the exposure setting (the MRS's physical environment), any other incidental nonmunitions-related contaminants (e.g., benzene, trichloroethylene) found at the MRS, and any potentially exposed human and ecological receptors. If possible, include a map of the MRS.

Description of Pathways for Human and Ecological Receptors: None at this site.

Description of Receptors (Human and Ecological): None at this site.

EHE Module: Munitions Type Data Element Table

DIRECTIONS: Below are 11 classifications of munitions and their descriptions. Circle the scores that correspond with <u>all</u> the munitions types known or suspected to be present at the MRS.

Note: The terms *practice munitions*, *small arms ammunition*, *physical evidence*, and *historical evidence* are defined in Appendix C of the Primer.

Classification	Description	Score
Sensitive	 UXO that are considered most likely to function upon any interaction with exposed persons (e.g., submunitions, 40mm high-explosive [HE] grenades, white phosphorus [WP] munitions, high-explosive antitank [HEAT] munitions, and practice munitions with sensitive fuzes, but excluding all other practice munitions). Hand grenades containing energetic filler. Bulk primary explosives, or mixtures of these with environmental media, such that the mixture poses an explosive hazard. 	30
High explosive (used or damaged)	 UXO containing a high-explosive filler (e.g., RDX, Composition B), that are not considered "sensitive." DMM containing a high-explosive filler that have: Been damaged by burning or detonation Deteriorated to the point of instability. 	25
Pyrotechnic (used or damaged)	 UXO containing a pyrotechnic filler other than white phosphorus (e.g., flares, signals, simulators, smoke grenades). DMM containing a pyrotechnic filler other than white phosphorus (e.g., flares, signals, simulators, smoke grenades) that have: Been damaged by burning or detonation Deteriorated to the point of instability. 	20
High explosive (unused)	 DMM containing a high-explosive filler that: Have not been damaged by burning or detonation Are not deteriorated to the point of instability. 	15
Propellant	 UXO containing mostly single-, double-, or triple-based propellant, or composite propellants (e.g., a rocket motor). DMM containing mostly single-, double-, or triple-based propellant, or composite propellants (e.g., a rocket motor) that are: Damaged by burning or detonation Deteriorated to the point of instability. 	15
Bulk secondary high explosives, pyrotechnics, or propellant	 DMM containing mostly single-, double-, or triple-based propellant, or composite propellants (e.g., a rocket motor). DMM that are bulk secondary high explosives, pyrotechnic compositions, or propellant (not contained in a munition), or mixtures of these with environmental media such that the mixture poses an explosive hazard. 	10
Pyrotechnic (not used or damaged)	 DMM containing a pyrotechnic filler (i.e., red phosphorus), other than white phosphorus filler, that: Have not been damaged by burning or detonation Are not deteriorated to the point of instability. 	10
Practice	 UXO that are practice munitions that are not associated with a sensitive fuze. DMM that are practice munitions that are not associated with a sensitive fuze and that have not: Been damaged by burning or detonation Deteriorated to the point of instability. 	5
Riot control	UXO or DMM containing a riot control agent filler (e.g., tear gas).	3
Small arms	 Used munitions or DMM that are categorized as small arms ammunition. (Physical evidence or historical evidence that no other types of munitions [e.g., grenades, subcaliber training rockets, demolition charges] were used or are present on the MRS is required for selection of this category.) 	2
Evidence of no munitions	 Following investigation of the MRS, there is physical evidence that there are no UXO or DMM present, or there is historical evidence indicating that no UXO or DMM are present. 	(0)
MUNITIONS TYPE	DIRECTIONS: Record <u>the single highest score</u> from above in the box to the right (maximum score = 30).	0

EHE Module: Munitions Type Data Element Table

DIRECTIONS: Below are 11 classifications of munitions and their descriptions. Circle the scores that correspond with all

the munitions types known or suspected to be present at the MRS.

Note: The terms practice munitions, small arms ammunition, physical evidence, and historical evidence are defined in

Appendix C of the Primer.

Classification Description Score

DIRECTIONS: Document any MRS-specific data used in selecting the *Munitions Type* classifications in the space

provided.

The SI field work for this site was conducted in November 2004. No MEC was found and no MC were detected above the RGs from the June 2004 ROD. Training Area 7 is not considered to have any sources for exposure pathways. A teleconference held in March 2005 to discuss findings of the field work and the Army, EPA, and IEPA concluded that based on the goals of the SI and the findings of the site walk, no further investigation was necessary for this site (SI Report, 2005—Section 4.3).

Tables 2—9

EHE Module: Source of Hazard Data Element Table

DIRECTIONS: Below are 11 classifications describing sources of explosive hazards. Circle the scores that correspond with <u>all</u> the sources of explosive hazards known or suspected to be present at the MRS.

Note: The terms former range, practice munitions, small arms range, physical evidence, and historical evidence are defined in Appendix C of the Primer.

DIRECTIONS: Document any MRS-specific data used in selecting the **Source of Hazard** classifications in the space provided.

It was determined that nor further investigation was necessary for this site. Therefore, Tables 2 through 9 have been intentionally omitted according to Active Army guidance.

Table 10Determining the EHE Module Rating

DIRECTIONS:

- 1. From Tables 1–9, record the data element scores in the **Score** boxes to the right.
- Add the **Score** boxes for each of the three factors and record this number in the **Value** boxes to the right.
- Add the three Value boxes and record this number in the EHE Module Total box below.
- 4. Circle the appropriate range for the **EHE Module Total** below.
- 5. Circle the **EHE Module Rating** that corresponds to the range selected and record this value in the **EHE Module Rating** box found at the bottom of the table.

Note:

An alternative module rating may be assigned when a module letter rating is inappropriate. An alternative module rating is used when more information is needed to score one or more data elements, contamination at an MRS was previously addressed, or there is no reason to suspect contamination was ever present at an MRS.

	Source	Score	value				
Explosive Hazard Factor Data Elements							
Munitions Type	Table 1	0	0				
Source of Hazard	Table 2		U				
Accessibility Factor Data Elements							
Location of Munitions	Table 3						
Ease of Access	Table 4						
Status of Property	Table 5						
Receptor Factor Data Elements							
Population Density	Table 6						
Population Near Hazard	Table 7						
Types of Activities/Structures	Table 8						
Ecological and/or Cultural Resources	Table 9						
EHE	MODULE	E TOTAL					
EHE Module Total	EHE	Module R	ating				
92 to 100		Α					
82 to 91		В					
71 to 81		С					
60 to 70		D					
48 to 59		E					
38 to 47		F					
less than 38	G						
	Evaluation Pending						
Alternative Module Ratings	No Longer Required						
	No Known or Suspected Explosive Hazard						
EHE MODULE RATING NO KNOWN OR SUSPEC							

Source

Score

Value

CHE Module: CWM Configuration Data Element Table

DIRECTIONS: Below are seven classifications of CWM configuration and their descriptions. Circle the scores that

correspond with <u>all</u> the CWM configurations known or suspected to be present at the MRS. **Note:** The terms *CWM/UXO*, *CWM/DMM*, *physical evidence*, and *historical evidence* are defined in Appendix C of the

Primer.

Classification	Description	Score
CWM, that are either UXO, or explosively configured damaged DMM	 The CWM known or suspected of being present at the MRS are: CWM that are UXO (i.e., CWM/UXO) Explosively configured CWM that are DMM (i.e., CWM/DMM) that have been damaged. 	30
CWM mixed with UXO	The CWM known or suspected of being present at the MRS are undamaged CWM/DMM or CWM not configured as a munition that are commingled with conventional munitions that are UXO.	25
CWM, explosive configuration that are undamaged DMM	The CWM known or suspected of being present at the MRS are explosively configured CWM/DMM that have not been damaged.	20
CWM/DMM, not explosively configured or CWM, bulk container	 The CWM known or suspected of being present at the MRS are: Nonexplosively configured CWM/DMM either damaged or undamaged Bulk CWM (e.g., ton container). 	15
CAIS K941 and CAIS K942	The CWM/DMM known or suspected of being present at the MRS are CAIS K941-toxic gas set M-1 or CAIS K942-toxic gas set M-2/E11.	12
CAIS (chemical agent identification sets)	CAIS, other than CAIS K941 and K942, are known or suspected of being present at the MRS.	10
Evidence of no CWM	Following investigation, the physical evidence indicates that CWM are not present at the MRS, or the historical evidence indicates that CWM are not present at the MRS.	0
CWM CONFIGURATION	DIRECTIONS: Record <u>the single highest score</u> from above in the box to the right (maximum score = 30).	0

DIRECTIONS: Document any MRS-specific data used in selecting the *CWM Configuration* classifications in the space provided.

The historical use of the site did not include CWM (HRR, 2005—Section 4.5.3). In addition, a visual survey of 10% of the site was completed from 15-18 November 2004 and no evidence of CWM was found (SI Report, 2005—Section 4.3).

Tables 12 - 19

CHE Module: Sources of CWM Data Element Table

DIRECTIONS: Below are 11 sources of CWM hazards and their descriptions. Review these classifications and circle

the scores that correspond with all the sources of CWM hazards known or suspected to be present at

the MRS.

Note: The terms CWM/UXO, CWM/DMM, CAIS/DMM, surface, subsurface, physical evidence, and historical evidence

are defined in Appendix C of the Primer.

Classification Description Score

No known or suspected CWM hazard is expected at this site. Therefore, Tables 12 through 19 have been intentionally omitted according to Active Army Guidance.

Table 20 Determining the CHE Module Rating

DIRECTIONS:

- 1. From Tables 11–19, record the data element scores in the **Score** boxes to the right.
- Add the **Score** boxes for each of the three factors and record this number in the **Value** boxes to the right.
- Add the three Value boxes and record this number in the CHE Module Total box below.
- 4. Circle the appropriate range for the **CHE Module Total** below.
- 5. Circle the **CHE Module Rating** that corresponds to the range selected and record this value in the **CHE Module Rating** box found at the bottom of the table.

Note:

An alternative module rating may be assigned when a module letter rating is inappropriate. An alternative module rating is used when more information is needed to score one or more data elements, contamination at an MRS was previously addressed, or there is no reason to suspect contamination was ever present at an MRS.

ig the One Moddle Rating	Source	Score	Value
CWM Hazard Factor Data Elemer	nts		
CWM Configuration	Table 11	0	0
Sources of CWM	Table 12	-	0
Accessibility Factor Data Elemer	nts		
Location of CWM	Table 13		
Ease of Access	Table 14	-	
Status of Property	Table 15		
Receptor Factor Data Elements			
Population Density	Table 16		
Population Near Hazard	Table 17	-	
Types of Activities/Structures	Table 18		
Ecological and/or Cultural Resources	Table 19		
CHE	MODULE	TOTAL	0
CHE Module Total	CHE	Module R	ating
92 to 100		Α	
82 to 91		В	
71 to 81		С	
60 to 70		D	
48 to 59		Е	
38 to 47		F	
less than 38		G	
	Evaluation Pending		
Alternative Module Ratings	No Longer Required		
	No Know	n or Suspec Hazard	ted CWM
CHE MODULE RATING	NO KNOWN OR SUSPECTED CWM HAZARD		

HHE Module: Groundwater Data Element Table

Contaminant Hazard Factor (CHF)

DIRECTIONS: Record the maximum concentrations of all contaminants in the MRS's groundwater and their comparison values (from Appendix B of the Primer) in the table below. Additional contaminants can be recorded on Table 27. Calculate and record the ratios for each contaminant by dividing the maximum concentration by the comparison value. Determine the CHF by adding the contaminant ratios together, including any additional groundwater contaminants recorded on Table 27. Based on the CHF, use the CHF Scale to determine and record the CHF Value. If there is no known or suspected MC hazard present in the groundwater, select the box at the bottom of the table.

Contaminant	Maximum Concentration (μg/L)	Comparison Value (μg/L)	Ratios		
CHF Scale	CHF Value	Sum The Ratios			
CHF > 100	H (High)	Maximum Concentration of Co	ontaminantl		
100 > CHF > 2	M (Medium)	CHF = [Maximum Concentration of Concentr			
2 > CHF	L (Low)	[Comparison Value for Conta	iminantj		
CONTAMINANT HAZARD FACTOR	DIRECTIONS: Record the CHF Value (maximum value = H).	from above in the box to the right			
DIRECTIONS: Circle to	Migratory Pathw he value that corresponds most closely to	ray Factor the groundwater migratory pathway at the l	MRS.		
Classification	Des	cription	Value		
Evident	Analytical data or observable evidence indicates moving toward, or has moved to a point of expos	that contamination in the groundwater is present at, ure.	Н		
Potential	Contamination in groundwater has moved only slightly beyond the source (i.e., tens of feet), could move but is not moving appreciably, or information is not sufficient to make a determination of Evident or Confined.				
Confined	Information indicates a low potential for contaminant migration from the source via the groundwater to a potential point of exposure (possibly due to the presence of geological structures or physical controls).				
MIGRATORY PATHWAY FACTOR	DIRECTIONS: Record <u>the single highest value</u> from above in the box to the right (maximum value = H).				
DIRECTIONS: Circle to	Receptor Face value that corresponds most closely to				
Classification	Des	cription	Value		
Identified	There is a threatened water supply well downgradient of the source and the groundwater is a current source of drinking water or source of water for other beneficial uses such as irrigation/agriculture (equivalent to Class I or IIA aquifer).				
Potential	There is no threatened water supply well downgradient of the source and the groundwater is currently or potentially usable for drinking water, irrigation, or agriculture (equivalent to Class I, IIA, or IIB aquifer).				
Limited	There is no potentially threatened water supply well downgradient of the source and the groundwater is not considered a potential source of drinking water and is of limited beneficial use (equivalent to Class IIIA or IIIB aquifer, or where perched aquifer exists only).				
RECEPTOR FACTOR	DIRECTIONS: Record the single high right (maximum value =	nest value from above in the box to the = H).			
	No Kno	wn or Suspected Groundwater MC Hazard	X		

HHE Module: Surface Water - Human Endpoint Data Element Table

Contaminant Hazard Factor (CHF)

DIRECTIONS: Record the maximum concentrations of all contaminants in the MRS's surface water and their comparison values (from Appendix B of the Primer) in the table below. Additional contaminants can be recorded on Table 27. Calculate and record the ratios for each contaminant by dividing the maximum concentration by the comparison value. Determine the CHF by adding the contaminant ratios together, including any additional surface water contaminants recorded on Table 27. Based on the CHF, use the CHF Scale to determine and record the CHF Value. If there is no known or suspected MC hazard with human endpoints present in the surface water, select the box at the bottom of the table.

Contaminant	Maximum Concentration (μg/L)	Comparison Value (μg/L)	Ratios	
CHF Scale	CHF Value	Sum The Ratios		
CHF > 100	H (High)	IManimum Cananatation of C	(
100 > CHF > 2	M (Medium)	CHF = [Maximum Concentration of Co	ontaminantj	
2 > CHF	L (Low)	[Comparison Value for Conta	minant]	
CONTAMINANT HAZARD FACTOR	DIRECTIONS: Record the CHF Value (maximum value = H).	from above in the box to the right		
DIRECTIONS: Circle t	Migratory Pathw the value that corresponds most closely to	ray Factor to the surface water migratory pathway at the	MRS.	
Classification	Description			
Evident	Analytical data or observable evidence indicates that contamination in the surface water is present at, moving toward, or has moved to a point of exposure.			
Potential	Contamination in surface water has moved only slightly beyond the source (i.e., tens of feet), could move but is not moving appreciably, or information is not sufficient to make a determination of Evident or Confined.			
Confined	Information indicates a low potential for contaminant migration from the source via the surface water to a potential point of exposure (possibly due to the presence of geological structures or physical controls).			
MIGRATORY PATHWAY FACTOR	DIRECTIONS: Record <u>the single highest value</u> from above in the box to the right (maximum value = H).			
	· · ·	the surface water receptors at the MRS.		
Classification		cription	Value	
Identified	Identified receptors have access to surface water	to which contamination has moved or can move.	Н	
Potential	Potential for receptors to have access to surface water to which contamination has moved or can move.			
Limited	Little or no potential for receptors to have access to surface water to which contamination has moved or can move.			
RECEPTOR FACTOR	DIRECTIONS: Record the single high the right (maximum value)			

No Known or Suspected Surface Water (Human Endpoint) MC Hazard

 \times

HHE Module: Sediment – Human Endpoint Data Element Table

Contaminant Hazard Factor (CHF)

FACTOR

DIRECTIONS: Record the **maximum concentrations** of all contaminants in the MRS's sediment and their **comparison** values (from Appendix B of the Primer) in the table below. Additional contaminants can be recorded on Table 27. Calculate and record the ratios for each contaminant by dividing the maximum concentration by the comparison value. Determine the CHF by adding the contaminant ratios together, including any additional sediment contaminants recorded on Table 27. Based on the CHF, use the CHF Scale to determine and record the CHF Value. If there is no known or suspected MC hazard with human endpoints present in the sediment, select the box at the bottom of the table

with nu	man endpoints present in the sediment, s	select the box at the bottom of the table.			
Contaminant	Maximum Concentration (mg/kg)	Comparison Value (mg/kg)	Ratios		
CHF Scale	CHF Value	Sum The Ratios			
CHF > 100	H (High)	- Maximum Concentration of Co	ontaminantl		
100 > CHF > 2	M (Medium)	CHF = [Maximum Concentration of Concentr	· /		
2 > CHF	L (Low)	[Comparison Value for Conta	iminantj		
CONTAMINANT HAZARD FACTOR	DIRECTIONS: Record the CHF Value maximum value = H).	from above in the box to the right			
Migratory Pathway Factor DIRECTIONS: Circle the value that corresponds most closely to the sediment migratory pathway at the MRS.					
Classification		cription	Value		
Evident	Analytical data or observable evidence indicates that contamination in the sediment is present at, moving toward, or has moved to a point of exposure.				
Potential	Contamination in sediment has moved only slightly beyond the source (i.e., tens of feet), could move but is not moving appreciably, or information is not sufficient to make a determination of Evident or Confined.				
Confined	Information indicates a low potential for contaminant migration from the source via the sediment to a potential point of exposure (possibly due to the presence of geological structures or physical controls).				
MIGRATORY PATHWAY FACTOR	DIRECTIONS: Record the single high right (maximum value =				
DIRECTIONS: Circle the	Receptor For the value that corresponds most closely to				
Classification Description					
Identified	Identified receptors have access to sediment to v	which contamination has moved or can move.	Н		
Potential	Potential for receptors to have access to sedimen	М			
Limited	Little or no potential for receptors to have access can move.	to sediment to which contamination has moved or	L		
RECEPTOR	DIRECTIONS: Record the single high	nest value from above in the box to			

the right (maximum value = H).

No Known or Suspected Sediment (Human Endpoint) MC Hazard

 \boxtimes

HHE Module: Surface Water - Ecological Endpoint Data Element Table

Contaminant Hazard Factor (CHF)

DIRECTIONS: Record the maximum concentrations of all contaminants in the MRS's surface water and their comparison values (from Appendix B of the Primer) in the table below. Additional contaminants can be recorded on Table 27. Calculate and record the ratios for each contaminant by dividing the maximum concentration by the comparison value. Determine the CHF by adding the contaminant ratios together, including any additional surface water contaminants recorded on Table 27. Based on the CHF, use the CHF Scale to determine and record the CHF Value. If there is no known or suspected MC hazard with ecological endpoints present in the surface water, select the box at the bottom of the table.

Contaminant	Maximum Concentration (μg/L)	Comparison Value (μg/L)	Ratios	
CHF Scale	CHF Value	Sum the Ratios		
CHF > 100	H (High)	— Maximum Cancontration of Co	ontominant]	
100 > CHF > 2	M (Medium)	CHF = [Maximum Concentration of Co		
2 > CHF	L (Low)	[Comparison Value for Conta	minantj	
CONTAMINANT HAZARD FACTOR	DIRECTIONS: Record the CHF Value (maximum value = H).	from above in the box to the right		
DIRECTIONS: Circle to	Migratory Pathw he value that corresponds most closely to	ray Factor the surface water migratory pathway at the	MRS.	
Classification	Description			
Evident	Analytical data or observable evidence indicates that contamination in the surface water is present at, moving toward, or has moved to a point of exposure.			
Potential	Contamination in surface water has moved only slightly beyond the source (i.e., tens of feet), could move but is not moving appreciably, or information is not sufficient to make a determination of Evident or Confined.			
Confined	Information indicates a low potential for contaminant migration from the source via the surface water to a potential point of exposure (possibly due to the presence of geological structures or physical controls).			
MIGRATORY PATHWAY FACTOR	DIRECTIONS: Record the single high right (maximum value =	nest value from above in the box to the = H).		
	, , , , , , , , , , , , , , , , , , ,	the surface water receptors at the MRS.		
Classification		cription	Value	
ldentified	identified receptors have access to surface water	r to which contamination has moved or can move.	Н	
Potential	Potential for receptors to have access to surface water to which contamination has moved or can move.			
Limited	Little or no potential for receptors to have access or can move.	to surface water to which contamination has moved	L	
RECEPTOR FACTOR	DIRECTIONS: Record the single high right (maximum value =	nest value from above in the box to the = H).		
	No Known or Suspected Surface	ce Water (Ecological Endpoint) MC Hazard	X	

HHE Module: Sediment - Ecological Endpoint Data Element Table

Contaminant Hazard Factor (CHF)

DIRECTIONS: Record the maximum concentrations of all contaminants in the MRS's sediment and their comparison values (from Appendix B of the Primer) in the table below. Additional contaminants can be recorded on Table 27. Calculate and record the ratios for each contaminant by dividing the maximum concentration by the comparison value. Determine the CHF by adding the contaminant ratios together, including any additional sediment contaminants recorded on Table 27. Based on the CHF, use the CHF Scale to determine and record the CHF Value. If there is no known or suspected MC hazard with ecological endpoints present in the sediment, select the box at the bottom of the table.

Contaminant	Maximum Concentration (mg/kg)	Comparison Value (mg/kg)	Ratios	
CHF Scale	CHF Value	Sum the Ratios		
CHF > 100	H (High)	— [Maximum Concentration of Co	ontaminantl	
100 > CHF > 2	M (Medium)	CHF = [Maximum Concentration of Co	i	
2 > CHF	L (Low)	[Comparison Value for Conta	minant]	
CONTAMINANT HAZARD FACTOR	DIRECTIONS: Record the CHF Valu (maximum value = H).			
DIRECTIONS: Circle the	Migratory Path he value that corresponds most closely	way Factor to the sediment migratory pathway at the MRS	S.	
Classification	Description			
Evident	Analytical data or observable evidence indicates that contamination in the sediment is present at, moving toward, or has moved to a point of exposure.			
Potential	Contamination in sediment has moved only slightly beyond the source (i.e., tens of feet), could move but is not moving appreciably, or information is not sufficient to make a determination of Evident or Confined.			
Confined	Information indicates a low potential for contaminant migration from the source via the sediment to a potential point of exposure (possibly due to the presence of geological structures or physical controls).			
MIGRATORY PATHWAY FACTOR	DIRECTIONS: Record the single highest value from above in the box to the right (maximum value = H).			
DIDECTIONS: Circle 4	Receptor I			
	he value that corresponds most closely	·		
Classification		scription	Value	
Identified	Identified receptors have access to sediment to which contamination has moved or can move.			
Potential	Potential for receptors to have access to sediment to which contamination has moved or can move.			
Limited	Little or no potential for receptors to have access to sediment to which contamination has moved or can move.			
RECEPTOR FACTOR	DIRECTIONS: Record the single hig right (maximum value	thest value from above in the box to the = H).		

No Known or Suspected Sediment (Ecological Endpoint) MC Hazard

 \times

HHE Module: Surface Soil Data Element Table

Contaminant Hazard Factor (CHF)

DIRECTIONS: Record the maximum concentrations of all contaminants in the MRS's surface soil and their comparison values (from Appendix B of the Primer) in the table below. Additional contaminants can be recorded on Table 27. Calculate and record the ratios for each contaminant by dividing the maximum concentration by the comparison value. Determine the CHF by adding the contaminant ratios together, including any additional surface soil contaminants recorded on Table 27. Based on the CHF, use the CHF Scale to determine and record the CHF Value. If there is no known or suspected MC hazard present in the surface soil, select the box at the bottom of the table.

Contaminant	Maximum Concentration (mg/kg)	Comparison Value (mg/kg)	Ratio	
CHF Scale	CHF Value	Sum the Ratios		
CHF > 100	H (High)	— Maximum Concentration of Co	ntaminantl	
100 > CHF > 2	M (Medium)	CHF = [Maximum Concentration of Con		
2 > CHF	L (Low)	[Comparison Value for Contar	ninant]	
CONTAMINANT HAZARD FACTOR	DIRECTIONS: Record the CHF Value (maximum value = H			
	Migratory Path	nway Factor		
DIRECTIONS: Circle the		to the surface soil migratory pathway at the M	RS.	
Classification	Description			
Evident	Analytical data or observable evidence indicates that contamination in the surface soil is present at, moving toward, or has moved to a point of exposure.			
Potential	Contamination in surface soil has moved only slightly beyond the source (i.e., tens of feet), could move but is not moving appreciably, or information is not sufficient to make a determination of Evident or Confined.			
Confined	Information indicates a low potential for contaminant migration from the source via the surface soil to a potential point of exposure (possibly due to the presence of geological structures or physical controls).			
MIGRATORY PATHWAY FACTOR	DIRECTIONS: Record the single highest value from above in the box to the right (maximum value = H).			
	Receptor	Factor_		
DIRECTIONS: Circle the	he value that corresponds most closely	to the surface soil receptors at the MRS.		
Classification		escription	Value	
Identified	Identified receptors have access to surface so	il to which contamination has moved or can move.	Н	
Potential	Potential for receptors to have access to surface soil to which contamination has moved or can move.			
Limited	Little or no potential for receptors to have acceran move.	ess to surface soil to which contamination has moved or	L	
RECEPTOR FACTOR	DIRECTIONS: Record the single hi right (maximum value	ighest value from above in the box to the e = H).		

No Known or Suspected Surface Soil MC Hazard



HHE Module: Supplemental Contaminant Hazard Factor Table

Contaminant Hazard Factor (CHF)

DIRECTIONS: Only use this table if there are more than five contaminants in any given medium present at the

MRS. This is a supplemental table designed to hold information about contaminants that do not fit in the previous tables. Indicate the **media** in which these contaminants are present. Then record all **contaminants**, their **maximum concentrations** and their **comparison values** (from Appendix B of the Primer) in the table below. Calculate and record the **ratio** for each contaminant by dividing the **maximum concentration** by the **comparison value**. Determine the **CHF** for each medium on the appropriate media-specific tables.

Note: Do not add ratios from different media.

Media	Contaminant	Maximum Concentration	Comparison Value	Ratio

Table 28 Determining the HHE Module Rating

DIRECTIONS:

- 1. Record the letter values (H, M, L) for the **Contaminant Hazard**, **Migration Pathway**, and **Receptor Factors** for the media (from Tables 21–26) in the corresponding boxes below.
- 2. Record the media's three-letter combinations in the **Three-Letter Combination** boxes below (three-letter combinations are arranged from Hs to Ms to Ls).
- 3. Using the **HHE Ratings** provided below, determine each media's rating (A–G) and record the letter in the corresponding **Media Rating** box below.

Media (Source)	Contaminant Hazard Factor Value	Migratory Pathway Factor Value	Receptor Factor Value	Three-Letter Combination (Hs-Ms-Ls)	Media Rating (A-G)
Groundwater (Table 21)					
Surface Water/Human Endpoint (Table 22)					
Sediment/Human Endpoint (Table 23)					
Surface Water/Ecological Endpoint (Table 24)					
Sediment/Ecological Endpoint (Table 25)					
Surface Soil (Table 26)					

DIRECTIONS (cont.):

4. Select the single highest Media Rating (A is highest; G is lowest) and enter the letter in the **HHE Module Rating** box.

Note:

An alternative module rating may be assigned when a module letter rating is inappropriate. An alternative module rating is used when more information is needed to score one or more media, contamination at an MRS was previously addressed, or there is no reason to suspect contamination was ever present at an MRS.

HHE MODULE RATING

HHE Ratings (for reference only)					
Combination	Rating				
ННН	Α				
ННМ	В				
HHL					
НММ	С				
HML					
MMM	D				
HLL	_				
MML	Е				
MLL	F				
LLL	G				
	Evaluation Pending				
Alternative Module Ratings	No Longer Required				
/ itemative module ratings	No Known or Suspected MC Hazard				

Table 29 **MRS Priority**

DIRECTIONS: In the chart below, circle the letter rating for each module recorded in Table 10 (EHE), Table 20 (CHE), and Table 28 (HHE). Circle the corresponding numerical priority for each module. If information to determine the module rating is not available, choose the appropriate alternative module rating. The MRS Priority is the single highest priority; record this relative priority in the MRS Priority or Alternative MRS Rating at the bottom of the table.

Note: An MRS assigned Priority 1 has the highest relative priority; an MRS assigned Priority 8 has the lowest relative priority. Only an MRS with CWM known or suspected to be present can be assigned Priority 1; an MRS that has CWM known or suspected to be present cannot be assigned Priority 8.

EHE Rating	Priority	CHE Rating	Priority	HHE Rating	Priority
		A 1		-	
Α	2	В	2	Α	2
В	3	С	3	В	3
С	4	D	4	С	4
D	5	E	5	D	5
E	6	F	6	E	6
F	7	G	7	F	7
G	8			G	8
Evaluation Pending		Evaluation Pending		Evaluation Pending No Longer Required	
No Longer Required No Longer Required No Known or Suspected Explosive Hazard				No Known or Susp	pected MC Hazard
MRS PRIORITY or ALTERNATIVE MRS RATING				NO KNOWN OI HAZ	

Table A

MRS Background Information

DIRECTIONS: Record the background information below for the MRS to be evaluated. Much of this information is available from Service and DoD databases. If the MRS is located on a FUDS property, the suitable FUDS property information should be substituted. In the MRS Summary, briefly describe the UXO, DMM, or MC that are known or suspected to be present, the exposure setting (the MRS's physical environment), any other incidental nonmunitions-related contaminants (e.g., benzene, trichloroethylene) found at the MRS, and any potentially exposed human and ecological receptors. If possible, include a map of the MRS.

Munitions Response Site Name: Former Burning Area (L34)						
Component: Active Army						
Installation/Property Name: Joliet Ar	my Ammunition Plan	t				
$\textbf{Location (City, County, State): } \underline{\textbf{Wilm}}$	<u>ington, Will County, I</u>	llinois				
Point of Contact/Phone No.: Art Holz	z; 815-423-2870					
Site Name/Project Name (Project No	o.): <u>JAAP-004-R-01</u>					
MRSPP Score (Date Scored): 14 Aug	gust 2009					
Preparer's Name (Organization): An	drew Maly (USAEC)					
MRSPP Rating: No known or suspect	ed hazard					
Date Information Entered/Updated: 14 August 2009; Information contained within this scoring was obtained from sources within the Joliet AAP Administrative Record. Point of Contact (Name/Phone): Andrew Maly, 410.436.1611 Project Phase (check only one): RI FS RD RA-C RIP RA-O RC ✓ LTM						
Media Evaluated (check all that apply): ✓ Groundwater □ Sediment (human receptor) ✓ Surface soil □ Surface Water (ecological receptor) □ Sediment (ecological receptor) □ Surface Water (human receptor)						
MDS Summonu	MDO O					

MRS Summary:

MRS Description: Describe the munitions-related activities that occurred at the installation, the dates of operation, and the UXO, DMM, or MC known or suspected to be present. When possible, identify munitions, CWM, and MC by type:

Ammunition manufacturing, load, assemble, and packaging occurred between 1941 and 1977. The plant made many types of munitions, including ICM and up to 8-inch Howitzer HE projectiles. The remedial action completed in 2007 found no evidence of MEC (HRR Addendum, 2008—Section 2).

Table A

MRS Background Information

DIRECTIONS: Record the background information below for the MRS to be evaluated. Much of this information is available from Service and DoD databases. If the MRS is located on a FUDS property, the suitable FUDS property information should be substituted. In the MRS Summary, briefly describe the UXO, DMM, or MC that are known or suspected to be present, the exposure setting (the MRS's physical environment), any other incidental nonmunitions-related contaminants (e.g., benzene, trichloroethylene) found at the MRS, and any potentially exposed human and ecological receptors. If possible, include a map of the MRS.

Description of Pathways for Human and Ecological Receptors:

Soil is considered to be a complete pathway for Human and Ecological Receptors. Current soil data has been input into this site evaluation.

Description of Receptors (Human and Ecological):

Human access to the site is limited. The only threatened or endangered species potentially inhabiting JOAAP are grassland birds including bobolinks, upland sandpipers, and Henslow's sparrows (SI Addendum, 2009-Section 4.1.4.4.3).

EHE Module: Munitions Type Data Element Table

DIRECTIONS: Below are 11 classifications of munitions and their descriptions. Circle the scores that correspond with <u>all</u> the munitions types known or suspected to be present at the MRS.

Note: The terms *practice munitions, small arms ammunition, physical evidence,* and *historical evidence* are defined in Appendix C of the Primer.

Classification	Description	Score
Sensitive	 UXO that are considered most likely to function upon any interaction with exposed persons (e.g., submunitions, 40mm high-explosive [HE] grenades, white phosphorus [WP] munitions, high-explosive antitank [HEAT] munitions, and practice munitions with sensitive fuzes, but excluding all other practice munitions). Hand grenades containing energetic filler. Bulk primary explosives, or mixtures of these with environmental media, such that the mixture poses an explosive hazard. 	30
High explosive (used or damaged)	 UXO containing a high-explosive filler (e.g., RDX, Composition B), that are not considered "sensitive." DMM containing a high-explosive filler that have: Been damaged by burning or detonation Deteriorated to the point of instability. 	25
Pyrotechnic (used or damaged)	 UXO containing a pyrotechnic filler other than white phosphorus (e.g., flares, signals, simulators, smoke grenades). DMM containing a pyrotechnic filler other than white phosphorus (e.g., flares, signals, simulators, smoke grenades) that have: Been damaged by burning or detonation Deteriorated to the point of instability. 	20
High explosive (unused)	DMM containing a high-explosive filler that:	15
Propellant	 UXO containing mostly single-, double-, or triple-based propellant, or composite propellants (e.g., a rocket motor). DMM containing mostly single-, double-, or triple-based propellant, or composite propellants (e.g., a rocket motor) that are: Damaged by burning or detonation Deteriorated to the point of instability. 	15
Bulk secondary high explosives, pyrotechnics, or propellant	 DMM containing mostly single-, double-, or triple-based propellant, or composite propellants (e.g., a rocket motor). DMM that are bulk secondary high explosives, pyrotechnic compositions, or propellant (not contained in a munition), or mixtures of these with environmental media such that the mixture poses an explosive hazard. 	10
Pyrotechnic (not used or damaged)	 DMM containing a pyrotechnic filler (i.e., red phosphorus), other than white phosphorus filler, that: Have not been damaged by burning or detonation Are not deteriorated to the point of instability. 	10
Practice	 UXO that are practice munitions that are not associated with a sensitive fuze. DMM that are practice munitions that are not associated with a sensitive fuze and that have not: Been damaged by burning or detonation Deteriorated to the point of instability. 	5
Riot control	UXO or DMM containing a riot control agent filler (e.g., tear gas).	3
Small arms	 Used munitions or DMM that are categorized as small arms ammunition. (Physical evidence or historical evidence that no other types of munitions [e.g., grenades, subcaliber training rockets, demolition charges] were used or are present on the MRS is required for selection of this category.) 	2
Evidence of no munitions	 Following investigation of the MRS, there is physical evidence that there are no UXO or DMM present, or there is historical evidence indicating that no UXO or DMM are present. 	$\left(\begin{array}{c} 0 \end{array}\right)$
MUNITIONS TYPE	DIRECTIONS: Record the single highest score from above in the box to the right (maximum score = 30).	0

EHE Module: Munitions Type Data Element Table

DIRECTIONS: Below are 11 classifications of munitions and their descriptions. Circle the scores that correspond with all

the munitions types known or suspected to be present at the MRS.

Note: The terms practice munitions, small arms ammunition, physical evidence, and historical evidence are defined in

Appendix C of the Primer.

Classification Description Score

DIRECTIONS: Document any MRS-specific data used in selecting the *Munitions Type* classifications in the space

provided.

The site was used for open burning of propellant and explosive waste. EODT performed a removal action for this area in 2001. The Ordnance Removal and Characterization Report indicates that 15 MEC scrap items consisting of ceramic and glass M5 mines and nose and base fuzes were found (one of which contained explosives); however, less than 10% of the site was cleared and UXO were considered likely to be present (SI Report, 2005—Section 4.4).

A removal action was conducted in 2007 by PIKA International and MKM. 3.5 acres of the site were cleared to 1' depth. No individual MEC items were discovered at the MRS during the RA (Draft Final Site-Specific Final Report MMRP Site L34, 2008).

Table 2—9

EHE Module: Source of Hazard Data Element Table

DIRECTIONS: Below are 11 classifications describing sources of explosive hazards. Circle the scores that correspond with <u>all</u> the sources of explosive hazards known or suspected to be present at the MRS.

Note: The terms former range, practice munitions, small arms range, physical evidence, and historical evidence are defined in Appendix C of the Primer.

DIRECTIONS: Document any MRS-specific data used in selecting the **Source of Hazard** classifications in the space provided.

No MEC items were discovered at the MRS during the RA (Draft Final Site-Specific Final Report MMRP Site L34, 2008). Therefore, Tables 2 through 9 have been intentionally omitted according to Active Army guidance.

Table 10Determining the EHE Module Rating

DIRECTIONS:

- From Tables 1–9, record the data element scores in the Score boxes to the right.
- 2. Add the **Score** boxes for each of the three factors and record this number in the **Value** boxes to the right.
- Add the three Value boxes and record this number in the EHE Module Total box below.
- 4. Circle the appropriate range for the **EHE Module Total** below.
- 5. Circle the **EHE Module Rating** that corresponds to the range selected and record this value in the **EHE Module Rating** box found at the bottom of the table.

Note:

An alternative module rating may be assigned when a module letter rating is inappropriate. An alternative module rating is used when more information is needed to score one or more data elements, contamination at an MRS was previously addressed, or there is no reason to suspect contamination was ever present at an MRS.

Explosive Hazard Factor Data Elements			
Munitions Type	Table 1	0	
Source of Hazard	Table 2		
Accessibility Factor Data Elemer	nts		
Location of Munitions	Table 3		
Ease of Access	Table 4		
Status of Property	Table 5		
Receptor Factor Data Elements			
Population Density	Table 6		
Population Near Hazard	Table 7		
Types of Activities/Structures	Table 8		
Ecological and/or Cultural Resources	Table 9		
EHE MODULE TOTAL			
EHE Module Total EHE Module Rating		ating	
92 to 100		Α	
82 to 91	В		
71 to 81		С	
60 to 70		D	
48 to 59	E		
38 to 47		F	
less than 38	G		
	Evaluation Pending		ding
Alternative Module Ratings	No Longer Required		
	No Known or Suspected Explosive Hazard		
EHE MODULE RATING NO KNOWN OR SUSPECTED EXPLOSIVE HAZARD			

Source

Score

Value

CHE Module: CWM Configuration Data Element Table

DIRECTIONS: Below are seven classifications of CWM configuration and their descriptions. Circle the scores that

Note: The terms CWM/UXO, CWM/DMM, physical evidence, and historical evidence are defined in Appendix C of the

correspond with <u>all</u> the CWM configurations known or suspected to be present at the MRS.

Primer.

Classification	Description	Score
CWM, that are either UXO, or explosively configured damaged DMM	 The CWM known or suspected of being present at the MRS are: CWM that are UXO (i.e., CWM/UXO) Explosively configured CWM that are DMM (i.e., CWM/DMM) that have been damaged. 	30
CWM mixed with UXO	The CWM known or suspected of being present at the MRS are undamaged CWM/DMM or CWM not configured as a munition that are commingled with conventional munitions that are UXO.	25
CWM, explosive configuration that are undamaged DMM	The CWM known or suspected of being present at the MRS are explosively configured CWM/DMM that have not been damaged.	20
CWM/DMM, not explosively configured or CWM, bulk container	 The CWM known or suspected of being present at the MRS are: Nonexplosively configured CWM/DMM either damaged or undamaged Bulk CWM (e.g., ton container). 	15
CAIS K941 and CAIS K942	The CWM/DMM known or suspected of being present at the MRS are CAIS K941-toxic gas set M-1 or CAIS K942-toxic gas set M-2/E11.	12
CAIS (chemical agent identification sets)	CAIS, other than CAIS K941 and K942, are known or suspected of being present at the MRS.	10
Evidence of no CWM	Following investigation, the physical evidence indicates that CWM are not present at the MRS, or the historical evidence indicates that CWM are not present at the MRS.	0
CWM CONFIGURATION	DIRECTIONS: Record <u>the single highest score</u> from above in the box to the right (maximum score = 30).	0

DIRECTIONS: Document any MRS-specific data used in selecting the *CWM Configuration* classifications in the space provided.

The historical use of the site did not include CWM (HRR, 2005—Section 4.4.3). In 1981, Donahue and Associates collected

samples on the site, and sampling again took place at the site in 1993 by Dames and Moore. EODT performed a removal action for this area in 2001. No CWM was found during these site investigations. Site clearance to 1' depth conducted in 2007 did not find any CWM (Draft Final Site-Specific Report MMRP Site L34, 2008).

Tables 12 - 19

CHE Module: Sources of CWM Data Element Table

DIRECTIONS: Below are 11 sources of CWM hazards and their descriptions. Review these classifications and circle

the scores that correspond with all the sources of CWM hazards known or suspected to be present at

the MRS.

Note: The terms CWM/UXO, CWM/DMM, CAIS/DMM, surface, subsurface, physical evidence, and historical evidence

are defined in Appendix C of the Primer.

Classification	Description	Score
Classification	Description	Sco

No known or suspected CWM hazard is expected at this site. Therefore, Tables 12 through 19 have been intentionally omitted according to Active Army Guidance.

Table 20 Determining the CHE Module Rating

DIRECTIONS:

- From Tables 11–19, record the data element scores in the Score boxes to the right.
- Add the **Score** boxes for each of the three factors and record this number in the **Value** boxes to the right.
- Add the three Value boxes and record this number in the CHE Module Total box below.
- 4. Circle the appropriate range for the **CHE Module Total** below.
- 5. Circle the **CHE Module Rating** that corresponds to the range selected and record this value in the **CHE Module Rating** box found at the bottom of the table.

Note:

An alternative module rating may be assigned when a module letter rating is inappropriate. An alternative module rating is used when more information is needed to score one or more data elements, contamination at an MRS was previously addressed, or there is no reason to suspect contamination was ever present at an MRS.

	Source	Score	Value
CWM Hazard Factor Data Elemer	nts		
CWM Configuration	Table 11	0	0
Sources of CWM	Table 12		0
Accessibility Factor Data Elemen	nts		
Location of CWM	Table 13		
Ease of Access	Table 14		
Status of Property	Table 15		
Receptor Factor Data Elements			
Population Density	Table 16		
Population Near Hazard	Table 17		
Types of Activities/Structures	Table 18		
Ecological and/or Cultural Resources	Table 19		
CHE MODULE TOT		E TOTAL	0
CHE Module Total CHE Module Ra		ating	
92 to 100		Α	
82 to 91		В	
71 to 81		С	
60 to 70		D	
48 to 59	E		
38 to 47	F		
less than 38	G		
	Evaluation Pending		
Alternative Module Ratings	No Longer Required		
	No Know	n or Suspec Hazard	ted CWM
CHE MODULE RATING	NO KNOWN OR		

HHE Module: Groundwater Data Element Table

Contaminant Hazard Factor (CHF)

DIRECTIONS: Record the maximum concentrations of all contaminants in the MRS's groundwater and their comparison values (from Appendix B of the Primer) in the table below. Additional contaminants can be recorded on Table 27. Calculate and record the ratios for each contaminant by dividing the maximum concentration by the comparison value. Determine the CHF by adding the contaminant ratios together, including any additional groundwater contaminants recorded on Table 27. Based on the CHF, use the CHF Scale to determine and record the CHF Value. If there is no known or suspected MC hazard present in the groundwater, select the box at the bottom of the table.

Contaminant	Maximum Concentration (μg/L)	Comparison Value (μg/L)	Ratios
CHF Scale	CHF Value	Sum The Ratios	
CHF > 100	H (High)	CHF = [Maximum Concentration of Co	ontaminantl
100 > CHF > 2	M (Medium)	CHF = \(\frac{1}{2} \)	orianilarit
2 > CHF	L (Low)	[Comparison Value for Conta	minantj
CONTAMINANT HAZARD FACTOR	DIRECTIONS: Record the CHF Value (maximum value = H).	from above in the box to the right	
DIRECTIONS: Circle t	·	the groundwater migratory pathway at the N	MRS.
Classification		cription	Value
Evident	Analytical data or observable evidence indicates moving toward, or has moved to a point of expos	that contamination in the groundwater is present at, ure.	Н
Potential	Contamination in groundwater has moved only slightly beyond the source (i.e., tens of feet), could move but is not moving appreciably, or information is not sufficient to make a determination of Evident or Confined.		М
Confined	Information indicates a low potential for contaminant migration from the source via the groundwater to a potential point of exposure (possibly due to the presence of geological structures or physical controls).		L
MIGRATORY PATHWAY FACTOR	DIRECTIONS: Record the single high right (maximum value =	nest value from above in the box to the = H).	
DIRECTIONS: Circle t	Receptor F he value that corresponds most closely to		
Classification	Des	cription	Value
Identified	There is a threatened water supply well downgra source of drinking water or source of water for ot (equivalent to Class I or IIA aquifer).	dient of the source and the groundwater is a current her beneficial uses such as irrigation/agriculture	Н
Potential	There is no threatened water supply well downgradient of the source and the groundwater is currently or potentially usable for drinking water, irrigation, or agriculture (equivalent to Class I, IIA, or IIB aquifer).		М
Limited	There is no potentially threatened water supply well downgradient of the source and the groundwater is not considered a potential source of drinking water and is of limited beneficial use (equivalent to Class IIIA or IIIB aquifer, or where perched aquifer exists only).		L
RECEPTOR FACTOR	DIRECTIONS: Record the single high right (maximum value =	nest value from above in the box to the = H).	
	No Kno	wn or Suspected Groundwater MC Hazard	X

HHE Module: Surface Water - Human Endpoint Data Element Table

Contaminant Hazard Factor (CHF)

DIRECTIONS: Record the maximum concentrations of all contaminants in the MRS's surface water and their comparison values (from Appendix B of the Primer) in the table below. Additional contaminants can be recorded on Table 27. Calculate and record the ratios for each contaminant by dividing the maximum concentration by the comparison value. Determine the CHF by adding the contaminant ratios together, including any additional surface water contaminants recorded on Table 27. Based on the CHF, use the CHF Scale to determine and record the CHF Value. If there is no known or suspected MC hazard with human endpoints present in the surface water, select the box at the bottom of the table.

Contaminant	Maximum Concentration (μg/L) Comparison Value (μg/L)		Ratios
CHF Scale	CHF Value	Sum The Ratios	
CHF > 100	H (High)		
100 > CHF > 2	M (Medium)	CHF = [Maximum Concentration of Co	ontaminantj
2 > CHF	L (Low)	[Comparison Value for Conta	minant]
CONTAMINANT HAZARD FACTOR	DIRECTIONS: Record the CHF Value (maximum value = H).	from above in the box to the right	
DIRECTIONS: Circle t	Migratory Pathw he value that corresponds most closely to	vay Factor to the surface water migratory pathway at the	MRS.
Classification	Description		Value
Evident	Analytical data or observable evidence indicates that contamination in the surface water is present at, moving toward, or has moved to a point of exposure.		Н
Potential	Contamination in surface water has moved only slightly beyond the source (i.e., tens of feet), could move but is not moving appreciably, or information is not sufficient to make a determination of Evident or Confined.		М
Confined	Information indicates a low potential for contaminant migration from the source via the surface water to a potential point of exposure (possibly due to the presence of geological structures or physical controls).		L
MIGRATORY PATHWAY FACTOR	DIRECTIONS: Record the single high right (maximum value =		
DIRECTIONS: Circle t	· ·	actor the surface water receptors at the MRS. cription	Value
		•	
Identified	Identified receptors have access to surface water to which contamination has moved or can move.		Н
Potential	Potential for receptors to have access to surface move.		M
Limited	Little or no potential for receptors to have access to surface water to which contamination has moved or can move.		
RECEPTOR FACTOR	DIRECTIONS: Record the single high the right (maximum value)		

No Known or Suspected Surface Water (Human Endpoint) MC Hazard

 \times

HHE Module: Sediment – Human Endpoint Data Element Table

Contaminant Hazard Factor (CHF)

DIRECTIONS: Record the **maximum concentrations** of all contaminants in the MRS's sediment and their **comparison** values (from Appendix B of the Primer) in the table below. Additional contaminants can be recorded on Table 27. Calculate and record the ratios for each contaminant by dividing the maximum concentration by the comparison value. Determine the CHF by adding the contaminant ratios together, including any additional sediment contaminants recorded on Table 27. Based on the CHF, use the CHF Scale to determine and record the CHF Value. If there is no known or suspected MC hazard with human endpoints present in the sediment, select the box at the bottom of the table.

Contaminant	Maximum Concentration (mg/kg)	Comparison Value (mg/kg)	Ratios
CHF Scale	CHF Value	Sum The Ratios	
CHF > 100	H (High)	— Maximum Concentration of C	ontominant]
100 > CHF > 2	M (Medium)	CHF = [Maximum Concentration of C	ontaminantj
2 > CHF	L (Low)	[Comparison Value for Conta	ıminant]
CONTAMINANT HAZARD FACTOR	DIRECTIONS: Record the CHF Value maximum value = H).	from above in the box to the right	
DIRECTIONS: Circle t	Migratory Pathw he value that corresponds most closely to	vay Factor the sediment migratory pathway at the MR	S.
Classification		cription	Value
Evident	Analytical data or observable evidence indicates that contamination in the sediment is present at, moving toward, or has moved to a point of exposure.		Н
Potential	Contamination in sediment has moved only slightly beyond the source (i.e., tens of feet), could move but is not moving appreciably, or information is not sufficient to make a determination of Evident or Confined.		M
Confined	Information indicates a low potential for contaminant migration from the source via the sediment to a potential point of exposure (possibly due to the presence of geological structures or physical controls).		L
MIGRATORY PATHWAY FACTOR	DIRECTIONS: Record <u>the single highest value</u> from above in the box to the right (maximum value = H).		
DIRECTIONS: Circle t	Receptor F he value that corresponds most closely to		
Classification		cription	Value
Identified	Identified receptors have access to sediment to which contamination has moved or can move.		Н
Potential	Potential for receptors to have access to sediment to which contamination has moved or can move.		М
Limited	Little or no potential for receptors to have access to sediment to which contamination has moved or can move.		
RECEPTOR FACTOR	DIRECTIONS: Record the single high the right (maximum val		

No Known or Suspected Sediment (Human Endpoint) MC Hazard

 \boxtimes

HHE Module: Surface Water - Ecological Endpoint Data Element Table

Contaminant Hazard Factor (CHF)

DIRECTIONS: Record the maximum concentrations of all contaminants in the MRS's surface water and their comparison values (from Appendix B of the Primer) in the table below. Additional contaminants can be recorded on Table 27. Calculate and record the ratios for each contaminant by dividing the maximum concentration by the comparison value. Determine the CHF by adding the contaminant ratios together, including any additional surface water contaminants recorded on Table 27. Based on the CHF, use the CHF Scale to determine and record the CHF Value. If there is no known or suspected MC hazard with ecological endpoints present in the surface water, select the box at the bottom of the table.

Contaminant	Maximum Concentration (μg/L)	Comparison Value (μg/L)	Ratios
CHF Scale	CHF Value	Sum the Ratios	
CHF > 100	H (High)	INAccione Consentantia e et C	
100 > CHF > 2	M (Medium)	CHF = [Maximum Concentration of Co	ontaminantj
2 > CHF	L (Low)	[Comparison Value for Conta	minant]
CONTAMINANT HAZARD FACTOR	DIRECTIONS: Record the CHF Value (maximum value = H).	from above in the box to the right	
DIRECTIONS: Circle to	Migratory Pathw he value that corresponds most closely to	vay Factor the surface water migratory pathway at the	MRS.
Classification	Des	cription	Value
Evident	Analytical data or observable evidence indicates that contamination in the surface water is present at, moving toward, or has moved to a point of exposure.		Н
Potential	Contamination in surface water has moved only slightly beyond the source (i.e., tens of feet), could move but is not moving appreciably, or information is not sufficient to make a determination of Evident or Confined.		М
Confined	Information indicates a low potential for contaminant migration from the source via the surface water to a potential point of exposure (possibly due to the presence of geological structures or physical controls).		
MIGRATORY PATHWAY FACTOR	DIRECTIONS: Record the single high right (maximum value =	hest value from above in the box to the = H).	
DIRECTIONS: Circle to	Receptor F	actor o the surface water receptors at the MRS.	
Classification	· ·	cription	Value
Identified		r to which contamination has moved or can move.	H
Potential	Potential for receptors to have access to surface water to which contamination has moved or can move.		М
Limited	Little or no potential for receptors to have access or can move.	to surface water to which contamination has moved	L
RECEPTOR FACTOR	DIRECTIONS: Record the single high right (maximum value =	hest value from above in the box to the = H).	
	No Known or Suspected Surface	ce Water (Ecological Endpoint) MC Hazard	X

HHE Module: Sediment - Ecological Endpoint Data Element Table

Contaminant Hazard Factor (CHF)

DIRECTIONS: Record the maximum concentrations of all contaminants in the MRS's sediment and their comparison values (from Appendix B of the Primer) in the table below. Additional contaminants can be recorded on Table 27. Calculate and record the ratios for each contaminant by dividing the maximum concentration by the comparison value. Determine the CHF by adding the contaminant ratios together, including any additional sediment contaminants recorded on Table 27. Based on the CHF, use the CHF Scale to determine and record the CHF Value. If there is no known or suspected MC hazard with ecological endpoints present in the sediment, select the box at the bottom of the table.

Contaminant	Maximum Concentration (mg/kg)	Comparison Value (mg/kg)	Ratios	
CHF Scale	CHF Value	Sum the Ratios		
CHF > 100	H (High)	— Maximum Concentration of Co	ntaminantl	
100 > CHF > 2	M (Medium)	CHF = [Maximum Concentration of Co	i	
2 > CHF	L (Low)	[Comparison Value for Conta	minant]	
CONTAMINANT HAZARD FACTOR	DIRECTIONS: Record the CHF Valu (maximum value = H).			
DIRECTIONS: Circle the	Migratory Pathway Factor DIRECTIONS: Circle the value that corresponds most closely to the sediment migratory pathway at the MRS.			
Classification		scription	Value	
Evident	Analytical data or observable evidence indicates that contamination in the sediment is present at, moving toward, or has moved to a point of exposure.		Н	
Potential	Contamination in sediment has moved only slightly beyond the source (i.e., tens of feet), could move but is not moving appreciably, or information is not sufficient to make a determination of Evident or Confined.		М	
Confined	Information indicates a low potential for contaminant migration from the source via the sediment to a potential point of exposure (possibly due to the presence of geological structures or physical controls).		L	
MIGRATORY PATHWAY FACTOR	DIRECTIONS: Record <u>the single highest value</u> from above in the box to the right (maximum value = H).			
DIRECTIONS: Circle to	Receptor he value that corresponds most closely			
Classification	· ·	scription	Value	
Identified	Identified receptors have access to sediment to which contamination has moved or can move.		Н	
Potential	Potential for receptors to have access to sedime	ent to which contamination has moved or can move.	M	
Limited	Little or no potential for receptors to have access to sediment to which contamination has moved or can move.		L	
RECEPTOR FACTOR	DIRECTIONS: Record the single hig right (maximum value	thest value from above in the box to the = H).		

No Known or Suspected Sediment (Ecological Endpoint) MC Hazard

 \times

HHE Module: Surface Soil Data Element Table

Contaminant Hazard Factor (CHF)

DIRECTIONS: Record the maximum concentrations of all contaminants in the MRS's surface soil and their comparison values (from Appendix B of the Primer) in the table below. Additional contaminants can be recorded on Table 27. Calculate and record the ratios for each contaminant by dividing the maximum concentration by the comparison value. Determine the CHF by adding the contaminant ratios together, including any additional surface soil contaminants recorded on Table 27. Based on the CHF, use the CHF Scale to determine and record the CHF Value. If there is no known or suspected MC hazard present in the surface soil, select the box at the bottom of the table.

Contaminant	Maximum Concentration (mg/kg) Comparison Value (mg/kg)		Ratio	
CHF Scale	CHF Value	Sum the Ratios		
CHF > 100	H (High)	CHF = [Maximum Concentration of Concentr	ntaminantl	
100 > CHF > 2	M (Medium)	CHF = \(\frac{1}{2} \)	· a	
2 > CHF	L (Low)	[Comparison Value for Contan	nınantj	
CONTAMINANT HAZARD FACTOR	DIRECTIONS: Record the CHF Value (maximum value = H			
DIRECTIONS: Circle t	·	nway Factor to the surface soil migratory pathway at the Mescription	RS. Value	
	Analytical data or observable evidence indicates that contamination in the surface soil is present at,			
Evident	moving toward, or has moved to a point of exp	moving toward, or has moved to a point of exposure.		
Potential	Contamination in surface soil has moved only slightly beyond the source (i.e., tens of feet), could move but is not moving appreciably, or information is not sufficient to make a determination of Evident or Confined.		М	
Confined	Information indicates a low potential for contaminant migration from the source via the surface soil to a potential point of exposure (possibly due to the presence of geological structures or physical controls).		L	
MIGRATORY PATHWAY FACTOR	DIRECTIONS: Record the single his right (maximum value	ighest value from above in the box to the e = H).		
	·	to the surface soil receptors at the MRS.		
Classification	Description		Value	
Identified	Identified receptors have access to surface soil to which contamination has moved or can move.		Н	
identined				
Potential	Potential for receptors to have access to surfa	ce soil to which contamination has moved or can move.	М	
		ce soil to which contamination has moved or can move.	M L	

No Known or Suspected Surface Soil MC Hazard



HHE Module: Supplemental Contaminant Hazard Factor Table

Contaminant Hazard Factor (CHF)

DIRECTIONS: Only use this table if there are more than five contaminants in any given medium present at the

MRS. This is a supplemental table designed to hold information about contaminants that do not fit in the previous tables. Indicate the **media** in which these contaminants are present. Then record all **contaminants**, their **maximum concentrations** and their **comparison values** (from Appendix B of the Primer) in the table below. Calculate and record the **ratio** for each contaminant by dividing the **maximum concentration** by the **comparison value**. Determine the **CHF** for each medium on the appropriate media-specific tables.

Note: Do not add ratios from different media.

Media	Contaminant	Maximum Concentration	Comparison Value	Ratio

Table 28 Determining the HHE Module Rating

DIRECTIONS:

- 1. Record the letter values (H, M, L) for the **Contaminant Hazard**, **Migration Pathway**, and **Receptor Factors** for the media (from Tables 21–26) in the corresponding boxes below.
- 2. Record the media's three-letter combinations in the **Three-Letter Combination** boxes below (three-letter combinations are arranged from Hs to Ms to Ls).
- 3. Using the **HHE Ratings** provided below, determine each media's rating (A–G) and record the letter in the corresponding **Media Rating** box below.

Media (Source)	Contaminant Hazard Factor Value	Migratory Pathway Factor Value	Receptor Factor Value	Three-Letter Combination (Hs-Ms-Ls)	Media Rating (A-G)
Groundwater (Table 21)					
Surface Water/Human Endpoint (Table 22)					
Sediment/Human Endpoint (Table 23)					
Surface Water/Ecological Endpoint (Table 24)					
Sediment/Ecological Endpoint (Table 25)					
Surface Soil (Table 26)					

DIRECTIONS (cont.):

4. Select the single highest Media Rating (A is highest; G is lowest) and enter the letter in the **HHE Module Rating** box.

Note:

An alternative module rating may be assigned when a module letter rating is inappropriate. An alternative module rating is used when more information is needed to score one or more media, contamination at an MRS was previously addressed, or there is no reason to suspect contamination was ever present at an MRS.

HHE MODULE RATING

HHE Ratings (for reference only)					
Combination	Rating				
ННН	Α				
ННМ	В				
HHL	С				
НММ					
HML	D				
MMM					
HLL	_				
MML	Е				
MLL	F				
LLL	G				
	Evaluation Pending				
Alternative Module Ratings	No Longer Required				
/ itemative module realings	No Known or Suspected MC Hazard				

Table 29 **MRS Priority**

DIRECTIONS: In the chart below, circle the letter rating for each module recorded in Table 10 (EHE), Table 20 (CHE), and Table 28 (HHE). Circle the corresponding numerical priority for each module. If information to determine the module rating is not available, choose the appropriate alternative module rating. The MRS Priority is the single highest priority; record this relative priority in the MRS Priority or Alternative MRS Rating at the bottom of the table.

Note: An MRS assigned Priority 1 has the highest relative priority; an MRS assigned Priority 8 has the lowest relative priority. Only an MRS with CWM known or suspected to be present can be assigned Priority 1; an MRS that has CWM known or suspected to be present cannot be assigned Priority 8.

EHE Rating	Priority	CHE Rating	Priority	HHE Rating	Priority
		A 1			
Α	2	В	2	Α	2
В	3	С	3	В	3
С	4	D	4	С	4
D	5	E	5	D	5
E	6	F	6	Е	6
F	7	G	7	F	7
G	8			G	8
Evaluation Pending		Evaluation Pending		Evaluation Pending	
No Longer Required		No Longer	Required	No Longer Required	
No Known or Suspected Explosive Hazard				No Known or Suspected MC Hazard	
MRS PRIORITY or ALTERNATIVE MRS RATING				NO KNOWN OR SUSPECTED HAZARD	